

Name & Address:

Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

16 Raffles Quay, #42-01

Hong Leong Building

Singapore 048581

Vehicle No:

SGA11E

Brand & Model:

Panamera

Chassis/VIN No:

WP0ZZZ97ZDL000615

Date:

2-Dec-24

Franchise:

PORSCHE

Contact Person (Eurokars):

FAIZ

Contact No (Eurokars):

6331 0680

Email/Fax No:

Contact No:

Type of Claim:

THIRD PARTY

YEAR MODEL:

13/11/2013

WIP#:

12834
PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT BUMPER	P970-505-911-41-	1		\$ 2,732.50	\$ 2,732.50
2	TOWING COVER	P970-505-703-00-G2L	1		-	\$ 54.10
3	BUMPER SENSOR	P150-919-275-C -G2L	1		-	\$ 360.90
4	SENSOR GASKET	P7PP-919-133- -	6		\$ 40.20	\$ 40.20
5	RETAINING FRAME RH	P970-505-564-03-1E0	1		-	\$ 116.50
6	RETAINING FRAME (RH) LOWER	P970-505-544-02-1E0	1		-	\$ 186.40
7	DISC (RH)	P970-505-574-00-1E0	1		-	\$ 155.10
8	DISC BLACK MAT RIGHT LOWER	P970-505-576-00-1E0	1		-	\$ 155.10
9	FIXING DEVICE	P970-505-719-00-	2		\$ 79.80	\$ 79.80
10	SUPPORT BRACKET RH	P970-505-554-00-	1		-	\$ 30.40
11	FRONT BUMPER RETAINER RH	P970-505-536-02-	1		-	\$ 57.60
12	BRACKET FOR HEADLIGHT WASHER	P999-507-998-40-	2		\$ 9.00	\$ 9.00
13	RETAINER PLATE LH FOR HEADLIGHT WASHER LH	P970-505-325-00-	1		\$ 100.90	\$ 100.90
14	RETAINER PLATE RH FOR HEADLIGHT WASHER RH	P970-505-326-00-	1		\$ 100.90	\$ 100.90
15	EXPANSION RIVET	PPAF-038-549- -	8		\$ 6.40	\$ 6.40
16	BLIND RIVET	P999-190-104-30-	8		\$ 16.00	\$ 16.00
17	ADDITIONAL HEADLIGHT RH	P970-631-082-05-	1		-	\$ 777.00
18						\$ -

Sub-Total (Parts Price) \$ 3,085.70 \$ 4,978.80

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE FRONT BUMPER & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR FRONT FENDER RH & ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,720.00	\$ 4,300.00
2	TO RESPRAY FRONT BUMPER, FRONT FENDER RH	\$ 2,600.00	\$ 2,800.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ -	\$ 250.00
4	TO TRANSFER THE FRONT BUMPER SENSORS.	\$ 250.00	\$ 500.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 600.00	\$ 600.00
7	SUNDRIES.	\$ 20.00	\$ 50.00

Survey Date & Time:	Repair Days:4 Days	Excess:
---------------------	---------------------------	---------

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price)	\$	5,340.00	\$	8,750.00
		REVISED		PRICE
Parts Price	\$	3,085.70	\$	4,978.80
Labour Price	\$	5,340.00	\$	8,750.00
Total (Initial Estimate)	\$	8,425.70	\$	13,728.80
Supp 1	\$	-	\$	-
Supp 2	\$	-	\$	-
Supp 3	\$	-	\$	-
Total (Before Excess)	\$	8,425.70	\$	13,728.80
Less Excess	\$	-	\$	-
TOTAL (After Excess)	\$	8,425.70	\$	13,728.80
GST 9%	\$	758.31	\$	1,235.59
GRAND TOTAL	\$	9,184.01	\$	14,964.39