



Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J

liusbro@gmail.com

Tel: 67411730

ESTIMATE

Name: India International Insurance Pte Ltd

Address Motor Claims Department

64 Cecil Street #04-00 & #05-00

IOB Building

Singapore 049711

Ref Date:

Ref No:

Vehicle No:

Model / Make:

02/10/2024

GBF238B240925

GBF238B

Fiat Doblo

Maxi 1.6 MTJ AMT Glaze

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear Rh	Tailgate	\$ 1,895.90	1	\$ 1,895.90		RX
2		Tailgate Weatherstrip	\$ 297.00	1	\$ 297.00		11X
3		Tailgate Lock Lower	\$ 192.90	1	\$ 192.90		11X
4		Tailgate Outer Garnish	\$ 321.80	1	\$ 321.80		Che ✓
5		Tailgate "Fiat" Emblem	\$ 87.80	1	\$ 87.80		11X
6		Tailgate "Fiat" Emblem	\$ 87.80	1	\$ 87.80		11X
7		Tailgate "Professional" Emblem	\$ 163.50	1	\$ 163.50		11X
8		Tailgate "6 PAX" Sticker	\$ 15.00	1	\$ 15.00	SN	11X
9		Tailgate "MULTIJET" Emblem	\$ 92.00	1	\$ 92.00		11X
10		Tailgate "90" Emblem	\$ 97.50	1	\$ 97.50		11X
11		Tailgate Glass Sealant	\$ 80.00	1	\$ 80.00	SN	11X
12	Rear Lh	Tailgate	\$ 2,156.30	1	\$ 2,156.30		11X
13		Tailgate Weatherstrip	\$ 344.50	1	\$ 344.50		11X
13		Tailgate Lock Lower	\$ 192.90	2	\$ 385.80		11X
20		Tailgate Number Plate Garnish	\$ 279.00	1	\$ 279.00		11X
21		Tailgate Number Plate Lamp	\$ 51.50	2	\$ 103.00		11X
8		Tailgate "DOBLO" Emblem	\$ 105.00	1	\$ 105.00		11X
9		Tailgate "Maxi" Emblem	\$ 90.00	1	\$ 90.00		11X
18		Tailgate "70 KM/H" Sticker	\$ 15.00	1	\$ 15.00	SN	11X
17		Tailgate Glass Sealant	\$ 80.00	1	\$ 80.00	SN	11X
19	Rear	Bumper	\$ 745.00	1	\$ 745.00		11X
20		Bumper Clips 1 set	\$ 65.00	1	\$ 65.00	SN	11X
21		Bumper Reinforcement	\$ 475.30	1	\$ 475.30		11X
22		Bumper Reverse Sensor	\$ 220.00	1	\$ 220.00	SN	11X
47		Number Plate & Base	\$ 48.00	1	\$ 48.00	SN	11X
23	Rear Lh	Bumper Reflector	\$ 117.60	1	\$ 117.60		11X
40		Tail Lamp	\$ 462.70	1	\$ 462.70		11X
48		Remove & reinstall Rear Rh & Lh Windscreen Glass to facilitate repairs			\$ 240.00		100/1pc
49		Remove and refix rear Rh & Lh tailgate components & wiper mechanism			\$ 180.00		50 1pc
50		Remove and refix rear reverse sensor			\$ 100.00		30
51		To check all wiring & electrical component for proper function			\$ 120.00		20
54		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 1,200.00		550
55		To putty & spray painting & including touch up paint on accident affected areas			\$ 900.00		700
56		To apply Rust Proofing, reseal tuff-coating treatment on accident area			\$ 80.00		30

Total Parts & Labour of estimate for damaged vehicle

\$ 11,843.40

Total amount in Lumpsum Basis for repaired vehicle

SDL

- hence notify the Repairer of the following:
- To resurvey before repair spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Liu's Bro Auto Engrg Wks

P-4863-4
102

4377-06

290

1480

6147.06

4917