Our Ref: GBF238B240925 Date: 20/10/2024

Your Ref:

India International Insurance Pte Ltd 64 Cecil Street #04-00 & #05-00 IOB Building Singapore 049711 Attn: Motor Claims Department

Dear Sir / Madam

Traffic Along	Geylang Lo				
Involving	GBF238B	and	SLF5470U	On	25/09/2024

We/I, Messers Goldbell Leasing Pte Ltd (ROC No: 199001196N), the registered owners of m/vehicle – GBF238B at all material times of the above accident. Our/my vehicle was surveyed by "
India Int'nl " authorized appraiser and we/I based our/my claims on his recommendation for S\$ 4,900-00 being the repair for 04 Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle <u>SLF5470U</u> when the same was involved in the aforesaid accident with our/my m/vehicle - <u>GBF238B</u>.

We/I whereby you are the insurers of m/vehicle <u>SLF5470U</u> and the driver/owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle - <u>GBF238B</u> has suffered loss and damage as follows:

(a)	Cost of repairs	S\$	4,900-00
(b)	PRI LOU for pre-repair notice 02 days @ S\$ 60-00		120-00
(c)	LOU Fee for <u>04</u> days @ S\$_60-00		240-00
(d)	GIA / LTA search fee		27-25
(e)	Towing Fee		
(f)	Survey & Report Fee		
	Total Amount	SS	5,287-25

We/I enclose herewith copies of the supporting documents for vehicle no. _GBF238B as follows:-

- (i) Motor Accident Report & Documents
- (ii) Repair Invoices
- (iii) Survey Report & Receipt

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,



The owner of m/vehicle GBF238B

Messers Goldbell Leasing Pte Ltd
cc. Liu's Bro Auto Engrg Auto Workshop



No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J liusbro@ymail.com Tel: 67411730

FINAL BILL

20/10/2024 Name: India International Insurance Pte Ltd Ref Date: Address Motor Claims Department Ref No: GBF238B240925 64 Cecil Street #04-00 & #05-00 Vehicle No: GBF238B

IOB Building Singapore 049711 Model / Make: Fiat Doblo

Maxi 1.6 MTJ AMT Glaze

Rear Rh Tailgate S1,895,90 1 \$1,895,90 1 \$ \$ \$ \$ \$ \$ \$ \$ \$	Item #	Damaged Description Unit Price		nit Price	Qty	Estimation /			Cost Of		
Tailgate Weatherstrip	reciti "	Area	Description	0,	int i i icc	Qty	Quotation		SN	SN Repair	
Tailgate Weatherstrip	1	Rear Rh	Tailgate	\$	1,895.90	1	\$ 1	.895.90		\$	-
Tailgate Lock Lower	2			_		1		_		\$	-
Tailgate Outer Garnish	3				192.90	1				\$	-
Tailgate "Fiat" Emblem	4			\$	321.80	1	\$			\$	-
Tailgate "Friat" Emblem	5					1					-
Tailgate "Proffessional" Emblem	6					1				\$	-
Tailgate "6 PAX" Sticker	7				163.50	1	\$	163.50		\$	-
Tailgate "MULTIJET" Emblem	8				15.00	1	\$	15.00	SN	_	-
Tailgate "90" Emblem				_		1				_	-
Tailgate Glass Sealant	10					1					-
Tailgate Sear Lh Tailgate Sear Lh Tailgate Sear Lh Tailgate Sear Lh	11			\$	80.00	1	\$	80.00	SN	\$	-
Tailgate Weatherstrip	12	Rear Lh			2,156.30	1	\$ 2	.156.30		\$	-
Tailgate Lock Lower	13			_		1				_	-
Tailgate Number Plate Lamp \$ 51.50 2	13		Tailgate Lock Lower		192.90	2	\$	385.80		\$	-
Tailgate Number Plate Lamp \$ 51.50 2	20		Tailgate Number Plate Garnish	\$	279.00	1	\$	279.00		\$	-
Tailgate "DOBLO" Emblem	21			\$	51.50	2	\$	103.00		_	-
Tailgate "Maxi" Emblem			-							_	-
Tailgate "70 KM/H" Sticker			Tailgate "Maxi" Emblem			1				\$	-
Tailgate Glass Sealant	18			_	15.00	1		15.00	SN		-
19 Rear Bumper \$ 745.00 1 \$ 745.00 \$ - 20 Bumper Clips 1 set \$ 65.00 1 \$ 65.00 SN \$ - 21 Bumper Reinforcement \$ 475.30 1 \$ 475.30 \$ - 22 Bumper Reverse Sensor \$ 220.00 1 \$ 220.00 SN \$ - 23 Rear Lh Bumper Reflector \$ 117.60 1 \$ 117.60 \$ - 23 Remove & reinstall Rear Rh & Lh Windscreen Glass to facilitate repairs \$ 462.70 1 \$ 462.70 \$ - 240.00 \$						1				_	-
Bumper Clips 1 set	19	Rear				1	\$			\$	-
Sumper Reinforcement \$ 475.30 1 \$ 475.30 \$ 5	20		Bumper Clips 1 set	\$	65.00	1	\$	65.00	SN	\$	-
Bumper Reverse Sensor \$ 220.00 1 \$ 220.00 SN \$ -	21			\$	475.30	1	_	475.30		\$	-
Number Plate & Base	22		Bumper Reverse Sensor	\$	220.00	1	\$	220.00	SN	\$	-
Tail Lamp	47		Number Plate & Base	\$	48.00	1	\$			\$	-
Remove & reinstall Rear Rh & Lh Windscreen Glass to facilitate repairs Remove and refix rear Rh & Lh tailgate components & wiper mechanism Remove and refix rear reverse sensor To check all wiring & electrical component for proper function Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affectedd areas To apply Rust Proofing , reseal tuff-	23	Rear Lh	Bumper Reflector	\$	117.60	1	\$	117.60		\$	-
Windscreen Glass to facilitate repairs Remove and refix rear Rh & Lh tailgate components & wiper mechanism Remove and refix rear reverse sensor Remove and refix rear reverse sensor To check all wiring & electrical component for proper function Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affected areas To apply Rust Proofing , reseal tuff-	40		Tail Lamp	\$	462.70	1	\$	462.70		\$	-
49 components & wiper mechanism \$ 180.00 \$ - 10 Remove and refix rear reverse sensor \$ 100.00 \$ - 11 To check all wiring & electrical component for proper function \$ 120.00 \$ - 12 Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs \$ 1,200.00 \$ - 13 To putty & spray painting & including touch up paint on accident affected areas \$ 900.00 \$ - 14 To apply Rust Proofing, reseal tuff-	48						\$	240.00		\$	-
To check all wiring & electrical component for proper function Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affected areas To apply Rust Proofing, reseal tuff-	49		S S				\$	180.00		\$	-
component for proper function Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affected areas To apply Rust Proofing, reseal tuff-	50		Remove and refix rear reverse sensor				\$	100.00		\$	
54 Straighten & Replacing Parts Etcs \$1,200.00 \$ - To putty & spray painting & including touch up paint on accident affected areas \$900.00 \$ - To apply Rust Proofing, reseal tuff-	51		C				\$	120.00		\$	-
touch up paint on accident affected \$ 900.00 \$ - areas To apply Rust Proofing , reseal tuff-	54		G, , ,				\$ 1	,200.00		\$	-
56 2000 4	55		touch up paint on accident affected areas				\$	900.00		\$	-
	56						\$	80.00		\$	-

Total Parts & Labour of estimate for damaged vehicle

Total amount in Lumpsum Basis for repaired vehicle

4,900.00

SDL Four Thousand Nine Hundred Only

Liu's Bro Auto Engrg Wks

> Back to OneMotoring

Land Transport Authority

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time: 02 Oct 2024 / 13:34:13

Receipt Date/Time: 02 Oct 2024 / 13:34:13

Tax Invoice/Receipt

Receipt No.: ITNET-00000-241002-002070

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLF5470U As at 25 Sep 2024/12:40:00 Insurance Co: INDIA INT'L INS PTE LTD 1 Insurance Enquiry - SLF5470U				
Enquiry Fee 20241002133251926617		25.00	2.25	27.25
	Sub-Total	25.00	2.25	27.25
	Total Before Rounding	25.00	2.25	27.25
	Rounding Difference			0.00
	Total Amount Payable			27.25
	Paid By			
	426588XXXXXX2658	eNETS Credit Card		27.25
	Total			27.25
	Cash Change			0.00
	Tendered Amount			27.25
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

1 of 1 2/10/2024, 1:35 pm