

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0405/24
DATE : 30-SEP-2024

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR SHALAN BIN HAPAH
ADDRESS : BLK 113, WOODLANDS STREET 13,
#11-18
S(730113)
TELEPHONE NO : 93285271

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : P11059246R00
VEHICLE NO : SNK4459K
MODEL CODE : FDWARV9P15HDA-C---
MODEL/YEAR : NISSAN KICKS 1.2L E-POWER PREMIUM MY2020
ENGINE NO : HR12447849C
CHASSIS NO : MNTFEAP15Z0005612
MILEAGE : 49405 KM
DATE IN : 30/09/2024
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 28/09/2024

not Authorized
her
never
3/10/24
take photo before paying
7 days
P/P \$8444.00

-9645 0084 elmr@anchorg.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SNK4459K

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR BOTH RR FENDER, RENEW TFLOR RR END PANEL, HATCHBACK DOOR & RR BUMPER <i>floor panel</i>	3440.00	2150
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	2660.00	1400
3	ZZ/003	PULL AND STRAIGHTENED REPAIR BOTH RR CHASSIS	360.00	X
4	ZZ/004	REMOVE AND INSTALL REAR WINDSCREEN GLASS	280.00	✓
5	ZZ/005	REMOVE AND INSTALL BOTH RR COMB LAMP AND CHECK LIGHT SYSTEM	80.00	✓
6	ZZ/006	REMOVE AND TRANSFER REVERSE CAMERA	240.00	120
7	ZZ/007	REMOVE AND TRANSFER HATCHBACK DOOR MECHANISM	120.00	✓
8	ZZ/008	RENEW REVERSE SENSOR AND INNER BRACKET REVERSE SENSOR	110.00	✓
9	ZZ/009	REMOVE AND INSTALL REAR SEAT	240.00	X
10	ZZ/011	APPLY SEALANT TO TRUNK FLOOR, RR END PANEL & HATCH BACK DOOR @ SGD\$100.00 PER PANEL	300.00	200
11	ZZ/012	PERFORM RUST PROOFING TRUNK FLOOR AND REAR END PANEL @ SGD\$120.00 PER PANEL	240.00	120
12	ZZ/013	COMPUTER CHECK DIAGNOSIS	120.00	✓
13	ZZ/10	REMOVE AND INSTALL BOTH INNER TRIM FENDER, TRUNK FLOOR LUGGAGE COVER	240.00	✓
TOTAL LABOUR CHARGES			8430.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SNK4459K

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMAR
1)	LH HATCHBACK DOOR <i>Lamp comb RR RH</i>	26555-5RP0B	<i>CNE</i> 223.70	<i>X</i>	257.80
2)	RH HATCHBACK DOOR LAMP <i>Lamp comb RR LH</i>	26550-5RP0B	<i>CNE</i> 223.70	<i>X</i>	257.80
3	LH REFLECTOR RR BUMPER	26560-8990A	<i>11</i> 68.90	<i>X</i>	
4	RH REFLECTOR RR BUMPER	26565-8990A	<i>11</i> 68.90	<i>X</i>	
5	LH RR COMB LAMP	26555-5RY0A	<i>SU</i> 857.30	<i>X</i>	
6	RH RR COMB LAMP	26550-5RY0A	<i>SU</i> 857.30	<i>X</i>	
7	SUNDRIES	NPN		<i>11</i>	50.00 <i>X</i>
8	REAR LICENCE PLATE	<i>✓</i> RLP		<i>SCR</i>	60.00
9	TRUNKFLOOR	G4514-5RYMA	<i>R</i> 697.10	<i>X</i>	
10	ANTENNA-SMART KEYLESS	285E5-JK60A	<i>11</i> 53.50	<i>X</i>	
11	EMBLEM-BACK DOOR E POWER	<i>✓</i> 90893-5RY0A	<i>neu</i> 131.00	<i>✓</i>	
12	EMBLEM-BACK DOOR NISSAN	<i>✓</i> 90890-5RB0A	<i>neu</i> 72.20	<i>✓</i>	
13	ORNAMENT-BACK DOOR KICKS	<i>✓</i> 90892-5RB0A	<i>neu</i> 72.20	<i>✓</i>	
14	PULL HANDLE HATCHBACK DOOR	90940-4N000	<i>11</i> 21.80	<i>X</i>	
15	TOP INNER TRIM HATCHBACK DOOR	90904-5RY0A	<i>11</i> 474.80	<i>X</i>	
16	INNER TRIM HATCHBACK DOOR	90900-5RY0A	<i>11</i> 367.30	<i>X</i>	
17	STRIKER-HATCHBACK DOOR	90570-5FA0A	<i>11</i> 38.70	<i>X</i>	
18	HATCHBACK DOOR LOCK	<i>✓</i> 90503-9428R		<i>Daye</i>	125.60
19	CENTER FINISHER OUTER HATCHBACK DOOR	90810-5RF3B	<i>SU</i> 435.50	<i>X</i>	
20	WEATHER STRIP HATCHBACK DOOR	<i>✓</i> 90830-5RY0A	<i>7m</i> 71.20	<i>✓</i>	
21	HATHBACK DOOR	<i>✓</i> K010M-5RYMA	<i>30d50</i> 920.80	<i>✓</i>	
22	RH RR FENDER INNER TRIM FINISHER	84950-5RY0A	<i>11</i> 90.10	<i>X</i>	
23	LH RR FNDR INNER TRIM FINISHER	84951-5RY0A	<i>11</i> 90.10	<i>X</i>	
24	CARPET-LUGGAGE FLOOR COVER	<i>✓</i> 84904-5RY0A	<i>CNE</i> 310.70	<i>✓</i>	
25	BOX-LUGGAGE FLOOR CENTER	<i>✓</i> 84975-5RY0A	<i>70m</i> 252.10	<i>✓</i>	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SNK4459K

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMAR
26 PLATE LUGGAGE REAR GARNISH	84992-5RY0A	85.00		
27 CLIP RR BUMPER @ SGD\$16.50 EACH	01553-1HA0A	165.00		
28 REVERSE SENSOR @ SGD\$258.20 EACH	28438-4CLOB			1032.80
29 ENERGY ABSORBER RR BUMPER	85090-5RY0A	79.50		
30 INNER BRACKET REVERSE SENSOR@SGD\$32.30 EACH	28533-6CA0C			129.20
31 RH SIDE BRACKET RR BUMPER	85220-5RF0A	72.40		
32 LH SIDE BRACKET RR BUMPER	85221-5RF0A	72.40		
33 STAY-RR BUMPER @SGD\$108.00 EACH	H5212-1HMMA	216.00		
34 REAR BUMPER	85022-5RJ0H	822.80		
SUB TOTAL		7912.00	0.00	1397.60
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1582.40	0.00	0.00
GRAND TOTAL		6329.60	0.00	1397.60
OVERALL TOTAL		7727.20		

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

rear end panel 22 ✓ \$ 365 ✓

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SNK4459K

TOTAL LABOUR CHARGES 8430.00
TOTAL SPARE PARTS CHARGES 7727.20

GRAND TOTAL 16157.20 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.