



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN: MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA2 IPM HB HIGH WHITE
CHASSIS NO.: JM6DJ2HAA01200187
ENGINE NO.: P520484407
REG NO.: ET9822X
REGN DATE: 30/11/2017

PAGE NO.: 1
DOCUMENT NO.: 1504
DOCUMENT DATE: 02/10/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV: Lee Yao Sheng
CSP/OP CODE: 1
DEPT: 20732
WIP NO.:
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price SGD	Stk/Status	Gross amount SGD	GST Code
NOTES	MS FIRST CAPITAL TP CLAIM				0.00	O
SUB	TO REMOVE & REPLACE REAR BUMPER, END PANEL & REAR FENDER LOWER PANEL LH. AND ALL ACCIDENT AFFECTED AREA.	792		1584	4,752.00	S
SUB	TO RESPRAY REAR BUMPER, END PANEL & REAR FENDER LOWER PANEL LH.	788		1512	3,780.00	S
SUB	TO TRANSFER REVERSE SENSORS.			180	330.00	S
SUB	TO SUPPLY NUMBER PLATE.			Scr	70.00	S
SUB	TO SUPPLY SPRAY TEROSTAT			11	180.00	S X
SUB	SEALANT ON THE CUTTING			11	792.00	S X
SUB	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.			11	250.00	S X
SUB	TO CARRY OUT BODY CAVITY PRESERVATION.			120	250.00	S
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			150	300.00	S
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.					

P/P \$5155.56

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

NOT Authorised
as
4/10/24
telephone before repair.
3 days



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn No: M90364005A

zoom-zoom

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417

LKK Auto Consultants hence notify
the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) to the resurvey

to confirmation

• Third party survey is on a "Without Prejudice" basis

to illegal modification(s) is allowed

any item(s) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN: MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA2 IPM HB HIGH WHITE
CHASSIS NO.: JM6DJ2HAA01200187
ENGINE NO.: P520484407
REG NO.: ET9822X
REGN DATE: 30/11/2017

PAGE NO.: 2
DOCUMENT NO.: 1504
DOCUMENT DATE: 02/10/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV: Lee Yao Sheng
CSP/OP CODE: I
DEPT: 20732
WIP NO.:
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
SUB	SUNDRIES.				50.00	S 20
DH4T-50-221	BEREAR BUMPER DJ W/SENSOR	1.00	1,024.24	*NO STOCK	-1,024.24	S
B45A-56-146A	FASTENER	7.00	2.36	*NO STOCK	-16.52	S
D09W-50-271A	STAY RR BUMPER DJ	2.00	9.78	*NO STOCK	19.56	S X
D09H-50-2J1A	RETAINER LHR DJ	1.00	27.57	*NO STOCK	27.57	S X
BHN1-50-0Z1A	GROMMET, SCREW	4.00	2.36	*NO STOCK	-9.44	S
DFR5-50-251	BRACKET, BUMPER SKYACTIV	1.00	4.64	*NO STOCK	4.64	S X
D09H-50-350	SHIELD LHR SPLASH M2 DJ	1.00	67.10	*NO STOCK	67.10	S X
GS1D-50-EM1A	TAPE, PROTECTOR	5.00	7.42	*NO STOCK	-37.10	S
D23P-67-SH0	CORD, SHORT DJ	1.00	187.54	*NO STOCK	187.54	S X
KD47-67-UC5A	RETAINER REV SENSOR	4.00	15.77	*NO STOCK	-63.08	S
GMK6-67-UC1	SENSOR, ULTRASONIC GJ/GL	2.00	184.59	STOCK	369.18	S 10 C
KD47-67-UC1	6.SENSOR, ULTRASONIC SKYACTIV	2.00	184.59	*NO STOCK	369.18	S 10 C
D0YH-70-75Z	PANEL, REAR END DJ	1.00	546.93	*NO STOCK	546.93	S 9
D0YH-71-44Y	PILLAR(L), REAR OUTER	1.00	748.71		748.71	S X

	GST Code	Rate	Service/Goods	GST
Parts	O	-		-
Surcharge	S	9.00%	14,244.79	1,282.03
Labour				
Menus				

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

	Before GST	GST	Total
Gross	14,244.79	1,282.03	15,526.82
Less: Deposit**	0.00	0.00	0.00
Amount Due	14,244.79	1,282.03	15,526.82

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date:

Customer signature

Authorised signature



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :
5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095
Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417