

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0699/2024/KS
DATE : 1-Oct-24
WIP : 31393

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/10/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR MUNIR TALHA
ADDRESS : 87 PASIR PANJANG
#04-09
SINGAPORE 118892
TELEPHONE : HP +65 84980451
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7240052021
VEHICLE NO : **SNQ 3808 L**
MODEL CODE : AUDI A4 2.0 TFSI S TRONIC
MODEL YEAR : 15/4/2024
ENGINE NO : DEM 036613
CHASSIS NO : WAUZZZF48NN006776
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Sep-24
PLACE OF ACCIDENT : TUAS, SINGAPORE
SINGAPORE CUSTOM TUAS

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SNQ 3808 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE FOR HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00	
2	TO REMOVE AND REINSTALL FRONT BUMPER. TO DISMANTLE AND RENEW RHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	
3	TO RESPRAY RHS FRONT FENDER.	\$	1,100.00	
4	TO RE-APPLY PAINT PROTECTION FILM ON ACCIDENT AFFECTED PANELS.	S/N	TBC	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	
TOTAL LABOUR CHARGES		:	\$ 3,972.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNQ 3808 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER - RH	1	\$ 1,308.00	
2	FRONT FENDER ATTACHMENT PARTS - RH	1	\$ 241.00	
3	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 90.00	
4	FRONT FENDER BRACKET - RH	1	\$ 45.00	
5	FRONT FENDER BRACKET - RH	1	\$ 72.00	
6	FRONT FENDER RIVET - RH	6	\$ 26.00	
7	FRONT FENDER BRACE - RH FRONT	1	\$ 177.00	
8	FRONT FENDER COVER - RH	1	\$ 39.00	
9	FRONT FENDER TOP COVER FOR HEADLIGHT - RH	1	\$ 55.00	
10	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS			: \$ 2,353.00	
TOTAL LABOUR CHARGES			: \$ 3,972.00	
GRAND TOTAL			: \$ 6,325.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT