

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile MS SOMPO INSURANCE SINGAPORE PL Ref: CS3/SMO24100051/Knp3m4 50 RAFFLES PLACE #03-03 Date: 15/10/2024 SINGAPORE LAND TOWER SINGAPORE 048623 Code: SMO 1. Policy Particulars :- PRE-REPAIR SURVEY Insured Veh. YQ 1030X Veh. Inspected **GBF 4421S** Policy No. D24MTPCVE001356 n Coverage Claim No. CMTD2403161/JYC **Excess** \$0.00 JIA YI 02/10/2024 Assign From **Assign Date** 2. **Vehicle Details** TOYOTA DYNA 150 MANUAL C.C Make & Model 2982 1KD2571593 10/12/2015 Engine No. Year of Reg. JTFAT35Y70K205502 Colour **SILVER** Chassis No. 190487 KM IN ORDER Odometer Steering **Brakes** IN ORDER General GOOD RIMS: NIL Modification(s) 3. **Conditions of Tyres** Size Make Balance (mm) 195 R15X8 **MICHELIN** R/H Front Tyre 3 195 R15X8 **MICHELIN** 3 L/H Front Tyre 1/1 155 R12X8 (D) **FALKEN** R/H Rear Tyre 155 R12X8 (D) **FALKEN** 2/2 L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 28/09/2024 **Inspection Date Accident Date** 07/10/2024 (13:00) Survey held at LC XTREME PTE LTD - 71 WOODLANDS AVE 10 #01-16 WOODLANDS INDUSTRIAL XCHANGE SINGAPORE 737743 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

KSC

5b.

KENNETH KONG SENG CHEONG

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Estimate Days of Repair