

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail: jlperfectautowork@gmail.com



DATE : 19.06.2024

TO	: INCOME MOTOR CLAIMS DEPTS
VEHICLE NO	: SLJ7070G
MODEL	: TOYOTA LEXUS NX350H
DATE OF ACCIDENT	: 19.06.2024
TIME OF ACCIDENT	: 11:05 HOURS

Veron.

CLAIM DETAIL : PARTS

CLAIM DETAIL PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Deleted</i>	1	\$ 1,270.90	\$ 1,270.90
2	REAR BUMPER LOWER CARNER GARNISH <i>new</i>	2	\$ 345.60	\$ 691.20
3	REAR BUMPER (LOWER) <i>Deleted</i>	1	\$ 974.80	\$ 974.80
4	REAR BUMPER REFLECTOR <i>Carbide</i>	2	\$ 264.80	\$ 529.60
5	REAR BUMPER CORNER RETAINER <i>2 for 1</i>	2	\$ 171.60	\$ 343.20
6	REAR BUMPER SIDE RETAINER	2	\$ 171.60	\$ 343.20
7	REAR BUMPER REINFORCEMENT <i>Deleted</i>	1	\$ 1,222.90	\$ 1,222.90
8	REAR BUMPER REINFORCEMENT BRACKET <i>new</i>	2	\$ 285.00	\$ 570.00
9	REAR BUMPER SENSOR <i>2 pieces damaged</i>	4	\$ 417.90	\$ 1,671.60
10	REAR BUMPER SENSOR HOLDER <i>new</i>	4	\$ 48.60	\$ 194.40
11	REAR BUMPER SENSOR WIRE HARNESS <i>new</i>	1	\$ 367.90	\$ 367.90
12	REAR BUMPER SMART SENSOR <i>3 for 1</i>	1	\$ 1,587.60	\$ 1,587.60
13	REAR BUMPER SMART SENSOR MODULE <i>3 for 1</i>		\$ 2,720.80	\$ 2,720.80
14	REAR BUMPER SMART SENSOR HOLDER GARNISH <i>Deleted</i>		\$ 286.40	\$ 286.40
15	TAILLAMP <i>LH out</i>	2	\$ 1,160.30	\$ 2,320.60
16	REAR FENDER INNER TRIM <i>2 for 1 new</i>	2	\$ 1,013.50	\$ 2,027.00
17	REAR FENDER INNER COWLING <i>3 for 1 new</i>	2	\$ 313.20	\$ 626.40
18	REAR WHEEL ARCED GARNISH <i>3 for Carbide</i>	2	\$ 165.70	\$ 331.40
19	TAILGATE <i>Deleted</i>	1	\$ 4,147.90	\$ 4,147.90
20	TAILGATE LAMP <i>WT</i>	1	\$ 2,481.20	\$ 2,481.20
21	TAILGATE OUTER GARNISH <i>Carbide</i>	1	\$ 1,729.50	\$ 1,729.50
22	TAILGATE NUMBER PLATE LAMP <i>new</i>	2	\$ 400.10	\$ 800.20

~~1/2~~ 720.
 100
~~1/2~~ 1160.30
 3880
 1995

TO : INCOME MOTOR CLAIMS DEPTS
 VEHICLE NO : SLJ7070G
 MODEL : TOYOTA LEXUS NX350H
 DATE OF ACCIDENT : 19.06.2024
 TIME OF ACCIDENT : 11:05 HOURS

23	TAILGATE EMBLEM 'LEXUS'	1	\$ 169.20	\$ 169.20
24	TAILGATE EMBLEM 'NX350H'	1	\$ 123.70	\$ 123.70
25	TAILGATE EMBLEM 'AWD'	1	\$ 82.80	\$ 82.80
26	TAILGATE COMPUTER MULTIPER NETWORK	1	\$ 1,685.90	\$ 1,685.90
27	TAILGATE DAMPER (ELETRIC)	2	\$ 1,968.70	\$ 3,937.40
28	TAILGATE INNER LOCK	1	\$ 1,077.80	\$ 1,077.80
29	TAILGATE LOWER LOCK	1	\$ 358.60	\$ 358.60
30	TAILGATE STOPPER	2	\$ 35.80	\$ 71.60
31	TAILGATE INNER TRIM (LOWER)	1	\$ 870.90	\$ 870.90
32	TAILGATE WINDSCREEN MOULDING	1	\$ 48.80	\$ 48.80
33	TAILGATE WEATHER STRIP	1	\$ 556.20	\$ 556.20
34	REVERSE CAMERA	1	\$ 1,709.50	\$ 1,709.50
35	TAIL GATE DETECTOR	1	\$ 485.60	\$ 485.60
36	TAIL GATE DETECTOR WIRE HARNESS	1	\$ 389.47	\$ 389.47
37	BUZZER	1	\$ 185.60	\$ 185.60
38	REAR END PANEL	1	\$ 1,354.60	\$ 1,354.60
39	REAR END PANEL TOP GARNISH	1	\$ 563.20	\$ 563.20
40	REAR SIDE COMPARTMENT COVER BOARD	2	\$ 325.60	\$ 651.20
41	REAR COMPARTMENT COVER BOARD	1	\$ 1,526.80	\$ 1,526.80
42	REAR STORAGE BOX GARNISH	2	\$ 486.10	\$ 972.20
43	REAR EXHAUST PIPE	2	\$ 2,680.30	\$ 5,360.60
44	REAR EXHAUST INSULATOR	1	\$ 366.80	\$ 366.80
45	REAR EXHAUST GASKET (SET)	1	\$ 47.50	\$ 47.50
46	REAR EXHAUST MOUNTING	4	\$ 39.60	\$ 158.40

18746.20

TOTAL PRICE

\$ 44,059.77

LESS 10%

\$ 4,405.98

16871.58

SUB TOTAL PRICE

\$ 39,653.79

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNITS/NETT	TOTALS/NETT
1	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS (SET)	1	\$ 120.00	\$ 120.00
3	REAR BUMPER BOTTOM INNER GARNISH CLIP (SET)	1	\$ 80.00	\$ 80.00
4	TAILLAMP CLIP (SET)	1	\$ 30.00	\$ 30.00

TO : INCOME MOTOR CLAIMS DEPTS
 VEHICLE NO : SLJ7070G
 MODEL : TOYOTA LEXUS NX350H
 DATE OF ACCIDENT : 19.06.2024
 TIME OF ACCIDENT : 11:05 HOURS

5	TAILGATE SEALANT <i>pl n</i>	1	\$	180.00	\$	180.00	<i>+</i>
6	TAILGATE OUTER GARNISH CLIP (SET) <i>n</i>	1	\$	40.00	\$	40.00	<i>20</i>
7	TAILGATE INNER TRIM CLIP (SET) <i>n</i>	1	\$	50.00	\$	50.00	<i>20</i>
8	TAILGATE WINDSCREEN SEALANT <i>pl n</i>	1	\$	180.00	\$	180.00	<i>40</i>
9	TAILGATE WINDSCREEN INNER SHIELD <i>pl n</i>	1	\$	120.00	\$	120.00	<i>30</i>
10	REAR FENDER INNER TRIM CLIPS (SET) <i>pl n</i>	1	\$	80.00	\$	80.00	<i>+</i>
11	REAR FENDER INNER COWLING CLIP (SET) <i>pl n</i>	1	\$	80.00	\$	80.00	<i>+</i>
12	REAR WHEEL ARCED CLIP (SET) <i>pl n</i>	1	\$	80.00	\$	80.00	<i>50</i>
13	REAR END PANEL TOP GARNISH CLIPS (SET) <i>pl n</i>	1	\$	60.00	\$	60.00	<i>20</i>
14	REAR END PANEL INSULATION SEAL <i>pl n</i>	1	\$	150.00	\$	150.00	<i>60</i>
15	REAR STORAGE BOX GARNISH CLIP (SET) <i>pl n</i>	1	\$	80.00	\$	80.00	<i>+</i>

310 TOTAL \$ 1,380.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,000.00	<i>800</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>700</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING AND BULB CHECK	\$ 250.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>60</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>30</i>
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>
8	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 80.00	<i>50</i>
9	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>x</i>
10	TRANSFER TAILGATE MECHANISM	\$ 80.00	<i>60</i>

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLJ7070G**
 MODEL : **TOYOTA LEXUS NX350H**
 DATE OF ACCIDENT : 19.06.2024
 TIME OF ACCIDENT : 11:05 HOURS

11	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
12	RESET TAILGATE AUTO SYSTEM	\$ 550.00	P
13	REMOVE AND REFIX SMART SENSOR AND RESET	\$ 180.00	X
14	REMOVE AND REFIX REAR EXHAUST	\$ 120.00	X
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	150

2130

TOTAL \$ 6,310.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 41,033.79
 TOTAL LABOUR COST : \$ 6,310.00
 TOTAL REPAIR COST : \$ 47,343.79

Adrian C
 L/S 24/06/24
 06 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Supplementary: 1089

Total: 20400.58

L/S: 16.3R ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 24.06.2024

TO : **INCOME** MOTOR CLAIMS DEPTS (SUPPLEMENTARY)
VEHICLE NO : **SLJ7070G**
MODEL : **TOYOTA LEXUS NX350H**
DATE OF ACCIDENT : 19.06.2024
TIME OF ACCIDENT : 11:05 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE SIDE SENSOR <i>cracked</i>	1	\$ 1,680.00	\$ 1,680.00

TOTAL PRICE \$ 1,680.00
LESS ~~25%~~ 10% \$ 420.00
SUB TOTAL PRICE \$ 1,260.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ -
TOTAL REPAIR COST : \$ -

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Supplementary: 1089

Adrian Lg
Slg.

1210

1210