



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2501571

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN:GARNET LOW

INV Date 17/03/2025
Reference CD/FCI24100053/Rma3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SNA 8555S
Insured Veh. SHA 2168L
Claim No. D24008519MFCT/CTPL
Policy No. D-24101861MFCT
Accident Date 26/09/2024
Inspection Date 10/10/2024

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (9%)	31.50
Grand Total	381.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN:GARNET LOW			Ref: CD/FCI24100053/Rma3q2(N) Date: 17/03/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 2168L	Veh. Inspected	SNA 8555S
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D24008519MFCT/CTPL	Excess (\$)	0.00
	Assign From	GARNET LOW	Assign Date	10/10/2024
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 216D A.T	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WBA2B32010V260098	Colour	BLACK
	Odometer	202351 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R17	PIRELLI	6 mm
	L/H Front Tyre	205/55 R17	PIRELLI	6 mm
	R/H Rear Tyre	205/55 R17	PIRELLI	6 mm
	L/H Rear Tyre	205/55 R17	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/09/2024	Inspection Date	10/10/2024
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNA 8555S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
2	RUBBER MOUNTING (SN)	SERVICEABLE	38.40	-
1	REAR SILENCER (SN)	BENT	1,176.05	1,176.05
1	TAILPIPE TRIM CHROME (SN)	SCRATCHED	123.15	123.15
2	HOLDER EXHAUST SYSTEM (SN)	SERVICEABLE	133.10	-
1	REAR BUMPER PANEL PRIMED (PDC) (SN)	DEFORMED	1,132.45	1,132.45
1	REAR BUMPER CARRIER (SN)	BENT	525.75	525.75
1	SUPPORT (SN)	SERVICEABLE	86.70	-
1	RR BUMPER LH INNER SIDE GUIDE (SN)	SERVICEABLE	172.60	-
1	LH PROTECTION FOIL (SN)	SERVICEABLE	6.15	-
1	REAR BUMPER HEAT INSULATOR (SN)	SERVICEABLE	86.55	-
4	DECOUPING RING PDC TORQUE CONVERTER (SN)	NOT NECESSARY	22.60	-
1	CLAMPING BUSH (SN)(ADDITIONAL)	NECESSARY	61.80	61.80
			3,715.30	3,099.20
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER AND ATTACHMENT .		1,700.00	850.00
	TO RESPRAY REAR BUMPER AND ATTACHMENT.		1,038.00	1,038.00
	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECK FOR LEAK.		531.00	531.00
	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	177.00
	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION.		177.00	177.00
			3,623.00	2,773.00
	GRAND TOTAL		7,338.30	5,872.20

RECOMMENDED COST OF REPAIRS			5,872.20
------------------------------------	--	--	-----------------

Report Ref No. CD/FCI24100053/Rma3q2(N)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNA 8555S



PHOTOGRAPHS FOR VEHICLE NO. : SNA 8555S



PHOTOGRAPHS FOR VEHICLE NO. : SNA 8555S



PHOTOGRAPHS FOR VEHICLE NO. : SNA 8555S



PHOTOGRAPHS FOR VEHICLE NO. : SNA 8555S



PHOTOGRAPHS FOR VEHICLE NO. : SNA 8555S



PHOTOGRAPHS FOR VEHICLE NO. : SNA 8555S



PHOTOGRAPHS FOR VEHICLE NO. : SNA 8555S



PHOTOGRAPHS FOR VEHICLE NO. : SNA 8555S



PHOTOGRAPHS FOR VEHICLE NO. : SNA 8555S



PHOTOGRAPHS FOR VEHICLE NO. : SNA 8555S



PHOTOGRAPHS FOR VEHICLE NO. : SNA 8555S





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 4 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SNA 8555S

