

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MOHAMED ZAINORDIN BIN MOHD BAHARIN
BLK 987B BUANGKOK GREEN #02-27
SINGAPORE 532987

Contact : 80221352

TP Budget Direct.
Hui Rong.

TAX INVOICE

Repair Code : CLM16436

Date in : 01/10/2024

Vehicle Num. : SLP3801J

Model : HONDA STREAM 1.8X A

Chassis/Eng# : RN61084050/R18A1793238

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRBAG ECU <i>Activated</i>	1	1177.60	✓ 1,177.60
AIRCON CONDENSER <i>Best</i>	1	877.60	✓ 877.60
AIRCON CONDENSER ALUMINIUM PIPE	1	301.40	+ 301.40
AIRCON CONDENSER DISCHARGE PIPE	1	288.70	+ 288.70
AIRCON CONDENSER FAN BLADE	1	88.70	+ 88.70
AIRCON CONDENSER FAN COWLING	1	166.70	+ 166.70
AIRCON CONDENSER FAN MOTOR	1	341.10	+ 341.10
CENTER PILLAR INNER GARNISH L/R	2	101.40	+ 202.80
DASHBOARD <i>torn</i>	1	865.00	- 865.00
DASHBOARD AIRCON PANEL <i>new</i>	1	464.70	+ 464.70
ENGINE UNDER COVER <i>Delid</i>	1	198.00	✓ 198.00
FLOOR PANEL CARPET <i>new</i>	1	1010.00	+ 1,010.00
FRONT AIR DUCT <i>new</i>	1	87.10	+ 87.10
FRONT BATTERY BRACKET <i>new</i>	1	90.00	+ 90.00
FRONT BATTERY TRAY <i>Delid</i>	1	95.00	✓ 95.00
FRONT BONNET <i>Delid</i>	1	638.10	✓ 638.10
FRONT BONNET HINGES L/R <i>new</i>	2	61.70	+ 123.40
FRONT BONNET INNER CENTER RUBBER SEAL <i>new</i>	1	38.20	+ 38.20

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

MOHAMED ZAINORDIN BIN MOHD BAHARIN
 BLK 987B BUANGKOK GREEN #02-27
 SINGAPORE 532987

Contact : 80221352

TAX INVOICE

Repair Code : CLM16436

Date in : 01/10/2024

Vehicle Num. : SLP3801J

Model : HONDA STREAM 1.8X A

Chassis/Eng# : RN61084050/R18A1793238

FRONT BONNET INNER TOP RUBBER SEAL <i>new</i>	1	45.10	+	45.10
FRONT BONNET INSULATOR <i>new</i>	1	155.90	+	155.90
FRONT BONNET MECHANISM LOCK <i>new</i>	1	133.40	✓	133.40
FRONT BUMPER <i>Disturb</i>	1	863.40	688	863.40
FRONT BUMPER FOGLAMP GARNISH L/R <i>new</i>	2	65.30	+	130.60
FRONT BUMPER LOWER GRILLE <i>Disturb</i>	1	150.00	✓	150.00
FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	533.80	297	533.80
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	35.90	+	71.80
FRONT FENDER INNER BRACKET L/R <i>new</i>	2	66.70	+	133.40
FRONT FENDER INNER SHIELD L/R <i>LH torn</i>	2	155.70	155.70	311.40
FRONT FENDER INNER TOP GARNISH L/R <i>new</i>	2	66.80	+	133.60
FRONT FENDER L/R <i>LH Disturb</i>	2	571.40	571.40	1,142.80
FRONT FENDER SIGNAL LAMP L/R <i>new</i>	2	58.70	+	117.40
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	48.10	✓	48.10
FRONT GRILLE (BASE) <i>missing</i>	1	301.40	✓	301.40
FRONT GRILLE OUTER CHROME COVER	1	328.40	✓	328.40
FRONT GRILLE TOP GARNISH <i>Disturb</i>	1	65.70	✓	65.70
FRONT HEADLAMP (HID) L/R <i>caused</i>	2	925.70	✓	1,851.40

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

MOHAMED ZAINORDIN BIN MOHD BAHARIN
 BLK 987B BUANGKOK GREEN #02-27
 SINGAPORE 532987

Contact : 80221352

TAX INVOICE

Repair Code : CLM16436

Date in : 01/10/2024

Vehicle Num. : SLP3801J

Model : HONDA STREAM 1.8X A

Chassis/Eng# : RN61084050/R18A1793238

FRONT HEADLAMP LOWER BRACKET L/R <i>cancel</i>	2	45.10	✓	90.20
FRONT LH CHASSIS OUTER BRACKET <i>best</i>	1	66.70	✓	66.70
FRONT LH CHASSIS SIDE MEMBER (INNER)	1	201.40	✓	201.40
FRONT LH CHASSIS SIDE MEMBER (OUTER)	1	188.70	✓	188.70
FRONT LH FENDER INNER ARCH PANEL (INNER)	1	188.70	✓	188.70
FRONT LH FENDER INNER ARCH PANEL (OUTER)	1	201.40	✓	201.40
FRONT LH PASSENGER AIRBAG <i>Assembled</i>	1	2236.80	✓	2,236.80
FRONT RESONATOR ASSY <i>cancel</i>	1	298.00	✓	298.00
FRONT SEAT BELT L/R <i>Assembled</i>	2	876.70	✓	1,753.40
FRONT STEERING AIRBAG <i>Assembled</i>	1	2111.40	✓	2,111.40
FRONT STEERING CLOCK SPRING SENSOR	1	501.40	✓	501.40
FRONT SUPPORT PANEL <i>cancel</i>	1	526.70	✓	526.70
FRONT WINDSCREEN <i>lt</i>	1	1010.00	✓	1,010.00
FRONT WINDSCREEN MOULDING <i>new</i>	1	198.00	✓	198.00
RADIATOR <i>Deleted</i>	1	1011.40	✓	1,011.40
RADIATOR FAN BLADE <i>new</i>	1	88.70	+	88.70
RADIATOR FAN COWLING <i>cancel</i>	1	155.70	✓	155.70
RADIATOR FAN MOTOR <i>new</i>	1	322.40	+	322.40

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MOHAMED ZAINORDIN BIN MOHD BAHARIN
BLK 987B BUANGKOK GREEN #02-27
SINGAPORE 532987

Contact : 80221352

TAX INVOICE

Repair Code : CLM16436

Date in : 01/10/2024

Vehicle Num. : SLP3801J

Model : HONDA STREAM 1.8X A

Chassis/Eng# : RN61084050/R18A1793238

RADIATOR SPARE TANK	Del'd	1	105.00	✓	105.00
RADIATOR TOP HOSE	new	1	38.70	✓	38.70
REAR BODY EXTENSION L/R	Repair	2	690.00	✓	1,380.00
REAR BUMPER	Disturbed	1	767.60	✓	767.60
REAR BUMPER LOWER BRACKET L/R	Best	2	28.90	✓	57.80
REAR BUMPER SIDE RETAINER L/R	could	2	38.30	✓	76.60
REAR BUMPER TOW HOOK COVER	Del'd	1	31.40	✓	31.40
REAR END PANEL	Disturbed	1	511.40	✓	511.40
REAR END PANEL INNER TOP GARNISH	Del'd	1	101.40	✓	101.40
REAR EXHAUST CHROME TAIL PIPE	Best	1	103.60	✓	103.60
REAR EXHAUST HEAT COVER	coupled	1	101.70	✓	101.70
REAR EXHAUST RUBBER MOUNTING	new	2	35.40	+	70.80
REAR EXHAUST SILENCER BOX	Best	1	458.70	✓	458.70
REAR FENDER INNER TRIM BOARD L/R	could	2	405.00	✓	810.00
REAR FLOOR PANEL	Brueed	1	871.40	✓	871.40
REAR FLOOR PANEL CARPET	Del'd	1	205.00	✓	205.00
REAR FLOOR PANEL TOP BOARD COVER L/R	Stained	2	201.40	✓	402.80
REAR FLOOR SIDE TOP PANEL L/R	Repair LH Repair, RH Brueed	2	258.40	+	516.80

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MOHAMED ZAINORDIN BIN MOHD BAHARIN
BLK 987B BUANGKOK GREEN #02-27
SINGAPORE 532987

Contact : 80221352

TAX INVOICE

Repair Code : CLM16436

Date in : 01/10/2024

Vehicle Num. : SLP3801J

Model : HONDA STREAM 1.8X A

Chassis/Eng# : RN61084050/R18A1793238

REAR LH DOOR <i>Dented</i>	1	767.60	✓	767.60
REAR LH DOOR BLACK TAPE <i>new</i>	1	48.70	✓	48.70
REAR LH DOOR INNER TRIM BOARD <i>new</i>	1	401.40	+	401.40
REAR LH DOOR MECHANISM LOCK <i>Dented</i>	1	301.40	✓	301.40
REAR LH DOOR WEATHER STRIP <i>new</i>	1	155.40	+	155.40
REAR LH FENDER <i>Bushed</i>	1	744.70	✓	744.70
REAR LH FENDER GLASS MOULDING <i>new</i>	1	105.00	✓	105.00
REAR LH FENDER INNER AIR VENT <i>could</i>	1	66.70	✓	66.70
REAR SPARE TYRE CARRIAGE <i>new</i>	1	235.40	+	235.40
REAR SPARE TYRE CARRIAGE BRACKET <i>new</i>	1	50.00	+	50.00
REAR SPARE TYRE CARRIAGE SCREW <i>new</i>	1	45.00	+	45.00
REAR TAILGATE <i>Dented</i>	1	1004.70	303 ✓	1,004.70
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	58.70	✓	58.70
REAR TAILGATE DAMPER L/R <i>new</i>	2	168.70	+	337.40
REAR TAILGATE HINGES L/R <i>new</i>	2	101.40	+	202.80
REAR TAILGATE INNER PULL HANDLE <i>Dented</i>	1	58.30	✓	58.30
REAR TAILGATE INNER RUBBER STOPPER L/R <i>new</i>	2	18.90	+	37.80
REAR TAILGATE INNER TRIM BOARD <i>could</i>	1	400.00	✓	400.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MOHAMED ZAINORDIN BIN MOHD BAHARIN
BLK 987B BUANGKOK GREEN #02-27
SINGAPORE 532987

Contact : 80221352

TAX INVOICE

Repair Code : CLM16436

Date in : 01/10/2024

Vehicle Num. : SLP3801J

Model : HONDA STREAM 1.8X A

Chassis/Eng# : RN61084050/R18A1793238

REAR TAILGATE MECHANISM LOCK	Jammed	1	201.40	✓	201.40
REAR TAILGATE OUTER GARNISH	crack	1	280.00	✓	280.00
REAR TAILGATE WEATHER STRIP	cut	1	296.00	✓	296.00
REAR TAILGATE WINDSCREEN MOULDING	new	1	169.00	✓	169.00
REAR TAILLAMP INNER PANEL L/R	Build	2	188.40	✓	376.80
REAR TAILLAMP L/R	Build	2	398.00	✓	796.00
REAR THIRD SEAT GARNISH	Deltd	1	265.90	✓	265.90
REAR THIRD SEAT L/R	new	2	1350.00	+	2,700.00
ROOF TOP PANEL	Riv	1	1028.00	+	1,028.00
ROOF TOP SIDE MOULDING L/R	cut	2	395.00	✓	790.00
Subtotal before discount					43,257.50
Percentage discount 20%					8,651.50
Sub-total 1					34,606.00
DASHBOARD RADIO SET	new	1	1800.00	80	1,800.00
FRONT BATTERY	new	1	280.00	+	280.00
FRONT BONNET INSULATOR CLIPS - SET	new	1	50.00	30	50.00
FRONT BUMPER CLIPS - SET	new	1	80.00	30	80.00
FRONT BUMPER NUMBER PLATE	Deltd	1	25.00	✓	25.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

MOHAMED ZAINORDIN BIN MOHD BAHARIN
 BLK 987B BUANGKOK GREEN #02-27
 SINGAPORE 532987

Contact : 80221352

TAX INVOICE

Repair Code : CLM16436

Date in : 01/10/2024

Vehicle Num. : SLP3801J

Model : HONDA STREAM 1.8X A

Chassis/Eng# : RN61084050/R18A1793238

FRONT BUMPER NUMBER PLATE HOLDER <i>new</i>	1	50.00	<i>x</i>	50.00
FRONT FENDER INNER SHIELD CLIPS L/R - SET <i>new</i>	2	50.00	<i>30</i>	100.00
FRONT FENDER INNER TOP GARNISH CLIPS L/R - SET <i>new</i>	2	30.00	<i>+</i>	60.00
FRONT GRILLE CLIPS - SET <i>new</i>	1	40.00	<i>20</i>	40.00
FRONT RH SEAT <i>new</i>	1	1680.00	<i>+</i>	1,680.00
FRONT WINDSCREEN SEALANT <i>new</i>	1	80.00	<i>60</i>	80.00
RADIATOR COOLANT <i>new</i>	1	80.00	<i>40</i>	80.00
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	<i>30</i>	80.00
REAR BUMPER REVERSE SENSOR (4 EYES) - SET <i>new</i>	1	320.00	<i>200</i>	320.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	40.00	<i>20</i>	40.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>new</i>	2	50.00	<i>60</i>	100.00
REAR FLOOR PANEL INSULATOR MAT <i>new</i>	1	300.00	<i>200</i>	300.00
REAR LH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	<i>+</i>	50.00
REAR LH FENDER GLASS SEALANT <i>new</i>	1	60.00	<i>40</i>	60.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	<i>30</i>	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	1	40.00	<i>20</i>	40.00
REAR TAILGATE REVERSE CAMERA <i>new</i>	1	600.00	<i>+</i>	600.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	80.00	<i>60</i>	80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MOHAMED ZAINORDIN BIN MOHD BAHARIN
BLK 987B BUANGKOK GREEN #02-27
SINGAPORE 532987

Contact : 80221352

TAX INVOICE

Repair Code : CLM16436

Date in : 01/10/2024

Vehicle Num. : SLP3801J

Model : HONDA STREAM 1.8X A

Chassis/Eng# : RN61084050/R18A1793238

REAR TAILLAMP CLIPS L/R - SET	2	25.00	50.00
ROOF TOP COMPARTMENT BOX ASSY	1	1950.00	1,950.00
Subtotal before discount			8,045.00
Percentage discount 0%			0.00
Sub-total 2			8,045.00
Parts-total			42,651.00

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	60	150.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	30	80.00
To remove, change air bag, air-bag sensor, air-bag wire and resetting system.	280	350.00
To reset system after repair works	X	500.00
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	✓	80.00
To remove, change windscreen. (Front)	120	150.00
To remove, reinstall tailgate windscreen	120	150.00
To remove, reinstall fender glass	60	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	100	180.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	60	80.00
To remove, change dashboard fascia and transfer where necessary.	250	400.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel, rear bumper, rear doors (L/R), and roof top panel.	1800	1,800.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MOHAMED ZAINORDIN BIN MOHD BAHARIN
BLK 987B BUANGKOK GREEN #02-27
SINGAPORE 532987

Contact : 80221352

TAX INVOICE

Repair Code : CLM16436

Date in : 01/10/2024

Vehicle Num. : SLP3801J

Model : HONDA STREAM 1.8X A

Chassis/Eng# : RN61084050/R18A1793238

To re-spray painting on the front bonnet, front support panel, front fender (L/R), front bumper and front doors (L/R).

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	9,950.00
Parts & Labour Total	52,601.00

10w	2,000.00
50	100.00
28w	3,400.00
150	300.00
60	80.00

6830

*** This is a computer-generated document which requires no signature.***

page 9

Adnan Lj
2/s 03/10/24.

21 Days.

total: 34396.28

h/s: 27.51C ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: