

Performance Motors Limited

A Sime Darby Motors Company
CO. Reg. No. 197401559N GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 71365

Page No. : 1 of 5

Date Estimated : 01/10/2024

Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

Seah Hwee Lian
62 Jalan Kemuning

Singapore 769784

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDM163Y	WBY42DU050SB20699	30/11/2023	iX3	17

DESCRIPTION

To replace rear bumper, tailgate and attachments.

VALUE

1700 2,550.00

To painting rear bumper and tailgate.

2,076.00

To check electrical wiring system and lighting at the rear section for proper function.

177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

177.00

To remove and install battery positive cables including perform high current test and charge up battery.

531.00

To remove and install rear windscreen glass to facilitate repair. (For glass that are NOT shattered).

649.00

To conduct water leak tests.

75.00

To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.

531.00

To carry out body cavity preservation. (Per panel).

118.00

Sundries

150.00

Total Labour 1: 7,034.00

DESCRIPTION

QTY

PRIC

VALUE

TRUNK LID 86

1 2,241.15

2,241.15

REAR BUMPER PANEL PRIMED (PDC+PMA) cut

1 1,629.75

1,629.75

REAR BUMPER BOTTOM TRIM PANEL (GLOS sure

1 304.55

304.55

REAR BUMPER COVER PAINTED (FROZEN G sure

1 287.15

287.15

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

200, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 71365
Date Estimated : 01/10/2024
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDM163Y	WBY42DU050SB20699	30/11/2023	iX3	17

DESCRIPTION	QTY	PRIC	VALUE
LH BOTTOM COVER (i BLUE) <i>XM</i>	1	91.90	91.90
RH BOTTOM COVER (i BLUE) <i>sel</i>	1	91.90	91.90
EMBLEM GROMMET <i>m</i>	2	1.00	2.00
PLAQUE 82MM <i>m</i>	1	76.55	76.55
LETTERING (i X3) <i>m</i>	1	103.35	103.35
(DG) CLEANER R1 (100ML) <i>m</i>	1	36.25	36.25
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>m</i>	2	154.00	308.00
(DG/SL) ACTIVATOR 1 30ML <i>m</i>	1	40.50	40.50
			5,213.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Claims OD *3rd Party* / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time *15/10/24* Excess S\$ _____

Surveyor's Name *RASUL* Sign _____

Surveyor's Tel *96061668* Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend *5 days*



Labour 1	:	7,034.00
Parts	:	5,213.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	1,102.23
Grand Total	:	13,349.28

THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors

BMW Dealer



Supplementary

Estimate No. : b1 71365
Date Estimated : 01/10/2024
Prepared By : Inthiran A/L Thurasamy

Page No. :

- ESTIMATE REPAIR FOR -

Seah Hwee Lian
62 Jalan Kemuning

Singapore 769784

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEASE
SDM163Y	WBY42DU050SB20699	30/11/2023	ix3	180156

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT <i>re</i>	3.05	2.00	0.00	6.10
# BLIND RIVET NUT M6 <i>re</i>	3.15	4.00	0.00	12.60
# EXPANDING RIVET BLACK <i>re</i>	1.50	10.00	0.00	15.00

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	33.70
Total Labour & Parts (before GST) :	33.70

Performance Motors Limited.
Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

A Sime Darby Motors Company