

NOT Withheld
 11 Rmp \$7650/h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G

SHF623B

Vehicle No.:
 Chassis No.:
 Co UEN:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

21 OCT 2021

AAD2409-116

SHF623B

JTDKB3FU403092081
 200303878K
 TOYOTA
 PRIUS GEN 4
 28/09/24
 SDX 4882X / China
 12/3/2021

PART

LIST

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 COVER, FLOOR UNDER, NO.1 LH
- 1 COVER, FLOOR UNDER, NO.2 RH
- 1 COVER, REAR FLOOR CTR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 PANEL SUB-ASSY, QUARTER, RH
- 1 LINER, REAR WHEEL HOUSE, RH
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 SPOILER SUB-ASSY, REAR
- 1 SEAL, REAR SPOILER
- 1 GLASS, BACK WINDOW FIX
- 1 DAM, WINDOW GLASS ADHESIVE
- 1 LAMP ASSY, REAR, LH
- 1 LAMP ASSY, REAR, RH
- 1 WEATHERSTRIP, BACK DOOR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH

\$	B ₁	612.68	✓
\$	B ₁	419.90	✓
\$	CM	27.93	✓
\$	B ₁	472.19	✓
\$	IN	167.48	X
\$	DIY	167.48	✓
\$	IN	49.25	X
\$	IN	49.25	X
\$	IN	220.50	X
\$	IN	304.92	X
\$	CM	290.43	✓
\$	IN	159.39	X
\$	B ₁	824.46	✓
\$	B ₁	1,099.46	✓
\$	IN	176.09	X
\$	B ₁	1,443.86	✓
\$	IN	1,986.92	X
\$	IN	21.32	X
\$	B ₁	957.39	✓
\$	IN	65.21	✓
\$	CM	370.44	✓
\$	CM	370.44	✓
\$	IN	469.25	X
\$	CM	1,156.89	✓
\$	IN	305.66	X
\$	IN	305.66	X
\$	IN	77.18	X
\$	IN	77.18	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2409-**SHF623B**

- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR

\$	<i>me</i>	68.88	—
\$	<i>me</i>	68.88	—
\$	<i>me</i>	90.30	—
TOTAL	\$	12,876.87	
25%	\$	3,219.22	
	\$	9,657.65	

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE STICKER "Trans-Cab"
- 1 REAR TAILGATE STICKER "6555-3333"
- 1 REAR BUMPER PROTECTOR
- 2 SEAM SEALANT
- 1SET REAR BUMPER RETAINER CLIP
- 1 END PANEL TRIM CLIP

\$	<i>me</i>	700.00	<i>2200n</i>
\$	<i>me</i>	95.00	<i>600n</i>
\$	<i>me</i>	150.00	<i>800n</i>
\$	<i>me</i>	200.00	—
\$	<i>me</i>	130.00	<i>600n</i>
\$	<i>me</i>	80.00	<i>300n</i>
\$	<i>me</i>	80.00	<i>300n</i>
\$	<i>nsp</i>	180.00	X
\$	<i>nn</i>	250.00	X
\$	<i>nn</i>	85.00	X
\$	<i>nn</i>	65.00	X

TOTAL \$ 2,015.00**TOTAL PARTS \$ 11,672.65****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 *1800*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *1000*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,600.00 *12000*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X

Trans-cab Auto Services Pte Ltd**AAD2409-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF623B

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 180.00 *601*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 250.00 *601*

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 *132d*

To reinstall rear bumper parking sensor.

\$ ~~170.00~~ 170.00 ** 501*

To Check Electrical Lighting Concerned.

\$ 170.00 *201***TOTAL \$ 5,030.00****Over All Total \$ 16,702.65****(PART-BY-PART) Repair Days****12 DAYS***9 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: