



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24100058/Uvp3m4
(BUDGET DIRECT INSURANCE)	Date:	18/10/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGZ 5125X	Veh. Inspected	SGS 7380Z
Policy No.	P11096874R00	Coverage	0
Claim No.	C10032033/JK	Excess	\$0.00
Assign From	JANICE KOH	Assign Date	02/10/2024

### 2. Vehicle Details

Make & Model	TOYOTA ESTIMA 2.4 A	C.C	2362
Engine No.	2AZC048610	Year of Reg.	22/03/2007
Chassis No.	ACR507031203	Colour	BLACK
Odometer	214218 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55R17	YOKOHAMA	6
L/H Front Tyre	225/55R17	YOKOHAMA	6
R/H Rear Tyre	225/55R17	YOKOHAMA	6
L/H Rear Tyre	225/55R17	YOKOHAMA	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	02/10/2024	Inspection Date	02/10/2024
Survey held at	SPEEDWERKZ PTE LTD 1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY@KAKI BUKIT, SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days