



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 01/10/24
VEHICLE : SND4238T
MAKE/MODEL : TOYOTA / SIENTA
CHASSIS NO : JTDZZ9H300L000935
MILLAGE :
TYRE SIZE :
DOA : 30/09/2024
TP INSURANCE : AIG

Not Authorized
L1 Rep &
Resurvey After Repair
11-13 days

List items

01 PC FRONT BONNET
02 PC FRONT BONNET HINGE @ \$ 124.85
01 PC FRONT BONNET LOCK
01 PC FRONT BONNET INSULATOR
01 PC FRONT BUMPER
02 PC FRONT BUMPER SIDE RETAINER @ \$ 80.06
01 PC FRONT BUMPER SPONGE
02 PC FRONT BUMPER FOG LAMP COVER @105.95
02 PC FRONT BUMPER SIDE OUTER MOULDING @ \$391.48
01 PC FRONT BUMPER REINFORCEMENT
01 PC FRONT BUMPER LOWER GRILLE
02 PC FRONT LH BUMPER LOWER GRILLE OUTER MOULDING
01 PC FRONT RH BUMPER LOWER GRILLE OUTER MOULDING
01 PC FRONT BUMPER UNDER COVER
01 PC FRONT BUMPER EMBLEM
01 PC ENGINE UNDER SIDE SHEILD
02 PC FRONT HEADLAMP @ \$1414.6
01 PC SUPPORT PANEL
01 PC SUPPORT PANEL TOP GARNISH
01 PC SUPPORT PANEL TOP GARNISH RUBBER
01 PC BRACE PANEL
01 PC SUPPORT AIR DUCT RH
01 PC SUPPORT AIR DUCT LH
01 PC RADIATOR
01 PC A/C CONDENSER
01 PC TAIL GATE
02 PC TAIL GATE HINGES @ \$235.40
02 PC TAIL GATE ABSORBER @ \$378.50
01 PC TAIL GATE TRIMBOARD
01 PC TAIL GATE OUTER MOULDING
01 PC TAIL GATE OUTER HANDLE
01 PC TAIL GATE EMBLEM (HYBRID)
01 PC TAIL GATE EMBLEM (LOGO)

Bus \$ 1,304.92 ✓
DVS \$ 249.70 ✓
SPR \$ 139.30 ✓
\$ 249.96 X
Bus \$ 1,465.00 ✓
SPR \$ 160.12 ✓
\$ 311.16 ?
\$ 211.90 X
\$ 782.96 X
\$ 740.25 ?
CM \$ 1,751.64 ✓
\$ 351.60 ?
CM \$ 351.60 ✓
\$ 461.76 X
\$ 197.24 ✓
\$ 336.28 X
\$ 2,829.20 ?
Bus \$ 1,460.52 ✓
NPS \$ 227.48 X
\$ 27.46 X
\$ 149.56 ?
\$ 73.28 ?
\$ 68.24 ?
\$ 1,025.40 ?
\$ 956.30 ?
\$ 2,070.40 ✓
\$ 470.80 ?
\$ 757.00 ?
Bus \$ 590.30 ✓
NPS \$ 365.90 X
my CM \$ 245.20 ✓
\$ 184.90 ✓
Bus \$ 230.60 ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

01 PC	TAIL GATE INNER LOCK
01 PC	TAIL GATE CATCH LOCK
01 PC	TAIL GATE INNER HANDLE
01 PC	REAR WIPER MOTOR
01 PC	REAR BUMPER
02 PC	REAR BUMPER SIDE RETAINER @ \$185.30
02 PC	REAR BUMPER CORNER PANEL GANISH @ \$246.75
01 PC	REAR BUMPER GARNISH
01 PC	REAR BUMPER PARKING SENSOR GARNISH
02 PC	REAR BUMPER REFLECTOR @ \$220.90
02 PC	REAR CORNER PANEL @ \$265.30
02 PC	REAR CORNER PANEL BRACKET @ \$208.50
01 PC	REAR END PANEL
01 PC	REAR END PANEL TOP GANISH
01 PC	REAR FENDER INNER TRIM BOARD LH
01 PC	REAR FENDER INNER TRIM BOARD RH
01 PC	REAR SPARE TYRES PANEL
01 PC	REAR SPARE TYRES PANEL BOARD
01 PC	REAR WEATHERSTRIP
02 PC	REAR TAIL LAMP @ \$785.40
02 PC	REAR TAIL GATE LAMP @ \$653.20
01 PC	REAR TAIL GATE CAMERA
01 PC	REAR ANTENNA SENSOR
TOTAL PARTS COST	

\$	591.90	✓
\$	155.70	?
\$	97.85	?
\$	745.20	?
\$	2,128.19	✓
\$	370.60	✓
\$	493.50	?
\$	325.40	✓
\$	164.90	?
\$	441.90	X
\$	530.60	X
\$	417.00	?
\$	1,589.60	✓
\$	375.60	✓
\$	638.90	?
\$	638.90	✓
\$	1,023.60	?
\$	756.30	?
\$	425.15	?
\$	1,570.80	?
\$	1,306.40	?
\$	640.50	X
\$	389.10	?
\$	36,615.52	

Special Nett Item:

06 PC	FRONT BONNET INSULATOR CLIP @ \$8
08 PC	FRONT BUMPER CLIP @ \$ 8
01 PC	FRONT NUMBER PLATE
01 PC	FRONT NUMBER PLATE COVER
02 PC	PARKING SENSOR @ \$220
10 PC	REAR TRIM BOARD CLIP @ \$8
01 PC	REAR WINDSCREEN SEALANT
06 PC	BUMPER CLIP @ \$8

\$	48.00	X
\$	64.00	—
\$	30.00	} 45.00
\$	30.00	
\$	440.00	✓
\$	80.00	—
\$	100.00	40.00
\$	48.00	—
\$	840.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS
4. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL
5. TO SUPPLY DIAGNOSTIC & REPROGRAMMING
6. TO SUPPLY LABOUR TO REMOVE & REFIT REAR WINDSCREEN
7. TO SUPPLY LABOUR TO REMOVE & REFIT REAR INNER UPHOLSTER
8. TO SUPPLY LABOUR TO TOP UP AIR COND GAS

\$	2,500.00	?
\$	1,500.00	1200
\$	300.00	400
\$	250.00	?
\$	300.00	?
\$	300.00	1200
\$	300.00	1000
\$	120.00	1000
\$	5,570.00	

TOTAL PARTS

SPECIAL NETT ITEM

TOTAL LABOUR

TOTAL COST OF REPAIR

\$	36,615.52
\$	840.00
\$	5,570.00
\$	43,025.52