

First Capital Insurance 6 Raffles Quay Singapore 048580

14/11/2024

Dear Sir / Madam

RE: DFSK EC31 Reg: GBM1073R

We are pleased to submit estimate for the repair of the above-mentioned vehicle:

Please confirm your acceptance of this quotation by sending us a return fax with your

| A) Labour Description | <u>Labour Cost</u> |
|--|--|
| 1 Remove, install & renew :- | \$ 3,500.00 2,500 |
| Hoist needed, Rear Carriage Box, Rear Carriage, Rear Lh Li | ght, Rear Rh light, |
| Parking Sensor, Rear Axle, Rear Absorber and Battery | |
| 2 To Supply Panel Beater to Knock Back and Welding The Re | s 25960 150 (4180) |
| 3 To Supply Electrician To Dismount High Voltage Before and After start work | \$ 25960 150 4130 |
| 4 To Respray Layer of Anti Rust Coating Rear and Anti Collisi | |
| 5 Respray premier & paint: | 100 |
| Rear carriage, Parking Sensor, | \$ 1,000.00 900 |
| 6 To Supply Labour And Machinery (Hunter) To Done Up All Alignment Before and After | \$ 1,000.00 900 Wheel \$ 240.00 (80 |
| 7 Merimen | \$ 12.00 |
| | 5 2.18 LEXCLUMED |
| 8 Search Fee | 3 2.18 J C/C 2.0103 |
| 9 Loss of use 16 of Oct 120 currently x30 including sat | and sun \$ 3,600.00 |
| Do note that the following Repairs needed to take up to 1 | |
| | |
| B) Parts | Qty PLUS 10% |
| 1 Rear Carriage CN | 1 \$ 5,684.88 |
| 2 Parking sensor SMA | 1 \$ 186.00 12505.88 |
| 3 Rear Rh light C/F | 1 \$ 55.00 |
| 4 Rear Lh light | 1 \$ 80.00 |
| 5 Rear Carriage Aluminium box | 1 \$ 7,775.00 6500 |
| TOTAL: | |
| Total | abour \$ 5,740.00 |
| Total Parts F | Plus 10% \$ 13,780.88 |
| | \$ 19,520.88 |
| | 9% GST \$ 1,756.88 |
| Gra | nd Total \$ 21,277.76 |
| Should this repair job require any additional parts, we will info | orm you and bill you accordingly. 4130.0 |

Workshop Department

Yours sincerely,

signature and company stamp on it.

Signature & Company stamp

I agree and accept the above quotation.