

Not Withheld
\$640k

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7648E

AAD2401-110

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

30 SEP 2024

SHB7648E

JTDKB3FUX03082560

200303878K

TOYOTA

PRIUS

23/1/2024

SKP6790Z/ China

1/8/2019

	PART
1	COVER, REAR BUMPER
1	COVER, REAR BUMPER, LOWER
1	GUARD, REAR BUMPER, CENTER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	FILLER, REAR BUMPER EXTENSION, LH
1	COVER, FLOOR UNDER, NO.1 LH
1	COVER, REAR FLOOR CTR
1	COVER, BACK DOOR TRIM
1	PANEL SUB-ASSY, BODY LOWER BACK
1	COVER, REAR COMBINATION LAMP, LH
1	LENS AND BODY, REAR LAMP, LH
1	LENS & BODY, REAR COMBINATION LAMP, LH
1	PANEL SUB-ASSY, QUARTER, LH
1	LINER, REAR WHEEL HOUSE, LH

	LIST	
\$	SK	558.39 X
\$	SL	19.43
\$	SL	726.92
\$	SL	419.90
\$	SL	155.72
\$	SL	220.50
\$	SL	290.43
\$	SL	31.50
\$	SK	824.46
\$	SL	81.48
\$	SL	634.73
\$	SL	559.13
\$	SK	1,099.46
\$	SL	176.09
TOTAL	\$	5,798.10
25%	\$	1,449.53
	\$	4,348.58

Special Nett

1SET	PARKING AID
1	REAR BUMPER CLIP
1	FENDER LINER CLIP
1	REAR TAIL LAMP CLIP
1	END PANEL INNER TRIM CLIP
2	WINDSCREEN SEALANT
1	WINDSCREEN MOULDING
1	WINDSCREEN INNER SPONGE SEAL

\$	SL	700.00	
\$	NN	65.00	
\$	NN	65.00	
\$	NN	65.00	
\$	NN	60.00	
\$	NN	150.00	
\$	NN	200.00	
\$	NN	130.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7648E**AAD2401-110****TOTAL \$ 1,435.00****TOTAL PARTS \$ 8,543.40****LABOUR**To Rust-Proofing and apply undercoat Of The Affected Areas. \$ *nn* 250.00 *X*Putty And Spray Painting Of The Affected Portion. \$ 1,800.00 *4401*To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ *nn* 380.00 *X*To Check Electrical Lighting Concerned. \$ *nn* 170.00 *X*Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 3,000.00 *2001*To check steering geometry and computer wheel alignment \$ *nn* 220.00 *X*To transfer of rear fender panel fittings, attachment and perform water seepage test. \$ *nn* 170.00 *X***TOTAL \$ 5,990.00****Over All Total \$ 18,881.98****(PART-BY-PART) Repair Days***06 Days**2 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: