



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref:	CS/SMO24100066/Uqp3m4 (N)
50 RAFFLES PLACE #03-03			Date:	03/01/2025
SINGAPORE LAND TOWERSINGAPORE 048623			Code:	SMO
ATTN: THELMA				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 4117G	Veh. Inspected	XD 7325L	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2403185/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	02/10/2024	
2. Vehicle Particulars & Condition				
Make & Model	SCANIA P400CB8X4MHZ	c.c	12742	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	YS2P8X40005311629	Colour	SILVER	
Odometer	258554 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	315/80R22.5 (D)	AURUN	6/6 mm	
L/H Front Tyre	315/80R22.5 (D)	AURUN	6/6 mm	
R/H Rear Tyre	315/80R22.5 (D/D)	AURUN	6/6/6/6 mm	
L/H Rear Tyre	315/80R22.5 (D/D)	AURUN	6/6/6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/09/2024	Inspection Date	18/11/2024	
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	