

not Authorised
n/c

Repair sum @ 2500

Hby S.

18/11/24

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

11-12-24

Date of Accident : 11-09-24

Attn: Mr. Marcus

OUR REF : XD 7325L/T/24

Date in/out : 18/11/24 to 21/11/24

Lie Yong Logistics & Engineering Pte Ltd

Blk 554 Jurong West St 42

#06-347

Singapore 640554

ESTIMATE BILL ON VEH NO : XD 7325L

VEHICLE MODEL : SCANIA P400C

CHASSIS NO. : YS2P8X40005311629

SPECIAL LIST ITEM

Tail Gate Assy

cnc 2,000.00

60KM Sticker

ner 20.00 10 S/W

Rear Bumper

n/c DO 1,600.00 X

Rear Bumper Reflector Sticker

n/c 150.00 X

Tail Gate Lower Member Sticker

2pcs @ 120.00 ner 240.00 150 S/W

Tail Gate bracket

ner 160.00 80 S/W

LABOUR CHARGE

To Respray Affected Areas

900.00 200

To Renew Damaged Parts, Straighten & Repair,
And Aligned All Parts

900.00 400

5,970.00

GST 8%: 417.90

TOTAL AMOUNT: 6,387.90

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) to the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S.N - 2240