

05.11.2024 10am.



Mercedes-Benz

05/10

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLL4728C

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information
WIP No 21151
Reg No/Reg Date SLL4728C / 02/02/2024
Date In/Mileage 1 0
Chassis No W1K1183842N4533367
Engine No 28281480092301
Make/Model MB/CLA 180 COUPE
Colour/Trim 027 787 Mountain Gr/ 041 111 Black

SLL4728C

Account No	Terms	Date/Time Printed	CSE	Operator				
WF001862	Credit	02/10/2024/ 16:33		1208/ Foong Shiuh Jye				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : 7240012766 // 30 SEP 2024								
DRIVE IN/EXCESS :								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
A BPILAB								
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								
A BPIRES								
RESPRAY BUMPER REAR								
A BPILAB								
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO								
M BPNSUN								
SUNDRIES								
M BUMPER REAR LOWER BLACK <i>de</i>					1.00	517.32	00.00	517.32
M BUMPER REAR CHROME <i>cm</i>					1.00	119.84	00.00	119.84
M BUMPER REAR CHROME RIGHT <i>cm</i>					1.00	146.70	00.00	146.70

THIS IS NOT AN OFFICIAL TAX INVOICE

Rasm
Ap 900 100 68
3 days
05/11/24
Res after repk

960 1088.00 ✓
800 960.00 ✓
0.10 380.00 ✓
15.00 ✓

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : 7240012766 // 30 SEP 2024

DRIVE IN/EXCESS :

DATE IN/DATE SURVEY:

BY/AUTHORIZED ON :

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY BUMPER REAR

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO

M BPNSUN

SUNDRIES

M BUMPER REAR LOWER BLACK de

M BUMPER REAR CHROME cm

M BUMPER REAR CHROME RIGHT cm

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Handwritten notes:
Ap 9w 100 68
3 days
05/11/24
Res after rsk

Handwritten calculations:
360 1088.00
800 960.00
380.00
15.00

Days Of Repair:

Final Balance

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Confirmed & accepted by

Foong Shih Jye

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6771 4346 HP: 97896038 Fax: 6872 1272

Email: shihjye.foong@cyclecarriage.com.sg

Nett 3,146.86
9% GST on 3146.86 283.22

Total Payable 3,430.08

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

Page 1 of 1