

C

Kenneth

1074

The U/C / Chassis frame / Body Structure affected due to collision.

D.O.I.

N/S	O/S

28110 11 Rye # 3250. Cash (Red. # 1264, 28%)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	747A
Vehicle Details	
Vehicle No.:	SNK2993Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	01 Oct 2024
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G A
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	L15B5004158
Chassis No.:	GK81103534
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$19,451.00
Original Registration Date:	13 Jun 2017
First Registration Date:	13 Jun 2017
Transfer Count:	1
Actual ARF Paid:	\$9,451.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jun 2027
PARF Rebate Amount:	\$5,670.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,106.00
COE Rebate Amount:	\$13,784.00
Total Rebate Amount:	\$19,454.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 01 Oct 2024

OK

Date: 4/10/2024

Vehicle No: SNK2993Y

Model: HONDA SHUTTLE

Chassis: GK81103534

Reg.Year: 2017

Not Notwithstanding
6/1 Sep @ 3250/2
Resurvey After Paint

Third Party Insurer: AUTO & GENERAL

Third Party Veh No: SJK3898E

Date of Accident: 28/8/2024

Estimator: JONATHAN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	RR BOOTLID <i>1193.70</i>			\$ <i>11</i> 1,250.00 ✓
	RR WEATHERSTRIP		<i>Dis/pt</i>	\$ 180.00 ✓
	RR BOOT INNER TRIM BOARD		<i>nd/ent</i>	\$ 280.00 ✓
	RR END PANEL		<i>B</i>	\$ 560.00 ✓
	RR END PANEL TOP GARNISH		<i>nd</i>	\$ 170.00 ✓
	RR BUMPER			\$ <i>Bm</i> 980.00 ✓
	RR EMBLEM (SHUTTLE)			\$ <i>na</i> 110.00 ✓
SUB TOTAL				\$ 3,530.00
Less 20%				-\$ 706.00
PARTS TOTAL				\$ 2,824.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	RR BUMPER CLIPS			\$ <i>na</i> 50.00 ✓
	RR BOOT INNER TRIM BOARD CLIPS			\$ <i>na</i> 50.00 X
	RR W/SCREEN SEALANT			\$ <i>na</i> 100.00 <i>Garw</i>
S/N TOTAL				\$ 200.00

LABOUR CHARGES:

To remove, replace, repair, readjust & refix RR affected areas	\$ 800.00	<i>Good</i>
To perform wiring checks on electrical systems	\$ 30.00	<i>201</i>
To remove, putty, repair, sand and respray affected areas	\$ 600.00	✓
To remove, replace & refix bumper sensors	\$ 30.00	✓
To remove, replace & reinstall Bootlid inner mechansim	\$ 30.00	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JONATHAN

LABOUR TOTAL \$ 1,490.00

TOTAL \$ 4,514.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 6 Singapore 554500
Tel: (+65) 6494 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 56047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

