

Date: 4/10/2024

Vehicle No: SNK2993Y

Model: HONDA SHUTTLE

Chassis: GK81103534

Reg. Year: 2017

Not Notwithstanding
6/1 Sep @ 3250/-
Resurvey After Paint

Third Party Insurer: AUTO & GENERAL

Third Party Veh No: SJK3898E

Date of Accident: 28/8/2024

Estimator: JONATHAN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	RR BOOTLID <i>1193.70</i>			\$ <i>Rn</i> 1,250.00 ✓
	RR WEATHERSTRIP		<i>Dis/pt</i> \$	180.00 ✓
	RR BOOT INNER TRIM BOARD		<i>nd/ent</i>	280.00 ✓
	RR END PANEL		<i>Bn</i> \$	560.00 ✓
	RR END PANEL TOP GARNISH		<i>nd</i> \$	170.00 ✓
	RR BUMPER		\$ <i>Bn</i>	980.00 ✓
	RR EMBLEM (SHUTTLE)		\$ <i>Rn</i>	110.00 ✓
SUB TOTAL				\$ 3,530.00
Less 20%				-\$ 706.00
PARTS TOTAL				\$ 2,824.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	RR BUMPER CLIPS			\$ <i>Rn</i> 50.00 ✓
	RR BOOT INNER TRIM BOARD CLIPS			\$ <i>Rn</i> 50.00 X
	RR W/SCREEN SEALANT			\$ <i>Rn</i> 100.00 ✓
S/N TOTAL				\$ 200.00

LABOUR CHARGES:

To remove, replace, repair, readjust & refix RR affected areas	\$ 800.00	<i>Good</i>
To perform wiring checks on electrical systems	\$ 30.00	<i>201</i>
To remove, putty, repair, sand and respray affected areas	\$ 600.00	✓
To remove, replace & refix bumper sensors	\$ 30.00	✓
To remove, replace & reinstall Bootlid inner mechanism	\$ 30.00	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LABOUR TOTAL \$ 1,490.00

TOTAL \$ 4,514.00

JONATHAN

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Bik 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 560047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

