

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24100076/TNP3E2
Date: 09/10/2024**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MAB00157
Claimant Vehicle No :	SHA8824L	Insured Vehicle No :	SMU8400L
Date of Loss:	02/10/2024	Nature of Claim:	TP
		Claim No:	M2405745

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA8824L		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2C28206
Reg. Date:	31/05/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU603081311
Colour:	Yellow	Odometer:	778864 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,325.16	2,489.02	1,836.14	42.45
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	2,380.00	1,630.00	750.00	31.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,717.16	4,131.02	2,586.14	38.50
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	6,717.16	3,300.00	3,417.16	50.87
+ GST 9.00/9.00% (S\$)	604.54	297.00	307.54	50.87
Nett Amount (S\$)	7,321.70	3,597.00	3,724.70	50.87

INSPECTION

Date of Assignment:	03/10/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	03/10/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Oct 2024)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA8824L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER SUB ASSY RH	Bent	1,111.93 FL	*1,111.93 FL
2	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	86.50 FL	*86.50 FL
3	1		*FRONT FENDER SHIELD RH	Deformed	198.50 FL	*198.50 FL
4	1		*FRONT BUMPER COVER	Repair	586.18 FL	*- FL
5	1		*FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
6	1		*FRT DOOR PANEL RH	Repair	1,264.00 FL	*- FL
7	1		*ROCKER PANEL GARNISH RH	Repair	576.00 FL	*- FL
8	1		*FRT WHEEL RIM RH	Dented	1,555.10 FL	*1,555.10 FL
9	1		*FRT DOOR COMFORT LOGO RH	Cut	75.00 F	*75.00 F
10	1		*RENEW ADVERTISEMENT	Necessary	200.00 F	*200.00 F
					Sub Total (\$\$)	5,675.21 3,227.03
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,350.05 738.01
					Total Parts (\$\$)	4,325.16 2,489.02

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (S\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,000.00	760.00
2	SPRAY PAINTING CHARGE	New	1,200.00	840.00
3	TRANSFER OF DOOR	New	120.00	0.00
4	TUFF KOTE	New	60.00	30.00
Gross Labour Cost (S\$)			2,380.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >