



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 29)

PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 29)

PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315


Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 7 of 29)



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P






PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P




PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 13 of 29)



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P




PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P




PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P





PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P





PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P



PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 29 of 29)

PHOTOGRAPHS FOR VEHICLE NO. : SLB 7833P

