

Wheelz 4 You

To: Motor Claims Department

Vehicle No: SLB7833P

Model: TOYOTA WISH

Date: 24/06/2023

not Andrew
No
24/6/23
d/s 13,000 /
6 hrs

Estimated Repair Cost For SLB7833P TOYOTA WISH

QTY	Parts	Amount
1	N/S WING MIRROR <i>SVC</i> <i>X</i>	\$ 1,188.00 <i>X</i>
1	N/S FRONT DOOR <i>3.5.00</i> <i>X</i>	\$ 2,693.00 <i>X</i>
1	N/S FRONT DOOR TAPE <i>24</i> <i>X</i>	\$ 101.00 <i>X</i>
1	N/S FRONT DOOR GLASS <i>17</i> <i>X</i>	\$ 830.00 <i>X</i>
1	N/S FRONT DOOR LOCK <i>24</i> <i>X</i>	\$ 709.00 <i>X</i>
1	N/S FRONT DOOR WEATHERSTRIP <i>21</i> <i>X</i>	\$ 212.00 <i>X</i>
1	N/S FRONT REGULATOR GEAR <i>21</i> <i>X</i>	\$ 355.00 <i>X</i>
1	N/S FRONT REGULATOR MOTOR <i>21</i> <i>X</i>	\$ 945.00 <i>X</i>
1	N/S FRONT DOOR INNER TRIM <i>1008.50</i> <i>X</i>	\$ 1,698.00 <i>X</i>
1	N/S FRONT DOOR CHROME MOULDING <i>320.00</i> <i>X</i>	\$ 635.00 <i>X</i>
1	N/S REAR DOOR <i>3.5.00</i> <i>X</i>	\$ 2,693.00 <i>X</i>
1	N/S REAR DOOR TAPE <i>24</i> <i>X</i>	\$ 101.00 <i>X</i>
1	N/S REAR DOOR LOCK <i>21</i> <i>X</i>	\$ 709.00 <i>X</i>
1	N/S REAR DOOR WEATHERSTRIP <i>21</i> <i>X</i>	\$ 212.00 <i>X</i>
1	N/S REAR DOOR REGULATOR GEAR <i>21</i> <i>X</i>	\$ 355.00 <i>X</i>
1	N/S REAR DOOR REGULATOR MOTOR <i>21</i> <i>X</i>	\$ 945.00 <i>X</i>
1	N/S REAR DOOR INNER TRIM <i>1008.20</i> <i>X</i>	\$ 1,698.00 <i>X</i>
1	N/S REAR DOOR HINGE (TOP) <i>21</i> <i>X</i>	\$ 182.00 <i>X</i>
1	N/S REAR DOOR HINGE (BTM) <i>21</i> <i>X</i>	\$ 182.00 <i>X</i>
1	N/S REAR DOOR CHECKER <i>21</i> <i>X</i>	\$ 221.00 <i>X</i>
1	N/S REAR DOOR CHROME MOULDING <i>320.00</i> <i>X</i>	\$ 635.00 <i>X</i>
1	N/S "B" PILLAR <i>21</i> <i>X</i>	\$ 1,400.00 <i>X</i>
1	N/S SIDE SKIRT <i>21</i> <i>X</i>	\$ 991.00 <i>X</i>
1	N/S ROCKER PANEL <i>21</i> <i>X</i>	\$ 1,453.00 <i>X</i>
1	N/S REAR QUARTER GLASS W/MOULDING <i>21</i> <i>X</i>	\$ 401.00 <i>X</i>
1	N/S REAR FENDER <i>1603.00</i> <i>X</i>	\$ 2,177.00 <i>X</i>
1	N/S REAR FENDER INNER SHIELD <i>21</i> <i>X</i>	\$ 431.00 <i>X</i>
1	N/S TAILLAMP <i>21</i> <i>X</i>	\$ 867.00 <i>X</i>
1	REAR BUMPER <i>831.50</i> <i>X</i>	\$ 1,007.00 <i>X</i>
1	N/S REAR BUMPER SIDE RETAINER <i>21</i> <i>X</i>	\$ 188.00 <i>X</i>
1	REAR END PANEL <i>21</i> <i>X</i>	\$ 905.00 <i>X</i>
1	N/S REAR RIM <i>1600.00</i> <i>X</i>	\$ 2,146.00 <i>X</i>
1	N/S REAR SHOCK ABSORBER <i>21</i> <i>X</i>	\$ 432.00 <i>X</i>
1	N/S REAR WHEEL HUB W/BEARING <i>21</i> <i>X</i>	\$ 919.00 <i>X</i>
Parts Sum:		\$ 30,616.00
Parts Less 25% :		\$ 7,654.00
Parts Total:		\$ 22,962.00

Special Nett Items

1	N/S FRONT DOOR INNER TRIM CLIPS	1m 30	\$	50.00	30
1	N/S REAR DOOR INNER TRIMS CLIPS	1m 30	\$	50.00	30
1	CHASSIS STICKER	11 X	\$	150.00	X
1	N/S SIDE SKIRT CLIP	1m 30	\$	50.00	30
1	N/S REAR QUARTER GLASS INNER SEAL	1m 20	\$	80.00	20
1	N/S REAR QUARTER GLASS SEALANT	1m 40	\$	40.00	40
1	N/S REAR FENDER INNER SHIELD CLIP	11 X	\$	40.00	X
1	REAR BUMPER CLIP	1m 30	\$	40.00	30
1	REAR BUMPER RIVET	11 X	\$	60.00	X
1	REAR END PANEL BODY SEALANT	11 X	\$	80.00	X
1	N/S REAR FENDER BODY SEALANT	11 X	\$	80.00	X
1	N/S FRONT DOOR BODY SEALANT	11 X	\$	80.00	X
1	N/S REAR DOOR BODY SEALANT	11 X	\$	80.00	X
1	N/S "B" PILLAR BODY SEALANT	11 X	\$	80.00	X
Special Nett Items Total:				\$	960.00

Labour & Misc Charges

	Description	Amount
To Check Light & Wirring		\$ 50.00 20
To Transfer Door parts		\$ 300.00 120
To transfer door glass		\$ 11 300.00 X
To fit reverse sensor on new bumper		\$ 50.00 30
To remove/refit n/s quarter glass		\$ 150.00 100
To remove/refit garnishes, inner trims, front seat, rear seat etc to facilitate repairs		\$ 350.00 80
To reset power window using diagnostic scanner		\$ 350.00 80
to reset central locking using diagnostic scanner		\$ 350.00 80
To transfer tyre to new rim		\$ 11 50.00 X
To replace undercarriage		\$ 280.00 120
To conduct 4 wheel computerise alignment		\$ 150.00 60
To rust proof on accident damage area		\$ 300.00 80
Labour to remove necc parts, to replace accident damaged parts		\$ 1,800.00 1000
To putty and respray accident damaged areas		\$ 1,800.00 1380
Labour Charges Total:		\$ 6,280.00

Parts Total:	\$	22,962.00
Special Nett Items Total:	\$	960.00
Labour Charges Total:	\$	6,280.00
Total Cost Of Repair:	\$	30,202.00
(Non-Inclusive of GST)		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-17473.40
257
13105.05
180
3070
16385.05
207
13084