



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100079/Unp3
16 RAFFLES QUAY	Date:	15/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9164B	Veh. Inspected	SNF 2061M
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24008692MFCT	Excess	\$0.00
Assign From	AINI	Assign Date	03/10/2024

2. Vehicle Details

Make & Model	TOYOTA PRIUS PLUS (AUTO)	C.C	1798
Engine No.	2ZR0C13164	Year of Reg.	23/05/2019
Chassis No.	JTDZS3EU90J030123	Colour	SILVER
Odometer	111868 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/40ZR18	MICHELIN	7
L/H Front Tyre	225/40ZR18	MICHELIN	7
R/H Rear Tyre	225/40ZR18	KUMHO	7
L/H Rear Tyre	225/40ZR18	KUMHO	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/10/2024	Inspection Date	03/10/2024
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days