



發福摩多車房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO. 375654/00C

Not Allowed
her
1/5 \$3600/
H dgs
Alpha Ake 17
2/10/24

Carplate: SBU4626J
Chassis No: JMONA306100103242
Accident Date: 25/09/2024
Make & Model: MAZDA MX 5

No.	Item	Price	✓/✗	Remarks
1	Rear Bootlid	\$ 1,780.00		na x
2	Rear Bootlid Weatherstrip	\$ 265.00		17 x
3	Rear Bootlid Lock Assembly	\$ 322.90		17 x
4	Rear Bootlid Outer Panel <i>garage</i>	\$ 680.00		cr - SW
5	Taillamp LH	\$ 619.20		17 x
6	Taillamp RH	\$ 619.20		17 x
7	Rear End Panel	\$ 822.00		20 / Sent ✓
8	Rear End Panel Top Garnish	\$ 210.50		17 x
9	Rear Bumper Reinforcement Beam	\$ 512.90		17 x
10	Rear Bumper Side Retainer LH	\$ 82.10		17 x
11	Rear Bumper Side Retainer RH	\$ 82.10		17 x
12	Rear Bumper Bracket LH	\$ 96.10		17 x
13	Rear Bumper Bracket RH	\$ 96.10		17 x
14	Rear Exhaust Pipe and Box	\$ 1,680.90		17 x
15	Rear Spare Tyre Wooden Board	\$ 318.90		17 x
16	<i>rear bumper inner retain</i>	<i>175</i>		<i>Sent</i>
17				
18				
19		<i>(202)</i>		
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				
30				
31				
32				
33				
34				
35				
36				

	Special Nett Items	Price	✓/✗	Remarks
1	Rear Number Plate and Casing	\$ 70.00		11X
2	Rear End Panel Sealant	\$ 120.00		11X
3	Rear Bumper Clips (1 Set)	\$ 40.00		1M ✓ S/N
4	Rear Bootlid Logo " ROADSTER "	\$ 80.00		1M 1M ✓ S/N
5	Rear Bumper (After Market)	\$ 1,800.00		Cm 1600 S/N
6				
7				
8				
9				
10				
11				
12				
13				
No.	All Necessary Work	Price	✓/✗	Remarks
1	To Carry Out Anti-rust Treatment	\$ 120.00		20
2	Remove and Install Exhaust Pipe and Box	\$ 280.00		11X
3	To Apply Ceramic Coating	\$ 650.00		11X \$150
4	Rewiring to Facilitate Repairs	\$ 150.00		11X
5	Remove and Refit All Trims, Upholders, Garnish and All Necessary to Facilitate Repair Works	\$ 320.00		50
6				
7				
8				
9				
10				
11	Labour to remove and replace damaged parts, including refitting and repositioning of replaced parts	\$ 1,200.00		500
12	Spray painting materials and respray of all affected and replaced parts necessary for paintwork	\$ 1,000.00		600
	Estimated No. of days for repairs and respray of all necessary	6 Days		

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-1007
202
805-60
2400
1400
4605-6
202
3684.