

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLT 6990E

	REPLACEMENT OF PARTS					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	REAR BUMPER	DEFORMED	\$1,067.70	\$1,067.70		
1	REAR BUMPER RETAINER LH	NOT NECESSARY	\$54.50	\$0.00		
1	REAR BUMPER REINFORCEMENT	* CHECK	\$189.90	\$0.00		
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	\$58.60	\$0.00		
1	REAR BUMPER REVERSE SENSOR LH	* CHECK	\$198.60	\$0.00		
1	END PANEL	* CHECK	\$565.70	\$0.00		
1	END PANEL UPPER GARNISH	NOT NECESSARY	\$174.20	\$0.00		
1	TAILLAMP OUTER LH	NOT NECESSARY	\$665.40	\$0.00		
1	REAR EXHAUST PIPE SYSTEM	NOT NECESSARY	\$1,496.30	\$0.00		
1	REAR EXHAUST FRONT RUBBER BUSH	NOT NECESSARY	\$52.90	\$0.00		
1	REAR EXHAUST REAR RUBBER BUSH	NOT NECESSARY	\$52.90	\$0.00		
6	END PANEL UPPER GARNISH CLIPS @\$4.60	* CHECK	\$27.60	\$0.00		
	LESS 20.00% DISCOUNT		(\$920.86)	(\$213.54)		
			\$3,683.44	\$854.16		
	Special	Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	WARNING LIGHT - RESETTING (SN)	* CHECK	\$200.00	\$0.00		
			\$200.00	\$0.00		
	Labour					
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
	BODY REPAIR, PANEL BEAT, STRAIGHTEN / REALIGN - ACCIDENT AREAS		\$600.00	\$200.00		
	SPRAY PAINT - REAR BUMPER, REAR FENDER LH & END PANEL		\$600.00	\$200.00		
	REMOVE & REFIT REAR EXHAUST PIPE & COMPARTMENT	NOT NECESSARY	\$180.00	\$0.00		
	ALIGN TAILLAMP, REVERSE SENSOR, CHECK HARNESS & TEST WIRING	NOT NECESSARY	\$100.00	\$0.00		
	RUST PROOFING	* CHECK	\$100.00	\$0.00		
			\$1,580.00	\$400.00		
	GRAND TOTAL		\$5,463.44	\$1,254.16		
			· ·			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,085.44 NETT)		\$1,254.16		
Report Ref No: CS/FCI24100080/Rvp3e2					

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.