

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24100082/EVP3E2  
**Date:** 13/12/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
<b>Claimant Vehicle No :</b>	SLK758Y	<b>Insured Vehicle No :</b>	SJD8388P
Date of Loss:	02/10/2024	Nature of Claim:	TP
		Claim No:	DMPC2401335H/02/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLK758Y</b>	Engine No:	2ZRR980574
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU603540658
Reg. Date:	04/01/2017 (Man. Year: 2016)	Odometer:	649596 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,296.57	1,297.75	9,998.82	88.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,392.00	2,856.00	3,536.00	55.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>17,688.57</b>	<b>4,153.75</b>	<b>13,534.82</b>	<b>76.52</b>
<b>+ GST 9.00/9.00% (S\$)</b>	<b>1,591.97</b>	<b>373.84</b>	<b>1,218.13</b>	<b>76.52</b>
<b>Nett Amount (S\$)</b>	<b>19,280.54</b>	<b>4,527.59</b>	<b>14,752.95</b>	<b>76.52</b>

INSPECTION

Date of Assignment:	03/10/2024	
Date Inspected:	04/10/2024	Inspected At: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	5.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2024)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK758Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*COVER, FR BUMPER	Repair	799.30 FL	*- FL
3	10		*PIECE, RR BUMPER	Not Necessary	58.00 FL	*- FL
4	1		*SUPPORT, FR BUMPER	Not Necessary	121.30 FL	*- FL
5	1		*FENDER SUB-ASSY, FR	Dented	1,488.90 FL	*1,488.90 FL
6	1		*PROTECTOR, FR FENDER	Not Necessary	129.90 FL	*- FL
7	1		*SEAL SUB-ASSY	Not Necessary	72.00 FL	*- FL
8	1		*SEAL, RADIATOR	Not Necessary	58.30 FL	*- FL
9	1		*LINER, FR FENDER, LH	Not Necessary	308.70 FL	*- FL
10	1		*PANEL SUB-ASSY, FR	Repair	1,996.10 FL	*- FL
11	1		*WEATHERSTRIP, FR	Not Necessary	320.90 FL	*- FL
12	1		*STRIPE, FR DOOR	Not Necessary	18.50 FL	*- FL
13	1		*STRIPE, FR DOOR	Not Necessary	60.40 FL	*- FL
14	1		*STRIPE, FR DOOR	Not Necessary	36.60 FL	*- FL
15	1		*WHEEL, DISC	Not Necessary	2,607.70 FL	*- FL
16	1		*CAP SUB-ASSY, WHEEL	Cut	293.60 FL	*293.60 FL
17	1		*UNIT, HEADLAMP	Not Necessary	4,063.00 FL	*- FL
18	1		*LAMP ASSY, FOG, LH	Not Necessary	1,449.90 FL	*- FL
19	1		*MIRROR ASSY, OUTER	Not Necessary	1,884.40 FL	*- FL
20	1		*COVER, OUTER MIRROR	Not Necessary	151.90 FL	*- FL
21	1		*EMBLEM, SIDE PANEL	Not Necessary	75.70 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,095.10	1,832.50
- List Item Discount on L Items 30.00/30.00% (\$\$)	4,798.53	534.75
Total Parts (\$\$)	11,296.57	1,297.75

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK WIRING SYSTEM	New	144.00	144.00
2	TO RESET ECU AND REPROGRAMME	New	144.00	144.00
3	CONDUCT WHEEL ALIGNMENT	New	144.00	144.00
4	REMOVE AND TRANSFER FRONT LEFT DOOR COMPARTMENT	New	576.00	0.00
5	R/I FRONT LEFT RIM	New	144.00	144.00
6	REPL ACC AFF AREA STRAIGHTEN AND PANEL BEAT ACC AFF AREA	New	2,880.00	864.00
7	RESPRAY ACC AFF AREA	New	2,360.00	1,416.00
<b>Gross Labour Cost (\$)</b>			<b>6,392.00</b>	<b>2,856.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >