



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no : 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987			S1000026 / ICECICS		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No.				
			0				
			Document Date				
			03/10/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZVW50R	AHXEBW Q2	04/01/2017	SLK0758Y	0	33623	75/DS/SLK0758Y
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU603540658		2ZRR980574	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SJD8388P ACC DATE:02/10/24 DRIVE IN:03/10/24 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				51	100.00
2	B	BP-LAB2 CHECK WIRING SYSTEM				/	144.00
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				/	144.00
4	B	BP-MECH2 CONDUCT WHEEL ALIGHTMENT				/	144.00
5	B	BP-LAB2 REMOVE AND TRANSFER FRONT LEFT DOOR COMP ARTMENT				X	576.00
6	B	BP-MECH2 R/I FRONT LEFT RIM				/	144.00
7	B	BP-LAB2 REPL ACC AFF AREA 770-70% X 1.5 STRAIGHTEN AND PANEL BEAT ACC AFF AREA				864	2880.00
8	B	BP-RES2 RESPRAY ACC AFF AREA 590-70% X 3				1416	2360.00
9	1	U52119-47962 COVER, FR BUMPER X	1.00	799.30	30.00		559.51
10	2	K52161-0K040 PIECE, RR BUMPER X	10.00	5.80	30.00		40.60
11	3	U52116-47050 SUPPORT, FR BUMPER X	1.00	121.30	30.00		84.91
12	4	U53802-47100 FENDER SUB-ASSY, FR X	1.00	1488.90	30.00		1042.23
13	5	U53828-47070 PROTECTOR, FR FENDER X	1.00	129.90	30.00		90.93
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd							
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no: 6631 1188

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

ESTIMATE

Account Details		Account No.	Customer Details	
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	M/S Grab Rentals Pte. Ltd	
		Document No. 0	3 Media Close #01-03/06 Singapore 138498	
		Document Date 03/10/2024	Work: 65703925	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZVW50R	AHXEBW Q2	04/01/2017	SLK0758Y	0	33623	75/DS/SLK0758Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU603540658	2ZRR980574	60	Ng Mei Yen	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	6	U53807-47020 SEAL SUB-ASSY, X	1.00	72.00	30.00	50.40
15	7	U53155-47010 SEAL, RADIATOR X	1.00	58.30	30.00	40.81
16	8	U53876-47110 LINER, FR FENDER, LH X	1.00	308.70	30.00	216.09
17	9	U67002-47163 PANEL SUB-ASSY, FR X R	1.00	1996.10	30.00	1397.27
18	0	U67862-47050 WEATHERSTRIP, FR X	1.00	320.90	30.00	224.63
19	1	U75976-47060 STRIPE, FR DOOR, X	1.00	18.50	30.00	12.95
20	2	U75986-47050 STRIPE, FR DOOR, X	1.00	60.40	30.00	42.28
21	3	U75966-47030 STRIPE, FR DOOR X	1.00	36.60	30.00	25.62
22	4	U42611-47450 WHEEL, DISC / cut (FR LH)	1.00	2607.70	30.00	1825.39
23	5	U42602-47181 CAP SUB-ASSY, WHEEL X	1.00	293.60	30.00	205.52
24	6	U81185-47691 UNIT, HEADLAMP X	1.00	4063.00	30.00	2844.10
25	7	U81220-47020 LAMP ASSY, FOG, LH X	1.00	1449.90	30.00	1014.93
26	8	U87940-47440 MIRROR ASSY, OUTER X	1.00	1884.40	30.00	1319.08
27	9	U87945-47060 A1 COVER, OUTER MIRROR, X	1.00	151.90	30.00	106.33
28	0	U75374-47150 EMBLEM, SIDE PANEL X	1.00	75.70	30.00	52.99

Steve (LKK)
4/10/24, 12:00pm
m ll

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			17,688.57
5 days PIP my Bo L sig	Please acknowledge receipt of vehicle	Parts 11,196.57 Labour 6,492.00 Sublet 0.00 Lubrication/Fluid 0.00 Others 0.00	GST 9.00% 1,591.97
			Less 0.00
			Amount Due 19,280.54

sterechina@lkkauto.com

Customer Copy