

(08/11/13) wef

ASS. REC. BY: MORAN

REF:

CS/MSA 24100083/UP3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHD 6370B

at Workshop m/s SMRT

of _____

Insured: XE 20535

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C 369K
Vehicle: IN / OUT

Date: _____ Person Contacted: LYA 821203

Veh No: SHD 6370B Yr Regn: 26/11/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Toyota Prius c.c. 1798

Colour: Maroon A/C: Insured / Std / NI / NA

Sp.Reading: 419150 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FUX03089377

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65-R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Goodridge

Front: _____ Rear: 6

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 02/10/24 D.O.I. 04/10/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Add Fee: ☐ : Site Insp (\$ _____) ☐ S + RS, SI

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHD6370B
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Maroon
Manufacturing Year:	2019
Engine No.:	2ZR2F42008
Chassis No.:	JTDKB3FUX03089377
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	26 Dec 2019
First Registration Date:	26 Dec 2019
Transfer Count:	0
Actual ARF Paid:	\$14,530.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Dec 2027
PARF Rebate Amount:	\$10,897.00
Intended COE Rebate Details	
COE Expiry Date:	25 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$25,581.00
COE Rebate Amount:	\$10,306.00
Total Rebate Amount:	\$21,203.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Oct 2024

OK

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Gener
User ID

*TOTAL less 202
for lump sum*
*Not Authorized
meras
4/10/24
d/s*
*5-Jays
Joseph H. Hare*

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicab
TO REPAIR RH PORTION	\$1,352.00 200	600
Total Labour	\$1,352.00	

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TO RESPRAY FRONT DOOR RH	\$378.00	17 X
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	150
TO RESPRAY VIEW MIRROR	\$220.00	17 X
TO RESPRAY RH REAR DOOR	\$378.00	200
TO RESPRAY REAR FENDER RH	\$378.00	200
TO RESPRAY REAR BUMPER	\$378.00	200
TO RESPRAY RIM	\$220.00	17 X
TO RESPRAY DOOR HANDLE	\$220.00	17 X
Total Spray Painting & Panel Beating	\$2,392.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TO WASH AND VACUUM	\$60.00	17 X
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	20
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	40
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	44 X 60
TO REMOVE AND REFIT TYRE	\$120.00	17 X
TO TRANSFER DOOR MECHANISM	\$240.00	40
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	17 X
TO REMOVE AND REFIX UNDERCARRIAGE	\$350.00	17 X
TO REPLACE SUNDRY PARTS	\$100.00	17 X
Total Other Costs	\$1,430.00	

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$525.40	30.00	\$367.78	Replace	17 X
		52462-47130	PAD, RR BUMPER, RH & LH, 3	2.00	\$12.00	30.00	\$16.80	Replace	17 X
		52462-47030	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	30.00	\$6.02	Replace	17 X
		52462-47020	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	30.00	\$6.02	Replace	17 X
		52575-47060	RETAINER, RR BUMPER, RH	1.00	\$143.60	30.00	\$100.52	Replace	17 X
		52161-16010	CLIPS PIECE, RR BUMPER	1.00	\$4.80	30.00	\$3.36	Replace	17 X
		67001-47153	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,407.80	30.00	\$985.46	Replace	17 X
			STICKER LOGO (FRT DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	17 X
		75850-47910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$649.10	30.00	\$454.37	Replace	17 X
		87910-47450	MIRROR ASSY, OUTER REAR VIEW, RH	1.00	\$1,556.00	30.00	\$1,089.20	Replace	17 X
		87915-47070-A1	COVER, OUTER MIRROR, RH	1.00	\$117.80	30.00	\$82.46	Replace	17 X
		67003-47211	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,401.70	30.00	\$981.19	Replace	17 X

58 ms167

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Genera

User ID

Section A - Accident Details

Registration Number	SHD6370B
Case Reference Number	TAX/10/24/2008
Registration Date	26/12/2019
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	WESLEY WANG YEONG CHENG
Type of Accident	Side Swipe
Accident Date and Time	2/10/2024 8:54 PM
Accident Reported Date and Time	3/10/2024 11:30 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	ACGJ24100007
Special Instruction to ARC, if any	TP
Prepared Date and Time	3/10/2024 1:05 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$0.00
Total Spray Cost	\$2,392.00	\$0.00
Total Spare Part Cost	\$5,802.62	\$0.00
Total Other Cost	\$1,430.00	\$0.00
TOTAL COST	\$10,976.62	\$0.00
Lump Sum Total	\$11,000.00	\$0.00
Number of Repair Days	10.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	03/10/2024 1:48 PM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodland
FAX Number
Estimator Te
Accident Rep

Date Genera

User ID

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
			STICKER LOGO (RR DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Re ✓
		61601-47150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	30.00	\$660.17	Replace	CM ✓
		61017-47010	MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	1.00	\$312.10	30.00	\$218.47	Replace	R X
		6556547010	PATCH, SIDE PANEL REAR END , RH & LH	1.00	\$37.70	30.00	\$26.39	Replace	11 X
		65637-47060	LINER, REAR FENDER , RH	1.00	\$151.10	30.00	\$105.77	Replace	11 X
		4261147450	WHEEL, DISC	1.00	\$2,036.30	30.00	\$1,425.41	Replace	CM 6225/Net/?
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	SW X
		42450-76020	HUB & BEARING ASSY WITH SPEED SENSOR , REAR AXLE , RH & LH	1.00	\$644.10	30.00	\$450.87	Replace	11 X
Total					\$10,197.94		\$7,227.00		

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Cf
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: