



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909 ATTN: JOEY TAY			Ref: CS/UOI24100086/Enp3e2(N) Date: 17/01/2025 Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SKS 1223L
	Policy No.		Coverage (\$)	0.00
	Claim No.	M11D00122410	Excess (\$)	600.00
	Assign From	JOEY TAY	Assign Date	03/10/2024
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. X1	c.c	1499
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	WBA32AA0005T16462	Colour	BLACK
	Odometer	52192 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50RF18	MICHELIN	6 mm
	L/H Front Tyre	225/50RF18	MICHELIN	6 mm
	R/H Rear Tyre	225/50RF18	MICHELIN	6 mm
	L/H Rear Tyre	225/50RF18	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/09/2024	Inspection Date	04/10/2024
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks				
	A)THE MARKET VALUE IS S\$143,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	