

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559H GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 71379 *P/P, Ray Bkt spy b parts* Page No. : 1 of 5
Date Estimated : 02/10/2024
Prepared By : Jack Ng Guo Ming *10 days*

- ESTIMATE REPAIR FOR -

Chua Guo Wei, Kent (Cai Guowei)
Apt Blk 80C Telok Blangah Street 31
#24-129

Singapore 103080

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS1223L	WBA32AA0005T16462	29/03/2021	X1 sDrive18i	33279

DESCRIPTION

VALUE

To replace new short engine and adjust engine timing
accordance to BMW specification.

8,496.00

To remove and install engine and auto transmission to
facilitate jacking of chassis and mounting of car on
car-o-liner including to replace damaged parts.

1,652.00

To replace auto transmission and attachments including
checks for proper function.

X 1,770.00

To send vehicle with new short engine to LTA for inspection.

191.00

LTA Application fees. (For engine or chassis
changes).

80.00

To replace rear exhaust silencer including alignment
system and conduct check for leak.

X ? 531.00

To replace front center exhaust silencer including
alignment system and conduct check for leak.

X ? 531.00

To replace RP Catalytic convertor near engine include alignent of
system and
conducting check for leak

664 / ? -631.00

To replace RMF start motor include conducting test for proper function

531 / ? -270.00

To remove radiator assembly, fan housing with fan including
pressure test, bleed cooling system and conduct check for
leak. (All models except 7 series).

To drink

826.00

To remove and install air con blower housing assembly to
facilitate the cutting of the front wheel housing.

To drink

814.00

To conducting test on trasmission for torque and horse power in
accordance with
BMW specification and check compression cylinder

Comper test

2,250.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559H GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 71379
Date Estimated : 02/10/2024
Prepared By : Jack Ng Guo Ming

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS1223L	WBA32AA0005T16462	29/03/2021	X1 sDrive18i	33279

DESCRIPTION

To tow accident vehicle to PML workshop.

To check electrical wiring system

Sundries.

Total Labour 1: 18,637.00

DESCRIPTION

QTY

PRIC

VALUE

DOWEL PIN 4X16MM / nec	1	3.30	3.30
(S/L) RP SHORT ENGINE (Complete - test prime low) - jumped	1	16,164.30	16,164.30
SHORTBLOCK X nn	1	6,774.85	6,774.85
OIL PAN X nn	1	748.85	748.85
COVER ACOUSTIC ? x nn	1	81.35	81.35
RELUCTOR ? / Nec	-3 1	61.85	185.55
CAM FOLLOWER ? / Nec	1	90.35	90.35
O RING 16X2MM - nec	2	5.85	11.70
OIL FILTER X nn	1	933.60	933.60
EXHAUST TURBOCHARGER SEAL - nec	1	17.90	17.90
RP turbochar ? x nn	1	4,280.75	4,280.75
SPARK PLUG HIGH POWER - nec	3	47.65	142.95
EXCHANGE STARTER MOTOR ? / Rusted	1	1,302.75	1,302.75
AIR FILTER ELEMENT - nec	1	98.95	98.95
CHARGE AIR COOLER ? / Rusted	1	647.85	647.85
MUFFLER CLAMP D=65.2MM ? / Nec	1	47.55	47.55
REAR SILENCER ? x nn	1	1,176.05	1,176.05
RP PETROL PARTICULATE FILTER (RDE) ? x nn	1	2,747.35	2,747.35
RP CATALYTIC CONVERTER NEAR ENGINE ? / Rusted	1	2,264.65	2,264.65
RP DOUBLE CLUTCH TRANSMISSION - nec	1	19,208.65	19,208.65
(S/L) BMW DCTF-2 (1 LITRES) - nec	4	63.90	255.60
(S/L) BMW DCTF-2 (1 LITRES) - nec	5	63.90	319.50

Total Parts : 57,504.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	18,637.00
Parts	:	57,504.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	6,852.72
Grand Total	:	82,994.07

YES ONLY**
WITHOUT PRIOR NOTICE **



** THIS E
** PRICE