

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

TP INC
Veron.

VEHICLE NO : SLH 4279 C

MAKE / MODEL : TOYOTA COROLLA

CHASSIS NO : NKE1657136810

ACCIDENT DATE : 30.09.2024

NO	DESCRIPTION	QTY	AMOUNT (\$)
LIST ITEMS			
1	Rear bumper <i>deluxe</i>	1	\$ 481.90
2	Rear bumper side holder @ \$271.10 <i>new</i>	2	\$ 542.20
3	Rear bumper clips <i>new</i>	1	\$ 36.00
4	Rear LH door <i>new</i>	1	\$ 1450
5	Rear LH door side moulding <i>new</i>	1	\$ 80.00
6	Rear LH fender <i>new</i>	1	\$ 1217.00
7	Rear LH fender lower sticker <i>new</i>	1	\$ 55.00
8	Rear LH sport rim <i>new</i>	1	\$ 650.00
9	Rear LH tyre <i>new</i>	1	\$ 380.00

1167.90

LESS 25% DISC

875.92

TOTAL

LABOUR COST

1	Remove + reinstall reverse sensor	1	\$ 150.00
2	Remove + reinstall door glass	1	\$ 100.00
3	Remove, replace + repair consistent to the accident	1	\$ 1000.00
4	Respray painting	1	\$ 1000.00

TOTAL

2250.00

GRAND TOTAL

5919.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Adm
h/s 25/10/24
03 Days

total: 1875.92

y/s: 1.5K

1.5K