

# JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #01-77 AUTOBAY@KAKI BUKIT

SINGAPORE 417883

TEL: 92327457

|               |                     |           |            |
|---------------|---------------------|-----------|------------|
| TO            | : CHINA TAIPING     | DATE      | 14/10/2024 |
| VEHICLE NO    | : SMF2335K (2018)   | Xiao Chen |            |
| VEHICLE MODEL | : KIA CERATO        |           |            |
| CHASSIS NO    | : KNAF3416MK5019486 |           |            |

| QTY                       | DESCRIPTION                                     | CONDITION           | REPAIRER'S ESTIMATE(S\$) |         | SURVEYOR ADJUSTMENT |  |
|---------------------------|-------------------------------------------------|---------------------|--------------------------|---------|---------------------|--|
| <u>PARTS (LIST ITEMS)</u> |                                                 | 1749<br><br>1574.10 | 651.00                   |         | ✓                   |  |
| 1                         | REAR BUMPER <i>Delud</i>                        |                     | 32.00                    |         | +                   |  |
| 2                         | REAR BUMPER SIDE HOLDER <i>ren</i>              |                     | 241.00                   |         | +                   |  |
| 3                         | REAR BUMPER LOWER GARNISH <i>ren</i>            |                     | 43.00                    |         | +                   |  |
| 4                         | REAR BUMPER UNDERCOVER SIDE <i>ren</i>          |                     | 675.00                   |         | +                   |  |
| 5                         | TAILLAMP <i>xtenu</i>                           |                     | 985.00                   |         | ✓                   |  |
| 6                         | REAR FENDER <i>Distorted</i>                    |                     | 145.00                   |         | +                   |  |
| 7                         | REAR FENDER INNER SHIELD                        |                     | 314.00                   |         | +                   |  |
| 8                         | REAR FENDER INNER TRIM BOARD <i>3 new</i>       |                     | 89.00                    |         | +                   |  |
| 9                         | REAR FENDER AIR VENT                            |                     | 113.00                   |         | ✓                   |  |
| 10                        | REAR WINDSCREEN MOULDING <i>new</i>             |                     |                          |         |                     |  |
|                           |                                                 | Less                | 10%                      | 3288.00 |                     |  |
|                           |                                                 |                     | 10%                      | 328.80  | 10%                 |  |
|                           |                                                 |                     |                          | 2959.20 |                     |  |
|                           |                                                 |                     |                          |         |                     |  |
| <u>SPECIAL NETT ITEMS</u> |                                                 | 750                 | 50.00                    |         | +30                 |  |
| 1                         | REAR BUMPER CLIPS <i>new</i>                    |                     | 40.00                    |         | +                   |  |
| 2                         | REAR BUMPER UNDERCOVER SIDE CLIPS <i>new</i>    |                     | 30.00                    |         | +                   |  |
| 3                         | REAR FENDER INNER SHIELD CLIPS <i>3 new</i>     |                     | 30.00                    |         | +                   |  |
| 4                         | REAR FENDER INNER TRIM BOARD CLIPS <i>3 new</i> |                     | 60.00                    |         | ✓                   |  |
| 5                         | REAR FENDER SEALANT <i>new</i>                  |                     | 680.00                   |         | 400                 |  |
| 6                         | REAR WHEEL RIM <i>ut</i>                        |                     | 250.00                   |         | 200                 |  |
| 7                         | REAR TYRE <i>Torn</i>                           |                     | 60.00                    |         | ✓                   |  |
| 8                         | REAR WINDSCREEN SEALANT <i>new</i>              |                     |                          |         |                     |  |
| Total Parts :             |                                                 |                     | 1200.00                  |         |                     |  |

| S/N           | DESCRIPTION                | REPAIRER'S ESTIMATE (S\$) | OUR ASSESSMENT (S\$) |
|---------------|----------------------------|---------------------------|----------------------|
| <u>LABOUR</u> |                            |                           |                      |
| 1             | PANEL BEATING              | 1000.00                   | 500                  |
| 2             | SPRAY PAINTING             | 800.00                    | 400                  |
| 3             | WIRING                     | 50.00                     | 30                   |
| 4             | TO APPLY TUFF COAT         | 150.00                    | 40                   |
| 5             | TO REMOVE UPHOLSTERY       | 150.00                    | 40                   |
| 6             | TO REMOVE REVERSE SENSOR   | 100.00                    | 50                   |
| 7             | TO PERFORM WHEEL ALIGNMENT | 150.00                    | 80                   |

|   |                           |                   |     |
|---|---------------------------|-------------------|-----|
| 8 | TO REMOVE REAR WINDSCREEN | <del>180.00</del> | 120 |
|   | Labour Total :            | 2580.00           |     |
|   | TOTAL (PARTS & LABOUR) :  | 6739.20           |     |

1260

total: 3584.10

L/S: 2.8K.

04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: