



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE LIMITED	Document No.	: SQT24002690	Page	1
	#42-0116 RAFFLES QUAY	Date	: 3. Oct 2024		
	HONG LEONG BUILDING	Customer No.	: WZF002		
	SINGAPORE 048581	Svc Advisor	: LEE CHEN SIN		
Registration No	: SMX3899Z	Engine No	: R16B25520549		
Chassis No	: MRHFC5650LT000433	Date Time	: 3. Oct 2024 11:15:01 AM		
Model	: CIVIC 1.6 VTI YM2020	Surveyor Name	:		
Owner's Name	: GOH JIA HENG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 2/10/2024				

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:GOH JIA HENG						
	OWNER INSURER:ECICS						
	ACC DATE:02/10/2024						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:MS FIRST CAPITAL						
	TP VEH:SHB6166K						
67050-TEA-T00ZZ	PANEL COMPL FR DOOR / M	1	949.20	25	711.90	64.07	775.97
67450-T2M-T02ZZ	HINGE,L FR DOOR UPPER	1	46.40	25	34.80	3.13	37.93
67460-T2M-T02ZZ	HINGE L FR DOOR LOWER	1	47.50	25	35.62	3.21	38.83
72340-TEA-T01	CHECKER COMPFR DOOR	1	16.40	25	12.30	1.11	13.41
72376-TEA-T01	SEALL FR DOOR FR GAP / M	1	15.10	25	11.32	1.02	12.34
72368-TEA-T01	SEALL FR DOOR LOWER / M	1	9.90	25	7.42	0.67	8.09
72465-TBA-A01	MOLDING ASSYL FR DOOR SASH (chm) / M	1	32.10	25	24.07	2.17	26.24
72496-TEA-T01	GARNISH L FR CENTER CORNER / M	1	1.90	25	1.42	0.13	1.55
72470-TEA-T01	GARNISH ASSYL FR DOOR SASH / M	1	16.50	25	12.37	1.11	13.48
72450-TEA-T01	MOLDING ASSYL FR DOOR / M	1	29.10	25	21.82	1.96	23.78
72150-TEA-T03	LATCH ASSYL FR DOOR POWER	1	111.50	25	83.62	7.53	91.15
72250-TEA-T01	REGULATOR ASSYL FR DOOR	1	109.30	25	81.97	7.38	89.35
67550-TEA-T00ZZ	PANELL RR DOOR / M	1	868.30	25	651.22	58.61	709.83
67950-T2M-T02ZZ	HINGE L R DOOR UPPER	1	46.00	25	34.50	3.11	37.61
67960-T2M-T02ZZ	HINGE L R DOOR LOWER	1	46.40	25	34.80	3.13	37.93
72840-TEA-T01	CHECKER COMPRR DOOR	1	11.40	25	8.55	0.77	9.32
72828-TEA-T01	SEALRR DOOR LOWER / M	1	7.40	25	5.55	0.50	6.05
72965-TEA-T01	MOLDING ASSYL RR DR INNER / M (chm)	1	62.00	25	46.50	4.19	50.69
72970-TEA-T01	GARNISH ASSYL RR DOOR SASH / M	1	28.30	25	21.22	1.91	23.13

Printed on 3/10/2024 11:56:07 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SMX3899Z
Chassis No : MRHFC5650LT000433
Model : CIVIC 1.6 VTI YM2020
Owner's Name : GOH JIA HENG
Ins Policy No. :
Date of Accident : 2/10/2024

Document No. : SQT24002690
Date : 3. Oct 2024
Customer No. : WZF002
Svc Advisor : LEE CHEN SIN
Engine No : R16B25520549
Date | Time : 3. Oct 2024 11:15:01 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
72761-TEA-T01	GARNISH L.RR.DOOR QUARTER OUT / <i>MC</i>	1	23.50	25	17.62	1.59	19.21
72996-TEA-T01	GARNISH L.RR.CENTER CORNER / <i>MC</i>	1	1.60	25	1.20	0.11	1.31
72950-TEA-T01	MOLDING ASSY,L.RR.DOOR / <i>MC</i>	1	30.50	25	22.87	2.06	24.93
72650-TBA-A02	LATCH ASSYL.RR.DOOR POWER / <i>MC</i>	1	194.50	25	145.87	13.13	159.00
72750-TEA-T01	REGULATOR ASSYL.RR.DOOR POWER / <i>MC</i>	1	133.00	25	99.75	8.98	108.73
71850-TEA-T51ZA	GARNISH ASSY,L.SIDE SILL / <i>BR</i>	1	142.50	25	106.87	9.62	116.49
04646-TED-305ZZ	PANEL SET,L.RR.OUTSIDE / <i>MC</i>	1	1353.90	25	1015.42	91.39	1106.81
74592-TEA-T00	FENDER L.RR.INNER X	1	102.80	25	77.10	6.94	84.04
91512-SED-003	CLIP INNER FENDER / <i>MC</i>	8	2.40	25	14.40	1.30	15.70
73227-TEA-003	RUBBER C WINDSHIELD DAM / <i>MC</i>	1	20.90	25	15.67	1.41	17.08
73525-SYY-000	RUBBERRR QTR W/SHIELD / <i>MC</i>	3	10.60	25	23.85	2.15	26.00
91501-S70-003	FASTENER BW/SHIELD / <i>MC</i>	2	5.30	25	7.95	0.72	8.67
91536-SS0-J01	FASTENER AW/SHIELD / <i>MC</i>	2	3.80	25	5.70	0.51	6.21
91568-TF0-003	CLIP,WINDSHIELD UPPER / <i>MC</i>	2	3.60	25	5.40	0.49	5.89
73125-SR3-000	RUBBER, W/SHIELD / <i>MC</i>	1	14.50	25	10.87	0.98	11.85
73126-SR3-000	RUBBER, W/SHIELD / <i>MC</i>	1	16.50	25	12.37	1.11	13.48
BO-WS-SEALANT	WINDSCREEN SEALANT (N) / <i>MC</i>	2	60.00		120.00	10.80	130.80
YHR-WM8522X1770A45X0	17 INCH GROSS BLACK FULL POLISH CIVIC RIM (SC22) / <i>MC</i> (Affixing rim)	1	320.00		320.00	28.80	348.80
Sum Item					3863.88	347.80	4,211.68
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00		650.00	58.50	708.50
BOSUN	SUNDRIES	1	100.00		100.00	9.00	109.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00		280.00	25.20	305.20
BKDR11K	TRANSFER FR L DOOR INCLUDING FITTINGS ON	1	650.00		650.00	58.50	708.50
BKDR21K	TRANSFER RR L DOOR INCLUDING FITTINGS	1	650.00		650.00	58.50	708.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00		650.00	58.50	708.50
BMI01D	REMOVE & INSTALL ROOF LINING GARNISHES SEATS	1	650.00		650.00	58.50	708.50
BMF00D	REMOVE & INSTALL FUEL TANK FUEL PIPES.(N) / <i>MC</i>	1	550.00		550.00	49.50	599.50

Printed on 3/10/2024 11:56:07 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SMX3899Z
Chassis No : MRHFC5650LT000433
Model : CIVIC 1.6 VTI YM2020
Owner's Name : GOH JIA HENG
Ins Policy No. :
Date of Accident : 2/10/2024

Document No. : SQT24002690 **Page** 3
Date : 3. Oct 2024
Customer No. : WZF002
Svc Advisor : LEE CHEN SIN
Engine No : R16B25520549
Date | Time : 3. Oct 2024 11:15:01 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
BPBODY - MINOR	REMOVE & RENEW RR L RIM INCLUDE BALANCING	1	80.00	/	80.00	7.20	87.20
BOJSE	BODY JOINT SEALANT. RR FENDER	1	80.00	/	80.00	7.20	87.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00	/	100.00	9.00	109.00
BKFE21R	CUT & RENEW RR L FENDER. STRAIGHTEN INNER PANEL 650 x 5	1	6500.00	3250	6500.00	585.00	7085.00
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P) 520 x 5	1	3640.00	2609	3640.00	327.60	3967.60
Sum Labor					14580.00	1,312.20	15,892.20
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	220.00		220.00	19.80	239.80
Sum Ext. Service					220.00	19.80	239.80

Survey By

Date & Time

Excess

Status

Signature

STEW (LKK)
7/10/24, 12.00pm
m
P/P
by BOL by
9 days

Total Amount 18,663.88 1,679.80 20,343.68

Total (Inclusive of GST) 20,343.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 3/
This is a comput
Part prices are t
The above estim
GST Amount is

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.
All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.