

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail: jlperfectautowork@gmail.com



DATE : 03.10.2024

TO	:	INDIA INTERNATIONAL	MOTOR CLAIMS DEPTS
VEHICLE NO	:	SKE6780K	
MODEL	:	TOYOTA COROLLA ALTIS	Xiao To
DATE OF ACCIDENT	:	03.10.2024	
TIME OF ACCIDENT	:	16:50 HOURS	

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS					
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	BOOTLID <i>Repr</i>	1	\$ 756.10	\$ 756.10	
2	BOOTLID LAMP LH <i>lit</i>	1	\$ 342.00	\$ 342.00	
3	BOOTLID LOGO	1	\$ 85.00	\$ 85.00	
4	BOOTLID EMBLEM 'COROLLA' <i>2 per</i>	1	\$ 70.00	\$ 70.00	
5	BOOTLID EMBLEM 'ALTIS'	1	\$ 70.00	\$ 70.00	
6	BOOT LID HINGE <i>new</i>	2	\$ 70.00	\$ 140.00	
7	BOOTLID TOP LOCK <i>2 per</i>	1	\$ 318.10	\$ 318.10	
8	BOOTLID LOWER LOCK <i>per</i>	1	\$ 20.00	\$ 20.00	
9	BOOTLID WEATHERSTRIP	1	\$ 195.00	\$ 195.00	
10	TAILLAMP <i>2 LH</i>	2	\$ 465.00	\$ 930.00	
11	TAILLAMP LOWER BARCKET <i>1 rhd</i>	2	\$ 115.10	\$ 230.20	
12	TAILLAMP PANEL LH <i>Distorted</i>	1	\$ 198.00	\$ 198.00	
13	REAR DOOR LH <i>Distorted</i>	1	\$ 1,250.00	\$ 1,250.00	
14	REAR DOOR LOCK CATCHER LH <i>2 new</i>	1	\$ 60.00	\$ 60.00	
15	REAR DOOR INNER LOCK LH <i>2nd</i>	1	\$ 480.00	\$ 480.00	
16	REAR DOOR INNER TRIM LH <i>1st new</i>	1	\$ 890.00	\$ 890.00	
17	REAR DOOR WEATHER STRIP LH <i>lit</i>	1	\$ 175.00	\$ 175.00	
18	REAR DOOR FRAME WEATHER STRIP LH <i>new</i>	1	\$ 110.00	\$ 110.00	
19	REAR DOOR OUTER MOULDING LH <i>new</i>	1	\$ 160.00	\$ 160.00	
20	REAR FENDER LH <i>Distorted</i>	1	\$ 987.00	\$ 987.00	
21	REAR FENDER INNER PANEL LH <i>Repr</i>	1	\$ 876.00	\$ 876.00	

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKE6780K**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 03.10.2024
 TIME OF ACCIDENT : 16:50 HOURS

22	REAR FENDER INNER COWLING <i>New</i>	2	\$ 350.20	\$ 700.40	+
23	REAR FENDER INNER TRIM <i>New</i>	2	\$ 770.10	\$ 1,540.20	+
24	REAR FENDER AIR VENT LH <i>Replaced</i>	1	\$ 75.00	\$ 75.00	✓
25	REAR WHEEL HOUSE PANEL LH <i>Replaced</i>	1	\$ 897.40	\$ 897.40	✓
26	REAR WHEEL HOUSE PANEL SUPPORT PANEL LH <i>Replaced</i>	1	\$ 480.00	\$ 480.00	+
27	REAR FUEL TANK INLET PIPE <i>New</i>	1	\$ 193.20	\$ 193.20	+
28	REAR FUEL TANK PIPE COVER HOLDER <i>New</i>	1	\$ 68.50	\$ 68.50	+
29	REAR FUEL TANK PIPE DOOR PANEL <i>Replaced</i>	1	\$ 156.40	\$ 156.40	+
30	REAR FUEL TANK PIPE DOOR PANEL LOCK <i>New</i>	1	\$ 96.30	\$ 96.30	+
31	REAR FUEL TANK PIPE DOOR PANEL LOCK CABLE <i>Replaced</i>	1	\$ 176.20	\$ 176.20	+
32	REAR FUEL TANK INLET PIPE COVER GARNISH <i>New</i>	1	\$ 68.50	\$ 68.50	+
33	REAR WINDSCREEN MOULDING <i>New</i>	1	\$ 163.00	\$ 163.00	✓
34	REAR WHEEL RIM LH <i>New</i>	1	\$ 985.00	\$ 985.00	500/SND
35	REAR ABS SENSOR LH <i>New</i>	1	\$ 295.00	\$ 295.00	+
36	REAR WHEEL HUP C/W BEARING LH <i>New</i>	1	\$ 810.00	\$ 810.00	+
37	REAR SHOCK ABSORBER LH <i>New</i>	1	\$ 390.00	\$ 390.00	+
38	REAR AXLE <i>New</i>	1	\$ 2,850.00	\$ 2,850.00	+
39	REAR END PANEL <i>Dented</i>	1	\$ 695.30	\$ 695.30	+
40	REAR END PANEL TOP GARNISH <i>New</i>	1	\$ 250.10	\$ 250.10	+
41	REAR FLOOR PANEL TOP BOARD <i>New</i>	1	\$ 271.10	\$ 271.10	+
42	REAR FLOOR PANEL <i>Replaced</i>	1	\$ 940.20	\$ 940.20	+
43	REAR FLOOR SIDE PANEL LH <i>Dented</i>	1	\$ 294.60	\$ 294.60	+
44	REAR BUMPER <i>Dishled</i>	1	\$ 539.90	\$ 539.90	✓
45	REAR BUMPER REINFORCEMENT <i>New</i>	1	\$ 386.60	\$ 386.60	X.
46	REAR BUMPER REFLECTOR <i>LH cracked</i>	2	\$ 75.10	\$ 150.20	75.10
47	REVERSE SENSOR (SET) <i>New</i>	1	\$ 386.20	\$ 386.20	+
48	REAR CHASSIS EXTEND MEMBER <i>New</i>	2	\$ 650.30	\$ 1,300.60	+

6927.30 S.N 500
 5155.47

TOTAL PRICE \$ 23,502.30
 LESS 25% \$ 5,875.58
SUB TOTAL PRICE \$ 17,626.73

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS (SET) New	1	\$ 50.00	\$ 50.00
2	BOOT LID INSULATOR CLIP (SET) New	1	\$ 80.00	\$ 80.00

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKE6780K**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 03.10.2024
 TIME OF ACCIDENT : 16:50 HOURS

3	TAILLAMP CLIPS (SET) <i>3 per</i>	1	\$ 30.00	\$ 30.00	+
4	TAILLAMP PANEL SEALANT	1	\$ 120.00	\$ 60.00	30
5	REAR FENDER SEALANT <i>new</i>	1	\$ 280.00	\$ 150.00	60
6	REAR FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
7	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
8	REAR WHEEL HOUSE PANEL SEALANT <i>new</i>	1	\$ 180.00	\$ 180.00	+
9	REAR WINDSCREEN SEALANT <i>3 per</i>	1	\$ 80.00	\$ 80.00	40
10	REAR WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	30
11	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
12	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
13	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 350.00	\$ 350.00	+
14	REAR DOOR SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
15	REAR TYRE LH <i>new</i>	1	\$ 350.00	\$ 350.00	+
16	BRAKE OIL <i>new</i>	1	\$ 80.00	\$ 80.00	+
			TOTAL	\$ 1,910.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	1400
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	1200
3	TUFF COAT	\$ 250.00	100
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	+
8	REAR CHASSIS ALIGNMENT	\$ 250.00	+

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKE6780K**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 03.10.2024
 TIME OF ACCIDENT : 16:50 HOURS

9	TRANSFER BOOTLID MECHANISM	\$	80.00	+
10	CONDUCT WATER LEAKAGE TEST	\$	100.00	+
11	TRANSFER REAR DOOR MECHANISM	\$	180.00	60
12	REMOVE AND REFIX REAR WINDSCREEN	\$	120.00	✓
13	REMOVE AND REFIX FUEL TANK TO FACILITATE REAR FENDER REPLACEMENT	\$	80.00	60
14	REMOVE AND REFIX REAR UNDERCARRIAGE	\$	650.00	+
15	FOUR WHEEL ALIGNMENT	\$	120.00	80
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$	280.00	+

TOTAL \$ 7,000.00

TOTAL PARTS COST : \$ 19,536.73
 TOTAL LABOUR COST : \$ 7,000.00
 TOTAL REPAIR COST : \$ 26,536.73

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP:8297 9787

Adrian S
 2/5 02/10/24.
 13 Days.
 3160

total: 9105.47
 L/S: 7K (Nett Value)

