

REF:

ASSIGNMENT

Front: _____ Date: _____
 Est: _____
 OD / TPRS / TP RES / OD RES / EVA / INV / MV
 To in _____ Vehicle No: _____
 at W _____
 of _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____

Veh No: SKE6780k Yr Regn: 2015, Sept.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis. CC: 1598
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 276279 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: MROS3REH1045385C3.

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SR / STD A/Rim or

Tyre Size: F: 205/55R16.
 R: 205/55R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kapsen

Front

R/Bal. 06 mmL/Bal. 06 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rees N/S.
 The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

TP III

COE Expiry: _____

Estimate given during: Yes (✓)

1st Survey: No ()

MV: 22KPV: 14.3KNett: 7.7K5412.

Date/Time, File Pass to?



: Preli. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

Report Format: _____

Report Form: _____

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 03.10.2024

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKE6780K**
MODEL : **TOYOTA COROLLA ALTIS**
DATE OF ACCIDENT : 03.10.2024
TIME OF ACCIDENT : 16:50 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Repair</i>	1	\$ 756.10	\$ 756.10
2	BOOTLID LAMP LH <i>lit</i>	1	\$ 342.00	\$ 342.00
3	BOOTLID LOGO	1	\$ 85.00	\$ 85.00
4	BOOTLID EMBLEM 'COROLLA' <i>2 for</i>	1	\$ 70.00	\$ 70.00
5	BOOTLID EMBLEM 'ALTIS'	1	\$ 70.00	\$ 70.00
6	BOOT LID HINGE <i>new</i>	2	\$ 70.00	\$ 140.00
7	BOOTLID TOP LOCK <i>for</i>	1	\$ 318.10	\$ 318.10
8	BOOTLID LOWER LOCK <i>for</i>	1	\$ 20.00	\$ 20.00
9	BOOTLID WEATHERSTRIP	1	\$ 195.00	\$ 195.00
10	TAILLAMP <i>6 LH</i>	2	\$ 465.00	\$ 930.00
11	TAILLAMP LOWER BARCKET <i>1 LH</i>	2	\$ 115.10	\$ 230.20
12	TAILLAMP PANEL LH <i>Dented</i>	1	\$ 198.00	\$ 198.00
13	REAR DOOR LH <i>Dented</i>	1	\$ 1,250.00	\$ 1,250.00
14	REAR DOOR LOCK CATCHER LH <i>new</i>	1	\$ 60.00	\$ 60.00
15	REAR DOOR INNER LOCK LH <i>2nd</i>	1	\$ 480.00	\$ 480.00
16	REAR DOOR INNER TRIM LH <i>for new</i>	1	\$ 890.00	\$ 890.00
17	REAR DOOR WEATHER STRIP LH <i>lit</i>	1	\$ 175.00	\$ 175.00
18	REAR DOOR FRAME WEATHER STRIP LH <i>new</i>	1	\$ 110.00	\$ 110.00
19	REAR DOOR OUTER MOULDING LH <i>new</i>	1	\$ 160.00	\$ 160.00
20	REAR FENDER LH <i>Distorted</i>	1	\$ 987.00	\$ 987.00
21	REAR FENDER INNER PANEL LH <i>Repair</i>	1	\$ 876.00	\$ 876.00

TO
VEHICLE NO
MODEL
DATE OF ACCIDENT
TIME OF ACCIDENT

: INDIA INTERNATIONAL MOTOR CLAIMS DEPTS
: SKE6780K
: TOYOTA COROLLA ALTIS
: 03.10.2024
: 16:50 HOURS

22	REAR FENDER INNER COWLING <i>new</i>	2	\$ 350.20	\$ 700.40	+
23	REAR FENDER INNER TRIM <i>new</i>	2	\$ 770.10	\$ 1,540.20	+
24	REAR FENDER AIR VENT LH <i>Replaced</i>	1	\$ 75.00	\$ 75.00	✓
25	REAR WHEEL HOUSE PANEL LH <i>Bushed</i>	1	\$ 897.40	\$ 897.40	-
26	REAR WHEEL HOUSE PANEL SUPPORT PANEL LH <i>Replaced</i>	1	\$ 480.00	\$ 480.00	+
27	REAR FUEL TANK INLET PIPE <i>new</i>	1	\$ 193.20	\$ 193.20	+
28	REAR FUEL TANK PIPE COVER HOLDER <i>new</i>	1	\$ 68.50	\$ 68.50	+
29	REAR FUEL TANK PIPE DOOR PANEL <i>Replaced</i>	1	\$ 156.40	\$ 156.40	+
30	REAR FUEL TANK PIPE DOOR PANEL LOCK <i>new</i>	1	\$ 96.30	\$ 96.30	+
31	REAR FUEL TANK PIPE DOOR PANEL LOCK CABLE <i>new</i>	1	\$ 176.20	\$ 176.20	+
32	REAR FUEL TANK INLET PIPE COVER GARNISH <i>new</i>	1	\$ 68.50	\$ 68.50	+
33	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 163.00	\$ 163.00	✓
34	REAR WHEEL RIM LH <i>new</i>	1	\$ 985.00	\$ 985.00	400/sms
35	REAR ABS SENSOR LH <i>new</i>	1	\$ 295.00	\$ 295.00	+
36	REAR WHEEL HUP C/W BEARING LH	1	\$ 810.00	\$ 810.00	+
37	REAR SHOCK ABSORBER LH <i>Not in</i>	1	\$ 390.00	\$ 390.00	+
38	REAR AXLE	1	\$ 2,850.00	\$ 2,850.00	+
39	REAR END PANEL <i>Dented</i>	1	\$ 695.30	\$ 695.30	+
40	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 250.10	\$ 250.10	+
41	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 271.10	\$ 271.10	+
42	REAR FLOOR PANEL <i>Replaced</i>	1	\$ 940.20	\$ 940.20	+
43	REAR FLOOR SIDE PANEL LH <i>Dented</i>	1	\$ 294.60	\$ 294.60	+
44	REAR BUMPER <i>Dishled</i>	1	\$ 539.90	\$ 539.90	✓
45	REAR BUMPER REINFORCEMENT <i>new</i>	1	\$ 386.60	\$ 386.60	+
46	REAR BUMPER REFLECTOR <i>LH cracked</i>	2	\$ 75.10	\$ 150.20	75.10
47	REVERSE SENSOR (SET) <i>new</i>	1	\$ 386.20	\$ 386.20	+
48	REAR CHASSIS EXTEND MEMBER <i>new</i>	2	\$ 650.30	\$ 1,300.60	+

TOTAL PRICE \$ 23,502.30
LESS 25% \$ 5,875.58
SUB TOTAL PRICE \$ 17,626.73

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
2	BOOT LID INSULATOR CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00

TO
VEHICLE NO
MODEL
DATE OF ACCIDENT
TIME OF ACCIDENT

: **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
: **SKE6780K**
: **TOYOTA COROLLA ALTIS**
: 03.10.2024
: 16:50 HOURS

3	TAILLAMP CLIPS (SET) <i>320</i>	1	\$ 30.00	\$ 30.00	+
4	TAILLAMP PANEL SEALANT	1	\$ 120.00	\$ 60.00	30
5	REAR FENDER SEALANT <i>new</i>	1	\$ 280.00	\$ 150.00	60
6	REAR FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
7	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
8	REAR WHEEL HOUSE PANEL SEALANT <i>new</i>	1	\$ 180.00	\$ 180.00	+
9	REAR WINDSCREEN SEALANT <i>320</i>	1	\$ 80.00	\$ 80.00	40
10	REAR WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	30
11	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
12	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
13	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 350.00	\$ 350.00	+
14	REAR DOOR SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
15	REAR TYRE LH <i>new</i>	1	\$ 350.00	\$ 350.00	+
16	BRAKE OIL <i>new</i>	1	\$ 80.00	\$ 80.00	+
TOTAL				\$ 1,910.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	1400
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	1200
3	TUFF COAT	\$ 250.00	100
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	+
8	REAR CHASSIS ALIGNMENT	\$ 250.00	+

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKE6780K**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 03.10.2024
 TIME OF ACCIDENT : 16:50 HOURS

9	TRANSFER BOOTLID MECHANISM	\$ 80.00	+
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	+
11	TRANSFER REAR DOOR MECHANISM	\$ 180.00	60
12	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	✓
13	REMOVE AND REFIX FUEL TANK TO FACILITATE REAR FENDER REPLACEMENT	\$ 80.00	60
14	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	?
15	FOUR WHEEL ALIGNMENT	\$ 120.00	80
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	+

TOTAL \$ 7,000.00

TOTAL PARTS COST : \$ 19,536.73
 TOTAL LABOUR COST : \$ 7,000.00
 TOTAL REPAIR COST : \$ 26,536.73

Adrian S
2/5 02/10/24
13 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP:8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer