

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : LIM TEE YEOW
BLK 568 CHOA CHU KANG STREET 52

SINGAPORE 680568

Claim No: MC1904601
No: MF1904461
Date: 11 Sept 2025
Policy No: V5017936
Veh Reg No: SJJ2078S
Make/Model: HONDA CIVIC 2.0L A
Chassis No: JHMFD26408S201998
TP Ins Co: INDIA

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 01/10/2024
TP Veh Reg No: SNF6390L

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SJJ2078S

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 REAR BOOT EMBLEM	1 PC	22.70	
2 REAR BOOT CIVIC LOGO	1 PC	32.10	
3 REAR BOOT I-VTEC LOGO	1 PC	34.70	
4 REAR BOOT 2.0 LOGO	1 PC	32.40	
5 REAR BUMPER	1 PC	730.10	
6 REAR BUMPER CLIP	15 PC	52.50	
		904.50	904.50
LABOUR			
7 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	50.00	
8 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR REAR BOOT & INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	200.00	
9 TO SPRAY REAR BOOT, REAR BUMPER	1 PC	350.00	
		600.00	600.00
Total			S\$ 1,504.50
Lump Sum Less 20%			-300.90
Sub Total			S\$ 1,203.60
Less Rounding			-3.60
Lum Sum Repair			S\$ 1,200.00
Add GST @ 9%			108.00
Total Amount Payable			S\$ 1,308.00

TOTAL: SINGAPORE DOLLAR ONE THOUSAND THREE HUNDRED AND EIGHT ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 07/10/2024

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LIM TEE YEOW
BLK 568 CHOA CHU KANG STREET 52
SINGAPORE 680568

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 01/10/2024
TP Veh Reg No: SNF6390L

SURVEYOR COPY
Estimate No: MC1904601
Date: 02 Oct 2024
Policy No: V5017936
Veh Reg No: SJJ2078S
Make/Model: HONDA CIVIC 2.0L A

*Not Authorised 3 day
11/10/24
Return After Paint*

Estimate Repair Cost to Vehicle No :SJJ2078S


Description	Quantity	List Price S\$	Amount S\$
QUOTE IN NETT PRICE			
SPARE PARTS			
1 REAR BOOT EMBLEM	1 PC	22.70	✓
2 REAR BOOT CIVIC LOGO	1 PC	32.10	✓
3 REAR BOOT I-VTEC LOGO	1 PC	34.70	✓
4 REAR BOOT 2.0 LOGO	1 PC	32.40	✓
5 REAR BUMPER	1 PC	730.10	✓
6 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	49.20	X
7 REAR BUMPER CLIP	15 PC	52.50	✓
		953.70	953.70
Special Nett			
8 REVERSE SENSOR	2 PC	200.00	X
		200.00	200.00
LABOUR			
9 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	X
10 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	501
11 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR REAR BOOT & INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	200
12 TO SPRAY REAR BOOT, REAR BUMPER	1 PC	500.00	3501
		1,000.00	1,000.00
Total			S\$ 2,153.70

Add GST @ 9% 193.83
Total Amount Payable S\$ 2,347.53

TOTAL: SINGAPORE DOLLAR TWO THOUSAND THREE HUNDRED FORTY SEVEN AND CENTS FIFTY THREE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



03-12-24
B Seong