

Veh No: GBK535C Yr Regn: 2020 / August

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Toyota Hiace C.D. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 156784 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTFHT02P000250687

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185R15C
R: 185R15C.

Remarks: <u>Vehicle had commenced its repair at the time of inspection.</u>	N/S	O/S
Bal. or Market Value: _____		
IDAC Accident Report _____	Consistent? : Yes or No	
GIA / PR Seen: _____	Consistent? : Yes or No	
Est. Repairs: _____ days	Res.: Yes or No	
Lum Sum: _____ %	3 Val.: Yes or No	
CA / REV / REP. / 24 HRS		
Date: _____	Person Contacted: _____	
		Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Kapsen.

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 02/10/24.

*Survey held at Success United

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP AIG
	COE Expiry : J
	Estimate given during : Yes (✓) 1st Survey : No ()
	MV :
	PV :
	Nett :

Date/Time, File Pass to? ☐ : Preli. Report
 1) ☐ : Final Report
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Report Format: _____

Additional Fee: ☐ : Site Insp. (\$) _____
☐ : Interview (\$) _____
☐ : Tech. Invt. (\$) _____

Survey Fee: _____
 Transportation: _____
 Photos _____
 Others _____

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub. Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attention : Motor Claim Department
Contact : 64191053 Fax No. : 68357416

Estimate : TP24-124

Date : 02/10/2024
Vehicle Num. : GBK5315C
Make/Model : Toyota Hiace-2020
Chassis/Eng# : JTFHT02P000250687/1KDB046914
Accident Date : 17/09/2024
Claim No. :
Reference :
Policy No. : SP2032024870

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
To repair and respray painting on frt bumper,
frt door LH, side sliding door, rear fender LH
and rear bumper.

1200
4,800.00

Labour Total S\$:

1,800.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adm LG
P/P 02/10/24.
03 Days.

Total S\$: 1,800.00
=====


SUCCESS UNITED PTE LTD