

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub, Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attention : Motor Claim Department
Contact : 64191053 Fax No. : 68357416

Estimate : TP24-124

Date : 02/10/2024
Vehicle Num. : GBK5315C
Make/Model : Toyota Hiace-2020
Chassis/Eng# : JTFHT02P000250687/1KDB046914
Accident Date : 17/09/2024
Claim No. :
Reference :
Policy No. : SP2032024870

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
To repair and respray painting on frt bumper,
frt door LH, side sliding door, rear fender LH
and rear bumper.

Labour Total S\$:

~~4,800.00~~

1,800.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adm LG
P/P 02/10/24.
03 Days.
Total: 12w
CP/P)

Total S\$: 1,800.00
=====


SUCCESS UNITED PTE LTD