

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100093/AMA3Q2**Date:** 30/07/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7220151113
Claimant Vehicle No : SMA1683M **Insured Vehicle No :** GBJ4310C
 Date of Loss: 03/10/2024 Nature of Claim: TP Claim No: 7945426733SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA1683M**
 Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 2NR5217825
 Reg. Date: 30/05/2018 (Man. Year: 2018) Chassis No: MR2B23F3101121547
 Colour: Silver Odometer: 182366 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,090.11	5,177.89	1,912.22	26.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,290.00	1,410.00	880.00	38.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,380.11	6,587.89	2,792.22	29.77
Approved Total (Overridden) (S\$)		5,250.00		
(S\$)	9,380.11	5,250.00	4,130.11	44.03
+ GST 9.00/9.00% (S\$)	844.21	472.50	371.71	44.03
Nett Amount (S\$)	10,224.32	5,722.50	4,501.82	44.03
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		6,424.68		
Global Sum Settlement (S\$)		6,400.00		

INSPECTION

Date of Assignment: 07/10/2024
 Date Inspected: 07/10/2024 Inspected At: Kang Car Repairers Pte Ltd (HQ)
 No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,327.95 FL	*1,327.95 FL
2	2		*BOOT LID HINGE	Not Necessary	182.40 FL	*- FL
3	1		*BOOT LID LOGO	Necessary	66.90 FL	*66.90 FL
4	1		*BOOT LID VIOS EMBLEM	Necessary	49.40 FL	*49.40 FL
5	1		*BOOT LID E EMBLEM	Necessary	38.40 FL	*38.40 FL
6	1		*BOOT LID LOCK	Damaged	432.50 FL	*360.00 FL
7	1		*BOOT LID LOCK CHECKER	Not Necessary	39.40 FL	*- FL
8	1		*BOOT LID TRIM	Not Necessary	352.00 FL	*- FL
9	1		*BOOT LID RUBBER	Cut	190.10 FL	*190.10 FL
10	1		*BOOT LID LAMP LH	Cracked	466.90 FL	*466.90 FL
11	1		*BOOT LID LAMP RH	Cracked	466.90 FL	*466.90 FL
12	1		*TAIL LAMP LH	Cracked	687.90 FL	*450.00 FL
13	1		*TAIL LAMP RH	Cracked	687.90 FL	*450.00 FL
14	1		*REAR BUMPER	Deformed	670.90 FL	*670.90 FL
15	1		*REAR BUMPER REINFORCEMENT	Dented	360.10 FL	*360.10 FL
16	2		*REAR BUMPER SIDE RETAINER	Not Necessary	335.80 FL	*- FL
17	2		*REAR BUMPER RETAINER (SMALL)	Not Necessary	130.20 FL	*- FL
18	1		*REAR BUMPER REFLECTOR LH	Cracked	191.80 FL	*191.80 FL
19	1		*REAR BUMPER REFLECTOR RH	Not Necessary	191.80 FL	*- FL
20	1		*REAR PANEL	Dented	803.20 FL	*803.20 FL
21	1		*REAR PANEL TRIM	Deformed	301.50 FL	*301.50 FL
22	1		*REAR FENDER TRIM LH	Not Necessary	356.40 FL	*- FL
23	1		*REAR ANTENNA SENSOR	Cracked	169.80 FL	*169.80 FL
24	1		*BOOT LID NUMBER 610 STICKER	Necessary	35.00 FS	*35.00 FS
25	1		*SET BOOTLID TRIM CLIPS	Not Necessary	40.00 FS	*- FS
26	2		*L PLATE BRACKET	Necessary	70.00 FS	*50.00 FS
27	1		*SET REAR BUMPER STICKER	Necessary	280.00 FS	*220.00 FS
28	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*80.00 FS
29	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
30	1		*SET REAR PANEL TRIM CLIPS	Necessary	40.00 FS	*20.00 FS
31	1		*SET REAR FENDER TRIM CLIPS LH	Not Necessary	60.00 FS	*- FS
32	1		*SET REAR FENDER TRIM CLIPS RH	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,215.15	6,768.85
- List Item Discount on L Items 25.00/25.00% (\$)	2,125.04	1,590.96
Total Parts (\$)	7,090.11	5,177.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REPLACE STICKERS	New	80.00	0.00
3	TO REMOVE AND REFIT REAR INNER TRIM	New	100.00	40.00
4	TO SPRAY ANTI RUST	New	60.00	40.00
5	(REAR) TO SPRAY PAINTING	New	1,000.00	600.00
6	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING /WELDING WORKS	New	1,000.00	700.00
Gross Labour Cost (\$\$)			2,290.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >