

(08/11/13) wef

REF:

CD / AIG 24100096 / Umo3

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SM L 62616at Workshop m/s Super Eel

of _____

Insured: SMF 590C

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: £ 6516.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

039f
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SM L 62616 Yr Regn: 18/12/09Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or (A)Make: Mazda MX-5 c.c. 1999Colour: Ref A/C: Insured / Std / NI / NASp. Reading: 169613 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMONC 30 F 2A 020566Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or affectedBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225 / 40 ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 03/10/24

Survey held at _____

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 4/10/24Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orO/S Ref, O/S body &The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep 136.

have video of folder renewed 31-10-2029 LTA 19013

als front hit on RH side barb have Tony 6.11

17/10/24 L/s & 8000 informed Christine

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I.: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

SUPER-ZEE MOTOR SERVICE

BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195 TEL: 6383 1913 FAX: 6383 9565
EMAIL: superzeemotor@gmail.com

4 Oct 2024

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #09-16
AIG Building
Singapore 079120

not Authorized
for
money
4/10/24
L/C #8000
Whph/Akary
6 days

THIRD PARTY CLAIM

OWNER NAME : LIU WEIJIE
VEHICLE REG NO : SML6261G
DATE OF ACCIDENT : 3 OCT 2024
PLACE OF ACCIDENT : ALEXANDRA ROAD/QUEENSWAY ROAD
INVOLVING VEH NO : SMF590C

We append herewith our estimate for Vehicle SML6261G as follows:

Materials Required

1 pc	Front Bumper	cur/10m	1558.00	S\$1,721.90	✓
1 pc	Front Bumper Retainer RH	na		S\$ 124.80	X
1 set 10 pcs	Front Bumper Clips	na		S\$ 65.00	305/N
1 pc	Front Fender RH	DO Bump		S\$ 587.20	✓
1 pc	Front Door RH	R		S\$1,310.10	X
1 pc	Front Door Outer Handle RH	cur		S\$ 285.50	✓
1 pc	Front Door Side Mirror RH	Che		S\$ 526.60	✓
1 pc	Rear Fender RH	R		S\$1,005.20	X
1 pc	Front Cross Member	but/twi	2164.00	S\$2,165.80	✓
1 pc	Front lower Arm RH	but/twi		S\$ 614.30	✓
1 pc	Front Lower Arm LH	but/twi	614.30	S\$ 753.10	✓
1 pc	Front Knuckle Arm LH	but	534	S\$ 651.20	✓
1 pc	Front Knuckle Arm Bearing LH	Dange	650	S\$ 898.60	✓
1 pc	Front Tie Rod LH	su		S\$ 269.30	X
1 pc	Front Rack End LH	na		S\$ 377.60	X
1 pc	Rear Knuckle Arm LH	na		S\$1,610.20	X
1 pc	Rear Knuckle Arm Bearing LH	na		S\$ 413.50	X
2 pcs	Front Tyre Rims RH/LH	cur/but		S\$1,900.00SN	1200 S/N
2 pcs	Front Tyre RH/LH	n/s cut	42280	S\$ 750.00SN	502 12C 140S/N
2 pcs	Rear Tyre Rims RH/LH	cur		S\$1,900.00SN	1PC 600 S/N
				S\$17,929.90	

202

SUPER-ZEE MOTOR SERVICE

BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195 TEL: 6383 1913 FAX: 6383 9565
EMAIL: superzeemotor@gmail.com

SML6261G

Page 2

Labour Charges

Towing Charge

To dismantle & replace damaged body parts and panelbeating

To dismantle & replace undercarriage parts

To putty, apply primer & spraypaint affected portion

To apply rustproofing on repaired, replaced panel

To check electrical wiring functions

Computerised Wheel Alignment

SS 100.00	✓
SS 950.00	580
SS 550.00	300
SS 1,200.00	880
SS 200.00	30
SS 80.00	20
SS 120.00	100

SS21,129.90

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUPER-ZEE MOTOR SERVICE

P-7533.90
202
P-6027.12
S.N 1970
L-2010
10007.12
Roo!

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 039F

Vehicle Details

Vehicle No.: SML6261G
Vehicle to be Exported: No
Intended Deregistration Date: 05 Oct 2024
Vehicle Make: MAZDA
Vehicle Model: MX5 2L AT RHT
Primary Colour: Red
Manufacturing Year: 2009
Engine No.: LF10882156
Chassis No.: JM0NC30F2A0201566
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$37,680.00
Original Registration Date: 18 Dec 2009
First Registration Date: 18 Dec 2009
Transfer Count: 7
Actual ARF Paid: \$37,680.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Oct 2029
COE Category: E - Open Category
COE Period(Years): 10
PQP Paid: \$37,502.00
COE Rebate Amount: \$19,013.00
Total Rebate Amount: \$19,013.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 05 Oct 2024

OK



Home Used Cars Listing

All Category

Filter

Search

Save Search



> 10 year(s) old X

8 Vehicles

Car Make


Car Model

Price Range

Depreciation

> 10 year(s) o...

Mileage



Mazda MX-5 Roadster 1.6M
(COE till 03/2029)

\$80,000

\$17,830 /yr

Instl. \$1,326

/mth

300,000 km

19-Oct-1991
(4yrs 5mths COE left)

1,597 cc 8 More than 6

For sale, immerse yourself in the timeless charm of this 1991 orange Miata MX-5 convertible. This classic beauty not only boasts a vibrant orange exterior that turns heads, but it also offers the joy of open top driving. With its sleek design, nimble handling, and a well maintained interior, this Miata promises a thrilling and stylish ride through the streets. Don't miss the chance to own a piece.



Compare

Posted 01-Oct-2024



Mazda MX-5 2.0A Roadster
(COE till 11/2027)

\$46,800

\$14,840 /yr

Instl. \$1,132

/mth

1,998 cc 8 More than 6

01-Feb-2008
(3yrs 1mth COE left)

N.A

Family 2nd car! Well kept and maintained by owner, genuine mileage done, comes with new 6 months road tax. Wear and tears replaced. Contact us For \$0 driveaway, flexible loan, full loan and trade in available. Viewing by appointment only.

Posted 20-Sep-2024

Compare



PREMIUM AD

Mazda MX-5 2.0A Roadster
(COE till 01/2029)

\$63,800

\$14,920 /yr

Instl. \$1,095

/mth

128,000 km

14-Jan-2009
(4yrs 3mths COE left)

1,998 cc 8 4 Owners

Family 2nd car! Well kept and maintained by owner, genuine low mileage done, comes with new 6 months road tax. Full cooling system replaced. For \$0 driveaway, flexible loan, full loan and trade in available. Viewing by appointment only.

Posted 19-Sep-2024

Compare

CONSIGNMENT

Compare

CASH SALE/WORK ORDER

YS TOWING PTE LTD

BLK 4015 ANG MO KIO INDUSTRIAL PARK A #01-502, SINGAPORE 569631

TEL: 6788 2233 / 6458 8480 FAX: 6288 8480

Company Registration No. 201628973E

24 hours Hotline : 9765 2992

No 3448

Date, 03/10/20

寶號

Messrs: Cash

車號

Vehicle No:

SML 62616

車型

Model No:

MAZDA

由

From:

Queenway

到

To:

W/S Dofu

時間(日/夜)

Time (day/night):

其他

Others:

CASH \$:

1000

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed, ERP Fees, Car park fees, Cancellation of job and other miscellaneous charges incurred whilst performing the services shall be borne by the customer.

經手人

Authorised by:



收貨人

Received by:

ARROW TYRES PTE LTD
50 SERANGOON NORTH AVE 4
#01-16 FIRST CENTRE BUILDING
SINGAPORE 555856
TEL : 65708087
FAX : 65708086

Work Order: R018116
 Date 16.10.24 12:22

Mazda : MX-5 : 2008-15 (NC) #200001- : with 17" Wheel
 4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-2°01'	-2°06'	
6°35'	6°35'	
0°05'	0°26'	-0°07' 0°16'
16°52'	16°56'	
14°51'	14°51'	

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-2°01'	-1°55'	
7°03'	7°03'	
0°04'	0°43'	-0°07' 0°16'
10°52'	10°47'	
8°51'	8°51'	

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°00'	-0°10'	-1°00' 1°00'
-0°29'	-0°29'	-1°00' 1°00'
6°00'	6°10'	
0°09'	1°09'	-0°13' 0°31'

Rear : Left

Actual	Before	Specified Range
-2°40'	-4°11'	
0°10'	1°11'	-0°03' 0°20'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-2°41'	-3°19'	
0°11'	0°57'	-0°03' 0°20'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°01'	-0°52'	-1°00' 1°00'
0°21'	2°08'	-0°05' 0°39'
0°00'	0°07'	

ARROW TYRES PTE LTD
50 SERANGOON NORTH AVE 4
#01-16 FIRST CENTRE BUILDING
SINGAPORE 555856
TEL : 65708087
FAX : 65708086

Work Order: R018044
 Date 7.10.24 12:15

Mazda : MX-5 : 2008-15 (NC) #200001- : with 17" Wheel
 4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-2°26'	-2°26'	
5°44'	5°44'	
-1°54'	-1°54'	-0°07' 0°16'
16°49'	16°49'	
14°23'	14°23'	

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°25'	0°24'	
8°44'	8°44'	
-2°04'	-2°05'	-0°07' 0°16'
4°31'	4°32'	
4°56'	4°56'	

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-2°51'	-2°51'	-1°00' 1°00'
-3°00'	-3°00'	-1°00' 1°00'
12°18'	12°17'	
-3°58'	-3°58'	-0°13' 0°31'

Rear : Left

Actual	Before	Specified Range
-3°49'	-3°47'	
1°14'	1°14'	-0°03' 0°20'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-3°43'	-3°43'	
0°54'	0°55'	-0°03' 0°20'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-0°05'	-0°04'	-1°00' 1°00'
2°09'	2°09'	-0°05' 0°39'
0°10'	0°10'	