

摩多廠 GUAN MOTOR WORKS

Business Regn. No: 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE GBJ9042T

NOT Authorized
C1 Ring & 3450h
Permy After Pain
4 days

No.	Qty	Nett Items	
1	1	Rear bumper	\$ 595.20 ✓
2	2	Rear bumper side retainer	\$ 140.80 x
3	2	Rear bumper reflector	\$ 191.60 x
4	1 set	Rear bumper clips	\$ 50.00 ✓
5	1	Rear bumper inner foam	\$ 124.70 ✓
6	1	Rear LH tailgate	\$ 1,967.80 ✓
7	1	Rear LH tailgate outer handle	\$ 351.50 ✓
8	1	Rear LH tailgate "NISSAN" LOGO	\$ 52.50 ✓
9	1	Rear LH tailgate "NV 200" emblem	\$ 86.40 ✓
10	1	Rear LH tailgate lower lock	\$ 166.10 x
11	1	Rear LH tailgate top lock	\$ 186.10 x
12	1	Rear RH tailgate	\$ 1,753.70 x
13	1	Rear RH tailgate rubber	\$ 351.50 x
14	1	Rear RH tailgate lower lock	\$ 166.10 x
15	1	Rear RH tailgate top lock	\$ 186.10 x
16	1 set	Rear tailgate inner trim board clips	\$ 80.00 ✓
17	1	Rear tailgate weatherstrip	\$ 79.10 x
18	1	Rear end panel	\$ 385.00 x
			\$ 6,914.20
			Less 10% \$ 691.42
			Total : \$ 6,222.78

Special Nett Items			
19	1	Rear LH tailgate "70km/h" sticker	\$ 15.00 ✓
20	1	Rear RH tailgate "6pax" sticker	\$ 15.00 ✓
21	1	Rear number plate	\$ 50.00 x
22	1 set	Reverse sensors	\$ 280.00 2005m
23	1 set	Rear end panel sealant	\$ 60.00 x
24	2 set	Rear windscreen sealant	\$ 100.00 405m
			Total : \$ 520.00

LKK Auto Consultants notice to the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$ 1,000.00 500d
2	To putty and spray Spray Paintings charges.	\$ 1,200.00 400d
3	To remove, refit both rear tailgate windscreen glass.	\$ 240.00 80d
4	To check wirings and lightings.	\$ 40.00 15d
5	To remove, transfer both tailgate fittings.	\$ 120.00 60d
6	To replace reverse sensors.	\$ 80.00 50d
7	To apply anti rust treatment	\$ 100.00 30d
		Total : \$ 2,780.00

Total Parts and Labour : \$ 9,522.78