

# FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

MS FIRST CAPITAL INSURANCE LIMITED  
16 RAFFLES QUAY  
#42-01 HONG LEONG BUILDING 048581

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 62223547

Estimate : ES709656

Date : 03/10/2024

Vehicle Num. : SMT2963Z

Make/Model : MAZDA 3

Chassis/Eng# : JM6BM42A8G0324493

Accident Date : 01/10/2024

Claim No. :

Reference :

Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|              |      |                                     |           |                     |
|--------------|------|-------------------------------------|-----------|---------------------|
| LIST ITEMS : |      |                                     |           |                     |
| 1.           | 1PC  | O/S FRONT DOOR                      | 20/304 ✓  | 1,098.50 1,489.00 ✓ |
| 2.           | 1PC  | O/S FRONT DOOR BLACK STICKER        | per ✓     | 60 75.00 ✓          |
| 3.           | 1PC  | O/S FRONT DOOR HINGE - TOP          | Bent ✓    | 125.00 ✓            |
| 4.           | 1PC  | O/S FRONT DOOR HINGE - LOWER        | Bent ✓    | 125.00 ✓            |
| 5.           | 1PC  | O/S FRONT DOOR CHECKER              | 701 ✓     | 145.00 ✓            |
| 6.           | 1PC  | O/S FRONT DOOR INNER LOCK           | 8VC ✓     | 398.00 X            |
| 7.           | 1PC  | O/S FRONT DOOR TRIM BOARD           | De/701 ✓  | 645.20 1,078.00 ✓   |
| 8.           | 1PC  | O/S FRONT DOOR REGULATOR            | Bent ✓    | 285.00 ✓            |
| 9.           | 1PC  | O/S FRONT DOOR REGULATOR GEAR MOTOR | 8VC ✓     | 395.00 X            |
| 10.          | 1PC  | O/S SIDE MIRROR                     | 320 ✓     | 697.00 ✓            |
| 11.          | 1PC  | O/S SIDE MIRROR COVER               | M5 ✓      | 100.50 175.00 ✓     |
| 12.          | 1PC  | O/S REAR DOOR                       | 20/304 ✓  | 1088.50 1,398.00 ✓  |
| 13.          | 1PC  | O/S REAR DOOR BLACK STICKER         | 111 ✓     | 60.00 75.00 ✓       |
| 14.          | 1PC  | REAR WINDSCREEN GLASS MOULDING      | 111 X     | 157.00 X            |
| 15.          | 1PC  | O/S REAR FENDER                     | 11 X      | 1,698.00 X          |
| 16.          | 1PC  | O/S REAR FENDER INNER SHIELD        | 11 X      | 387.00 X            |
| 17.          | 1PC  | REAR BUMPER                         | 247/701 ✓ | 1061.20 1,387.00 ✓  |
| 18.          | 1PC  | O/S REAR BUMPER SIDE RETAINER       | 8VC ✓     | 68.00 X             |
| 19.          | 1 PC | O/S FRONT FENDER                    | 20/304 ✓  | 450.50 854.00 ✓     |
| 20.          | 1 PC | O/S FRONT FENDER INNER SHIELD       | 11 X      | 198.00 X            |
| 21.          | 1PC  | O/S REAR RIM                        | 647 ✓     | 1120.50 1,397.00 ✓  |
| 22.          | 1PC  | O/S REAR WHEEL BEARING              | 11 X      | 485.00 X            |

CONTINUE / ...

# FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

MS FIRST CAPITAL INSURANCE LIMITED  
16 RAFFLES QUAY  
#42-01 HONG LEONG BUILDING 048581

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 62223547

Estimate : ES709656

Date : 03/10/2024  
Vehicle Num. : SMT2963Z  
Make/Model : MAZDA 3  
Chassis/Eng# : JM6BM42A8G0324493  
Accident Date : 01/10/2024  
Claim No. :  
Reference :  
Policy No. :

| S/N | Quantity | Particular                                               | Unit Price | Amount S\$          |
|-----|----------|----------------------------------------------------------|------------|---------------------|
| 23. | 1PC      | O/S REAR SHOCK ABSORBER <i>11 X</i>                      |            | 398.00 <i>X</i>     |
|     |          | List Total S\$ :                                         |            | 13,489.00           |
|     |          | 20.00% Discount S\$ :                                    |            | 2,697.80            |
|     |          |                                                          |            | 10,791.20           |
|     |          | SPECIAL NETT ITEMS :                                     |            |                     |
| 1.  | 1SET     | O/S FRONT DOOR TRIM BOARD CLIP <i>11 30</i>              |            | 50.00 <i>30 S/N</i> |
| 2.  | 1PC      | REAR WINDSCREEN GLASS INNER SEAL <i>11 X</i>             |            | 80.00 <i>X</i>      |
| 3.  | 1PC      | REAR WINDSCREEN GLASS SEALANT <i>11 X</i>                |            | 40.00 <i>X</i>      |
| 4.  | 1SET     | O/S REAR FENDER INNER SHIELD CLIPS <i>11 X</i>           |            | 50.00 <i>X</i>      |
| 5.  | 1 SET    | O/S FRONT FENDER INNER SHIELD CLIPS <i>11 X</i>          |            | 50.00 <i>X</i>      |
| 6.  | 1SET     | O/S REAR BUMPER CLIP <i>11 30</i>                        |            | 50.00 <i>30 S/N</i> |
|     |          | Special Nett Total S\$ :                                 |            | 320.00              |
|     |          | LABOUR :                                                 |            |                     |
|     |          | TO REMOVE/REFIX REAR WINDSCREEN GLASS <i>11</i>          |            | 150.00 <i>X</i>     |
|     |          | TO TRANSFER DOOR MECHANISM <i>120</i>                    |            | 180.00              |
|     |          | RE-SPRAY ANTI-RUST <i>80</i>                             |            | 150.00              |
|     |          | APPLY BODY SEALANT TO CAR JOINTS <i>11 X</i>             |            | 150.00 <i>X</i>     |
|     |          | INSTALL REVERSE SENSOR <i>30</i>                         |            | 100.00              |
|     |          | TO REMOVE INNER TRIM, GARNISH, SEAT AND ETC TO FACILITAT |            |                     |

CONTINUE / ...

# FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

MS FIRST CAPITAL INSURANCE LIMITED  
16 RAFFLES QUAY  
#42-01 HONG LEONG BUILDING 048581

Attention : Motor Claim Department  
Contact : 62222311 Fax No. : 62223547

Estimate : ES709656

Date : 03/10/2024  
Vehicle Num. : SMT2963Z  
Make/Model : MAZDA 3  
Chassis/Eng# : JM6BM42A8G0324493  
Accident Date : 01/10/2024  
Claim No. :  
Reference :  
Policy No. :

| S/N | Quantity | Particular                                  | Unit Price | Amount S\$    |
|-----|----------|---------------------------------------------|------------|---------------|
|     |          | REPAIRS AND TO FIX BACK                     |            | 60 180.00     |
|     |          | PANEL BEATING LABOUR                        |            | 550 900.00    |
|     |          | TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS |            | 1200 1,500.00 |
|     |          | Labour Total S\$ :                          |            | 3,310.00      |

E. & O.E. Total S\$ : 14,421.20

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-7062-80  
208  
5650.24  
60  
2040  
7750.24  
217  
6200