

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. : SAC2400943

INV Date : 11-10-2024

Reference CD/CTI24060002/Kpa3

Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. PC 3485J
Insured Veh. YN 5071S
Claim No. SNM24D203359/C02
Policy No. DMCVSNW00027712400
Accident Date 07/06/2024
Inspection Date 10/06/2024

Description	Amount
Third Party Express Settlement	400.00
Sub-Total	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS CHINA TAIPING INSURANCE (S) PTE LTD	Ref:	CD/CTI24060002/Kpa3
3 ANSON ROAD #16-00	Date:	11/10/2024
SPRINGLEAF TOWER SINGAPORE 079909	Code:	CTI

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	YN 5071S	Veh. Inspected	PC 3485J
Policy No.	DMCVSNW00027712400	Coverage	0
Claim No.	SNM24D203359/C02	Excess	\$0.00
Assign From	JACQUELINE TAN	Assign Date	07/06/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE COMMUTER GL 3.0 A	C.C	2982
Engine No.	1KD2483356	Year of Reg.	30/04/2015
Chassis No.	KDH2230022743	Colour	SILVER
Odometer	543131 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15X8	LAUFENN	3
L/H Front Tyre	195R15X8	LAUFENN	6
R/H Rear Tyre	195R15X8	KAPSEN	3
L/H Rear Tyre	195R15X8	KAPSEN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/06/2024	Inspection Date	10/06/2024
Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO PC 3485J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR LH	BENT	\$1,999.70	\$1,712.15
1	FRONT DOOR RUBBER /LH	SERVICEABLE	\$310.90	\$0.00
1	FRONT DOOR OUTER CHANNEL /LH	BENT	\$273.40	\$273.40
	LESS 20.00 / 25.00% DISCOUNT		(\$516.80)	(\$496.39)
			\$2,067.20	\$1,489.16

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR 'BIZ SAFE 3' STICKERS (SN)	NECESSARY	\$120.00	\$120.00
1	SLIDING DOOR 'EXCURSION BUS' STICKERS (SN)	NECESSARY	\$60.00	\$30.00
1	SLIDING DOOR 'AUTO' STICKERS (SN)	NECESSARY	\$40.00	\$30.00
1	SLIDING DOOR 'BODHI TREE' STICKERS (SN)	NECESSARY	\$280.00	\$200.00
			\$500.00	\$380.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED PANELS	NOT NECESSARY	\$120.00	\$60.00
	TO TRANSFER FRONT DOOR MECHANISM TO NEW DOOR		\$120.00	\$60.00
	TO CHECK WATER SEEPAGE		\$60.00	\$20.00
	TO COMPUTER WHEEL ALIGNMENT		\$120.00	\$0.00
	TO REPAIR,PANEL BEAT ON AFFECTED AREA AND TO REPLACE ABOVE PART		\$800.00	\$550.00
	TO PUTTY,PRIMER & SPRAY PAINT ON LEFT FRT DOOR ,LEFT DOOR REAR PANEL ,PETROL LID & LEFT SLIDING DOOR USING 2K PAINT		\$1,000.00	\$600.00
			\$2,220.00	\$1,290.00

GRAND TOTAL	\$4,787.20	\$3,159.16
--------------------	-------------------	-------------------

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	\$2,500.00
---	-------------------

Report Ref No: CD/CTI24060002/Kpa3



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

KSC

KENNETH KONG SENG CHEONG


DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : PC 3485J



PHOTOGRAPHS FOR VEHICLE NO. : PC 3485J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 5)



PHOTOGRAPHS FOR VEHICLE NO. : PC 3485J



PHOTOGRAPHS FOR VEHICLE NO. : PC 3485J



PHOTOGRAPHS FOR VEHICLE NO. : PC 3485J



PHOTOGRAPHS FOR VEHICLE NO. : PC 3485J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : PC 3485J

