

not Authorized
 in
 means
 4/10/24
 1/5 \$15,800
 25 days
 REPAIR ESTIMATE

Claim Type: Third Party Claim
 Attn: MS First Capital Insurance Limited
 Motor Claims Department
 Owner: YANG FENG
 DOA: 24 Sep 2024

Date: 30 Sep 2024
 Vehicle Num: SMC8389G
 Make/Model: HONDA ODYSSEY 2.4L AT
 Chassis #: JHMRB38509C201482
 Engine #: K24Z21301489
 Yr. Of Manu: 2009

No.	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	FRONT BUMPER Dis	1	S\$ 713.60	S\$ 713.60 ✓
2	FRONT BUMPER SIDE RETAINER LH/RH But o/s N/S	2	S\$ 22.50	S\$ 45.00 1PC
3	FRONT BUMPER BRACKET LH/RH NS	2	S\$ 37.40	S\$ 74.80 ✓
4	FRONT FOG LAMP LH/RH 11	2	S\$ 303.80	S\$ 607.60 ✓
5	FRONT FOG LAMP GRILLE LH/RH 11	2	S\$ 80.10	S\$ 160.20 ✓
6	FRONT BUMPER LOWER GRILLE Torn	1	S\$ 153.90	S\$ 153.90 ?
7	FRONT GRILLE b/w	1	S\$ 245.60	S\$ 245.60 ✓
8	FRONT GRILLE CHROME MOULDING b/w	1	S\$ 220.50	S\$ 220.50 ✓
9	FRONT GRILLE EMBLEM net	1	S\$ 28.30	S\$ 28.30 ✓
10	FRONT BUMPER TOE COVER Torn \$ 31.00	1	S\$ 421.60	S\$ 421.60 ✓
11	FRONT BUMPER REINFORCEMENT But	1	S\$ 233.70	S\$ 233.70 ✓
12	FRONT BUMPER UNDER COVER 11	1	S\$ 168.30	S\$ 168.30 ✓
13	FRONT SUPPORT PANEL But	1	S\$ 524.10	S\$ 524.10 ✓
14	FRONT SUPPORT PANEL TOP GARNISH Torn	1	S\$ 61.50	S\$ 61.50 ✓
15	HEADLAMP ASSY LH/RH N/S one o/s b/w	2	S\$ 758.90	S\$ 1,517.80 ✓
16	HEADLAMP PANEL LH/RH R	2	S\$ 205.20	S\$ 410.40 X
17	HEADLAMP BRACKET LH/RH one	2	S\$ 37.40	S\$ 74.80 ?
18	BONNET But	1	S\$ 712.40	S\$ 712.40 ✓
19	BONNET HINGE LH/RH But	2	S\$ 46.70	S\$ 93.40 ✓
20	BONNET INSULATOR PAD But	1	S\$ 88.90	S\$ 88.90 ✓
21	BONNET CABLE 11	1	S\$ 33.90	S\$ 33.90 X
22	BONNET RUBBER Torn	1	S\$ 42.60	S\$ 42.60 ✓
23	BONNET LOCK But	1	S\$ 93.40	S\$ 93.40 ✓
24	BONNET CATCH 11	1	S\$	S\$ 0.00 X
25	WIPER GARNISH COVER 11	1	S\$ 217.60	S\$ 217.60 X
26	WIPER ARM LH/RH 11	2	S\$ 92.30	S\$ 184.60 X
27	WIPER BLADE LH/RH 11	2	S\$ 85.40	S\$ 170.80 X
28	WIPER NOZZLE LH/RH 11	2	S\$ 29.70	S\$ 59.40 X

Continue on next page...

29 HORN	one
30 AIR DUCT	7m
31 ENGINE MOUNTING LH/RH	11
32 ENGINE MOUNTING BRACKET LH/RH	0/5 one
33 AIR CLEARER BOX	11
34 INTAKE MANFOLD	11
35 A/C COMPRESSOR	11
36 A/CALTERNATOR	11
37 V-BELT	11
38 A/C CONDENSER	best / part
39 A/C FAN MOTOR	7m
40 A/C FAN COWLING	one
41 A.C FAN BLADE	best
42 A/C SUCTION PIPE	11
43 A/C DISCHARGE PIPE	11
44 RADIATOR	holder one / best
45 RADIATOR BRACKET LH/RH	2
46 RADIATOR MOTOR	7m
47 RADIATOR COWLING	one
48 RADIATOR BLADE	best
49 RADIATOR TOP HOUSE	11
50 RADIATOR BOTTOM HOSE	11
51 RADIATOR SPARE TANK	De
52 WIPER TANK	11
53 WIPER TANK MOTOR	11
54 FRONT FENDER LH/RH	MS R old best
55 FRONT FENDER INNER SHIELD LH/RH	11
56 FRONT FENDER INNER SHIELD COWLING LH/RH	11
57 REAR BUMPER	MS
58 REAR BUMPER SIDE RETAINER LH/RH	MS R old best
59 REAR BUMPER REFLECTOR LH/RH	one / two
60 REAR BUMPER REINFORCEMENT	best
61 REAR BUMPER REINFORCEMENT BRACKET LH/RH	best
62 REAR END PANEL	3.5.20
63 REAR END PANEL BRACKET LH/RH	MS
64 REAR END PANEL TOP GARNISH	3.5
65 REAR FLOOR PANEL	crushed / one
66 TAIGLATE	3.5.20

1 S\$	56.20 S\$	56.20	✓
1 S\$	42.70 S\$	42.70	✓
2 S\$	268.50 S\$	537.00	✓
2 S\$	111.80 S\$	223.60	72C
1 S\$	898.80 S\$	898.80	X
1 S\$	343.50 S\$	343.50	X
1 S\$	1408.6 S\$	1,408.60	X
1 S\$	2049.80 S\$	2,049.80	X
1 S\$	110.30 S\$	110.30	3
1 S\$	753.70 S\$	753.70	✓
1 S\$	296.80 S\$	296.80	2
1 S\$	82.90 S\$	82.90	2
1 S\$	54.80 S\$	54.80	✓
1 S\$	249.30 S\$	249.30	X
1 S\$	280.90 S\$	280.90	X
1 S\$	1565.70 S\$	1,565.70	✓
2 S\$	28.50 S\$	57.00	X
1 S\$	305.80 S\$	305.80	✓
1 S\$	107.50 S\$	107.50	2
1 S\$	55.60 S\$	55.60	2
1 S\$	35.70 S\$	35.70	X
1 S\$	31.90 S\$	31.90	X
1 S\$	67.40 S\$	67.40	2
1 S\$	86.80 S\$	86.80	X
1 S\$	66.20 S\$	66.20	X
2 S\$	549.20 S\$	1,098.40	12C
2 S\$	158.90 S\$	317.80	X
2 S\$	125.70 S\$	251.40	X
1 S\$	714.90 S\$	714.90	✓
2 S\$	25.40 S\$	50.80	12C
2 S\$	42.30 S\$	84.60	✓
1 S\$	197.20 S\$	197.20	✓
2 S\$	64.30 S\$	128.60	✓
1 S\$	490.80 S\$	490.80	✓
2 S\$	55.30 S\$	110.60	X
1 S\$	187.20 S\$	187.20	✓
1 S\$	309.50 S\$	309.50	✓
1 S\$	1010.30 S\$	1,010.30	✓

Continue on next page...



JOO HAK KEE AUTO PTE LTD

裕合记汽车私人有限公司

SINCE 1986

67 TAILGATE ABSORBER LH/RH	11	2	S\$	166.90	S\$	333.80	X
68 TAILGATE HINGE LH/RH	11	2	S\$	79.50	S\$	159.00	X
69 TAILGATE INNER TRIM	11	1	S\$	214.90	S\$	214.90	X
75 TAIGLATE WEATHER STRIP	11	1	S\$	156.90	S\$	156.90	/
76 TAILGATE LOCK	11	1	S\$	202.60	S\$	202.60	/
77 TAILGATE CATCH	11	1	S\$	23.40	S\$	23.40	X
78 TAIGLATE LOGO EMBLEM	11	1	S\$	39.50	S\$	39.50	/
79 TAIGLATE ODYSSEY EMBLEM	11	1	S\$	39.20	S\$	39.20	/
80 TAIGLATE OPENING SENSOR	11	1	S\$	195.30	S\$	195.30	X
81 TAIGLATE OUTER GARNISH	11	1	S\$	492.90	S\$	492.90	/
82 TAILGATGE LAMP ASSY LH/RH	11	2	S\$	287.30	S\$	574.60	/
83 TAILLAMP ASSY LH/RH	11	1	S\$	320.60	S\$	320.60	/
84 TAILLAMP PANEL LH/RH	11	2	S\$	157.30	S\$	314.60	12C
85 REAR WIPER MOTOR	11	1	S\$	345.60	S\$	345.60	X
86 REAR WIPER BLADE	11	1	S\$	49.30	S\$	49.30	X
87 REAR WIPER ARM	11	1	S\$	66.50	S\$	66.50	X
88 REAR FENDER LH/RH	11	2	S\$	1005.20	S\$	2,010.40	12C
89 REAR FENDER INNER	11	2	S\$	358.70	S\$	717.40	/
90 REAR FENDER INNER SHIELD COWLING LH/RH	11	2	S\$	327.90	S\$	655.80	X
91 REAR EXHAUST MUFFLER	11	2	S\$	514.20	S\$	1,028.40	12C
92 REAR EXHAUST PIECE	11	1	S\$	1,887.00	S\$	1,887.00	/
93 REAR EXHASUT BRACKET	11	2	S\$	22.80	S\$	45.60	X
94 REAR EXHASUT TIP	11	2	S\$	93.40	S\$	186.80	12C
95 REAR EXHAUST HEAT INSULATOR	11	1	S\$	52.70	S\$	52.70	/
						Amt S\$	32,192.10
DISCOUNT:						20% S\$	6,438.42
						Subtotal S\$	25,753.68

No.	Description	Qty	U/P	Amt
-----	-------------	-----	-----	-----

Section: Special Nett

96 FRONT BUMPER CLIPS - 1 SET	11	1	S\$	80.00	S\$	80.00	30
97 FRONT LOWER GRILLE CLIPS - 1 SET	11	1	S\$	80.00	S\$	80.00	X
98 FRONT NUMBER PLATE WITH CASING	11	1	S\$	120.00	S\$	120.00	40
99 FRONT BUMPER LOWEE SPOLIER	11	1	S\$	550.00	S\$	550.00	X
100 FRONT BUMPER LOWEE SPOLIER CLIPS - 1 SET	11	1	S\$	80.00	S\$	80.00	X
101 FRONT GRILLE CLIPS - 1 SET	11	1	S\$	80.00	S\$	80.00	20
102 FRONT BUMPER PARKING SENSOR	11	1	S\$	300.00	S\$	300.00	200

Continue on next page...

BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701

TEL: 6743 1913 FAX: 6743 5234

CO/GST REG NO: 201300082W

BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

EMAIL: admin@jkh.com.sg

WEBSITE: www.jkh.com.sg

bizSAFE₃



JOO HAK KEE AUTO PTE LTD

裕合记汽车私人有限公司

SINCE 1986

103	FROTN BUMPER UNDER COVER CLIPS - 1 SET	1	S\$	80.00	S\$	80.00	X
104	FRONT SUPPORT PANEL TOP GARNSIH CLIPS - 1 SET	1	S\$	80.00	S\$	80.00	30
105	BONNET INSULATOR PAD CLIPS - 1 SET	1	S\$	80.00	S\$	80.00	30
106	FRONT FENDER INNER SHIELD CLIPS LH/RH CLIPS - SET	2	S\$	80.00	S\$	160.00	X
107	REAR BUMPER CLIPS - 1 SET	1	S\$	80.00	S\$	80.00	30
108	REAR BUMPER REVERSE SENSOR	1	S\$	300.00	S\$	300.00	200
109	REAR END PANEL TOP GARNSIH CLIPS - 1 SET	1	S\$	80.00	S\$	80.00	X
110	REAR BUMPER LOWER SPOLIER	1	S\$	550.00	S\$	550.00	X
111	REAR BUMPER LOWER SPOLIER - 1 SET	1	S\$	80.00	S\$	80.00	X
112	TAIGATE INNER TRIM BOAD CLIPS - 1 SET	1	S\$	80.00	S\$	80.00	40
113	REAR NUMBER PLATE WITH CASING	1	S\$	120.00	S\$	120.00	40
114	REAR TAILGATE LAMP CLIPS LH/RH - SET	2	S\$	80.00	S\$	160.00	X
115	TAILLAMP CLIPS LH/RH -SET	2	S\$	80.00	S\$	160.00	X
116	REAR BUMPER UNDER COVER CLIPS - SET	1	S\$	80.00	S\$	80.00	X
117	REAR EXHAUST HEAT INSULATOR PAD CLIPS	1	S\$	80.00	S\$	80.00	X
118	REAR FENDER INNER SHIELD CLIPS LH/RH CLIPS - SET	2	S\$	80.00	S\$	160.00	X
						Amt S\$	3620.00

No.	Description	Qty	U/P	Amt
<u>Section: LABOUR</u>				
119	TO RE-SPRAY PAINTING ON THE CHANGE BODY PARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.(FRT & RR)		S\$	2,000.00 1800
120	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.(FRT & RR)		S\$	2,000.00 1900
121	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REFOCUS HEADLAMP & TAILLAMP. (FRT & RR)		S\$	120.00 30
122	TRANSFER AND REPLACE TAILGATE INNER MECHANISM TO NEW TAILGATE		S\$	150.00 60
123	REMOVE, REPLACE, AND REINSTALL FRONT AND REAR INNER GARNISH, BOARDS, ROOF LINING, SEATS, CARPET, AND TRIMS TO ASSIST REPAIR		S\$	250.00 80
124	REMOVE AND REPLACE FRONT PARKING SENSOR & REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR		S\$	100.00 40

Continue on next page...

BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701

TEL: 6743 1913 FAX: 6743 5234

CO/GST REG NO: 201300082W

BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

EMAIL: admin@jhk.com.sg

WEBSITE: www.jhk.com.sg

bizSAFE₃




JOO HAK KEE AUTO PTE LTD

裕合记汽车私人有限公司

SINCE 1986

REMOVE , REPLACE AND REINSTALL A/C CONDENSER AND VACUUM & TOP		
125 UP A/C GAS TO FACILITATE REPAIR	S\$	120.00
REMONVE , REPLACE AND REINSTALL RADIATOR AND TOP UP COOLANT TO		
126 FACILITATE REPAIR	S\$	120.00
REMOVE , REPLACE AND REINSTALL ESHASUT TO FACILTATE REPAIR		
127	S\$	120.00
REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS TO ASSIST		
128 REPAIR	S\$	150.00
	S\$	5130.00



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal: S\$	25,753.68
SPECIAL NETT ITEMS Subtotal S\$	3,620.00
LABOUR Subtotal: S\$	5,130.00
Total: S\$	34,503.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s), during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-18582.40
202
P-14865.92
S.N-760
L-4110
19835.92
202
15865.

BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701

BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

TEL: 6743 1913 FAX: 6743 5234

EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W

WEBSITE: www.jhk.com.sg

bizSAFE₃

SUPPLEMENTARY

Claim Type:	Third Party Claim	Date :	45,565.00
Attn:	MS First Capital Insurance l	Vehicle Num :	SMC8389G
	Motor Claims Department	Make/Model :	HONDA ODYSSEY 2.4L AT
Owner:	YANG FENG	Chassis # :	JHMRB38509C201482
DOA:	24 Sep 2024	Engine # :	K24Z21301489
		Yr. Of Manu :	2,009.00

No.	Description	Qty	U/P	Amt
-----	-------------	-----	-----	-----

Section: LIST ITEMS

1 REAR SEAT MOTOR	<i>Damage</i> 1 S\$	980.70 S\$	980.70
-------------------	---------------------	------------	--------

Amt S\$ 980.70

DISCOUNT: 0.20 S\$ 196.14

Subtotal S\$ 784.56

No.	Description	Qty	U/P	Amt
-----	-------------	-----	-----	-----

Section: Special Nett


2 REAR SEAT	<i>Damage</i> 1 S\$	1,850.00 S\$	1,850.00 <i>X</i>
3 REAR SPARE TYRE	<i>Damage</i> 1 S\$	250.00 S\$	250.00 <i>100 S/N</i>

Amt S\$ 2100.00

LIST ITEMS Subtotal: S\$ 784.56

SPECIAL NETT ITEMS Subtotal S\$ 2,100.00

Total: S\$ 2,884.56



Joo Hak Kee Auto Pte. Ltd.