

ESTIMATE

3/10/2024

SMRT BUSES LTD
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

Vehicle No: SMT1489H
Vehicle Model: H/FIT
Est No: CBMQ24100039
Claims ref:
Accident Date: 28/09/24
In Charge: JUNIOR
Remarks:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	TAILGATE <i>bt</i>	1	PC \$ 870.00	\$ 870.00 ✓
2	TAILGATE LOCK ASSY <i>Xm</i>	1	PC \$ 380.00	\$ 380.00 X
3	TAILGATE WEATHERSTRIP <i>cut</i>	1	PC \$ 280.00	\$ 280.00 208.50
4	TAILGATE EMBLEM "FIT" <i>re</i>	1	PC \$ 30.00	\$ 30.00 ✓
5	REAR WINDSCREEN MOULDING <i>re</i>	1	PC \$ 170.00	\$ 170.00 ✓
6	TAILGATE OUTER HANDLE CHROME <i>cm</i>	1	PC \$ 360.00	\$ 360.00 245.50
7	TAILGATE OUTER HANDLE CHROME EMBLEM <i>re</i>	1	PC \$ 80.00	\$ 80.00 35
	"HONDA" LOGO <i>re</i>			
8	REAR BUMPER <i>re</i>	1	PC \$ 580.00	\$ 580.00 ✓
9	REAR BUMPER CLIPS <i>re</i>	10	PC \$ 5.00	\$ 50.00 ✓
10	REAR BUMPER SPONGE - CHECK	1	PC	\$ -
11	REAR BUMPER REINFORCEMENT - CHECK	1	PC	\$ -
12	REAR END PANEL <i>? repair</i>	1	PC \$ 490.00	\$ 490.00 XR
13	TAILLAMP RH & LH <i>RH - cm</i>	1/2	PC \$ @ 420.00	\$ 840.00 345
14	REAR FENDER RH & LH - REPAIR <i>RH - repair / LH - Xm</i>	1	PC	\$ -
15	REAR BUMPER RETAINER RH & LH <i>LH - X / RH - ? Xm</i>	2	PC \$ 190.00	\$ 380.00 X
LIST TOTAL S\$			2534	\$ 4,510.00
20% DISCOUNT S\$			20%	\$ (902.00)
			2027.20	\$ 3,608.00
SPECIAL NET ITEMS:				
1	REVERSE SENSOR CTR <i>Xm</i>	1	SET \$ 280.00	\$ 280.00 X
2	REAR WINDSCREEN GLASS SEALANT <i>re</i>	1	PC \$ 40.00	\$ 40.00 ✓
SPECIAL NET TOTAL S\$			40	\$ 320.00

LABOUR CHARGE:

- 1 TO CUT, WELD, PANEL BEAT, STRAIGHTEN, REPLACEMENT, REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS
- 2 TO PUTTY SPRAY PAINT ON TAILGATE, REAR BUMPER, REAR FENDER RH &

600 800
\$ 1,100.00

ESTIMATE

3/10/2024

SMRT BUSES LTD
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

Vehicle No: SMT1489H
Vehicle Model: H/FIT
Est No: CBMQ24100039
Claims ref:
Accident Date: 28/09/24
In Charge: JUNIOR
Remarks:

Main Office:
MOVA Building
No. 22, Upper Changi Road
Singapore 484439
Tel: (65) 6271 3333
Fax: (65) 6271 5881
www.mova.com.sg
Workshop Dept:
Block 1013
Bukit Merah Lane 3
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8814
Co Reg: 198904033G
GST Reg: MZ-0088842

No	Description	Qty	U. Price	Amounts S\$
	LH TAILGATE, REAR END PANEL, REAR SPARE TYRE COMPARTMENT.			\$ 1,300.00
3	TO CHECK WIRING ELECTRICAL SYSTEM FOR PROPER FUNCTION			\$ 50.00
4	TO REMOVE & REFIT REAR WINDSCREEN GLASS			\$ 150.00
5	TO APPLY SPRAY TEROSTAT SEALANT ON REAR END PANEL, REAR SPARE TYRE COMPARTMENT			\$ 200.00
6	TO REMOVE & REFIT REAR FENDER INNER TRIM LH & RH, OTHER ATTACHMENT PARTS			\$ 100.00
7	TO REMOVE & REFIT REAR END PANEL, REAR SPARE TYRE COMPARTMENT TRIM & OTHER ATTACHMENT PARTS			\$ 100.00
8	TO REMOVE & REFIT TAILGATE INNER TRIM & OTHER ATTACHMENT PARTS			\$ 100.00
	TOTAL LABOUR COST S\$			\$ 3,100.00

AMOUNT S\$ \$ 7,028.00
GST @ 9% \$ 632.52
AMOUNT DUE S\$ \$ 7,660.52

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2027.20

40100

1880.00

3947.20

267

3157.76

45-83,150/5days

Ram

Hy 9m/w68

5 days + 1 = 6 days

L/S

22/10/24

Reg after repair