

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

3/10/2024

S MRT BUSES LTD

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

Vehicle No: SMT1489H

Vehicle Model: H/FIT

Est No: CBMQ24100039

Claims ref:

Accident Date: 28/09/24

In Charge: JUNIOR

Remarks:

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	TAILGATE <i>lt</i>	1	PC \$ 870.00	\$ 870.00
2	TAILGATE LOCK ASSY <i>X</i>	1	PC \$ 380.00	\$ 380.00
3	TAILGATE WEATHERSTRIP <i>cut</i>	1	PC \$ 280.00	\$ 280.00
4	TAILGATE EMBLEM "FIT" <i>re</i>	1	PC \$ 30.00	\$ 30.00
5	REAR WINDSCREEN MOULDING <i>re</i>	1	PC \$ 170.00	\$ 170.00
6	TAILGATE OUTER HANDLE CHROME <i>cm</i>	1	PC \$ 360.00	\$ 360.00
7	TAILGATE OUTER HANDLE CHROME EMBLEM <i>re</i>	1	PC \$ 80.00	\$ 80.00
	"HONDA" LOGO <i>re</i>			
8	REAR BUMPER <i>de</i>	1	PC \$ 580.00	\$ 580.00
9	REAR BUMPER CLIPS <i>re</i>	10	PC \$ 5.00	\$ 50.00
10	REAR BUMPER SPONGE - CHECK	1	PC	\$ -
11	REAR BUMPER REINFORCEMENT - CHECK	1	PC	\$ -
12	REAR END PANEL <i>?</i>	1	PC \$ 490.00	\$ 490.00
13	TAILLAMP RH & LH <i>RH-cm</i>	1 <i>2</i>	PC \$ 420.00	\$ 840.00
14	REAR FENDER RH & LH - REPAIR <i>RH-repair/LH-X</i>	1	PC	\$ -
15	REAR BUMPER RETAINER RH & LH <i>LH-X/RH-?</i>	2	PC \$ 190.00	\$ 380.00
LIST TOTAL S\$				\$ 4,510.00
20% DISCOUNT S\$				\$ (902.00)
				<u>\$ 3,608.00</u>

SPECIAL NET ITEMS:

1	REVERSE SENSOR CTR <i>X</i>	1	SET \$ 280.00	\$ 280.00
2	REAR WINDSCREEN GLASS SEALANT <i>re</i>	1	PC \$ 40.00	\$ 40.00

SPECIAL NET TOTAL S\$

\$ 320.00
LABOUR CHARGE:

1	TO CUT, WELD, PANEL BEAT, STRAIGHTEN, REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS			<i>600</i> \$ 1,100.00
2	TO PUTTY SPRAY PAINT ON TAILGATE, REAR BUMPER, REAR FENDER RH &			

ESTIMATE

3/10/2024

SMRT BUSES LTD
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

Vehicle No: SMT1489H
Vehicle Model: H/FIT
Est No: CBMQ24100039
Claims ref:
Accident Date: 28/09/24
In Charge: JUNIOR
Remarks:

Main Office:
Mova Building
No. 22, Jalan Khatib,
Singapore, 351109
Tel: (65) 6276 3333
Fax: (65) 6271 5891
www.mova.com.sg
Workshop Dept:
Block 1008,
Bukit Meran Lane 3,
#01-04706/04707/04708/04709/04710
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 1814
Co Reg 1989040336
GST Reg M2-008864-2

No	Description	Qty	U. Price	Amounts S\$
	LH TAILGATE, REAR END PANEL, REAR SPARE TYRE COMPARTMENT.			\$ 1,300.00 600
3	TO CHECK WIRING ELECTRICAL SYSTEM FOR PROPER FUNCTION			\$ 50.00 30
4	TO REMOVE & REFIT REAR WINDSCREEN GLASS			\$ 150.00 120
5	TO APPLY SPRAY TEROSTAT SEALANT ON REAR END PANEL, REAR SPARE TYRE COMPARTMENT			\$ 200.00 40.40
6	TO REMOVE & REFIT REAR FENDER INNER TRIM LH & RH, OTHER ATTACHMENT PARTS			\$ 100.00 X
7	TO REMOVE & REFIT REAR END PANEL, REAR SPARE TYRE COMPARTMENT TRIM & OTHER ATTACHMENT PARTS			\$ 100.00 40.7
8	TO REMOVE & REFIT TAILGATE INNER TRIM & OTHER ATTACHMENT PARTS			\$ 100.00 50
	TOTAL LABOUR COST S\$			\$ 3,100.00



AMOUNT S\$ \$ 7,028.00
GST @ 9% \$ 632.52
AMOUNT DUE S\$ \$ 7,660.52

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

Rame
Hy 9m/w68
5 days
4/5
22/10/24
Rag after repair

PART - \$3030 - 20%
= \$2424.00
SN - \$ 40.00
LABOUR - \$ 1880.00
\$ 4344.00
4s - \$ 3450.00
4

615411
615411