

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

3/10/2024

SMRT BUSES LTD

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

Vehicle No: SMT1489H

Vehicle Model: H/FIT

Est No: CBMQ24100039

Claims ref:

Accident Date: 28/09/24

In Charge: JUNIOR

Remarks:

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	TAILGATE	1	PC \$ 870.00	\$ 870.00
2	TAILGATE LOCK ASSY	1	PC \$ 380.00	\$ 380.00
3	TAILGATE WEATHERSTRIP	1	PC \$ 280.00	\$ 280.00
4	TAILGATE EMBLEM "FIT"	1	PC \$ 30.00	\$ 30.00
5	REAR WINDSCREEN MOULDING	1	PC \$ 170.00	\$ 170.00
6	TAILGATE OUTER HANDLE CHROME	1	PC \$ 360.00	\$ 360.00
7	TAILGATE OUTER HANDLE CHROME EMBLEM "HONDA" LOGO	1	PC \$ 80.00	\$ 80.00
8	REAR BUMPER	1	PC \$ 580.00	\$ 580.00
9	REAR BUMPER CLIPS	10	PC \$ 5.00	\$ 50.00
10	REAR BUMPER SPONGE - CHECK	1	PC	\$ -
11	REAR BUMPER REINFORCEMENT - CHECK	1	PC	\$ -
12	REAR END PANEL	1	PC \$ 490.00	\$ 490.00
13	TAILLAMP RH & LH	2	PC \$ 420.00	\$ 840.00
14	REAR FENDER RH & LH - REPAIR	1	PC	\$ -
15	REAR BUMPER-RETAINER RH & LH	2	PC \$ 190.00	\$ 380.00
LIST TOTAL S\$				\$ 4,510.00
20% DISCOUNT S\$				\$ (902.00)
				<u>\$ 3,608.00</u>

SPECIAL NET ITEMS:

1	REVERSE SENSOR CTR	1	SET \$ 280.00	\$ 280.00
2	REAR WINDSCREEN GLASS SEALANT	1	PC \$ 40.00	\$ 40.00

SPECIAL NET TOTAL S\$

\$ 320.00
LABOUR CHARGE:

1	TO CUT, WELD, PANEL BEAT, STRAIGHTEN, REPLACEMENT, REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS			\$ 1,100.00
2	TO PUTTY SPRAY PAINT ON TAILGATE, REAR BUMPER, REAR FENDER RH &			

Main Office:
MOVA BUILDING
No. 22, Jalan Kiang,
Singapore 339439
Tel: (65) 6272 3333
Fax: (65) 6272 1589
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-14/15/16/17/18/19/20
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 188904033G
GST Reg. M2-0088884-2


ESTIMATE

3/10/2024

SMRT BUSES LTD
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

Vehicle No: SMT1489H
Vehicle Model: H/FIT
Est No: CBMQ24100039
Claims ref:
Accident Date: 28/09/24
In Charge: JUNIOR
Remarks:

No	Description	Qty	U. Price	Amounts S\$
	LH TAILGATE, REAR END PANEL, REAR SPARE TYRE COMPARTMENT.			\$ 1,300.00
3	TO CHECK WIRING ELECTRICAL SYSTEM FOR PROPER FUNCTION			\$ 50.00
4	TO REMOVE & REFIT REAR WINDSCREEN GLASS			\$ 150.00
5	TO APPLY SPRAY TEROSTAT SEALANT ON REAR END PANEL, REAR SPARE TYRE COMPARTMENT			\$ 200.00
6	TO REMOVE & REFIT REAR FENDER INNER TRIM LH & RH, OTHER ATTACHMENT PARTS			\$ 100.00
7	TO REMOVE & REFIT REAR END PANEL, REAR SPARE TYRE COMPARTMENT TRIM & OTHER ATTACHMENT PARTS			\$ 100.00
8	TO REMOVE & REFIT TAILGATE INNER TRIM & OTHER ATTACHMENT PARTS			\$ 100.00
	TOTAL LABOUR COST S\$			<u>\$ 3,100.00</u>



AMOUNT S\$ \$ 7,028.00
GST @ 9% \$ 632.52
AMOUNT DUE S\$ \$ 7,660.52

Customer's Signature

MOVA AUTOMOTIVE PTE LTD