



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400387W
GST Reg No. MR-8500111-X

ESTIMATE FOR SCN113Z

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No 18991
Reg No/Reg Date SCN113Z / 27/08/2018
Date In/Mileage / 0
Chassis No WDD2130422A475009
Engine No 27492031519037
Make/Model MB/MB E 200 SEDAN EXCLUSIVE/EXCLUSIVE
Colour/Trim 029 992 Selenite Gr/ 048 801 Leather Nap

Account No	Terms	Date/Time Printed	CSE	Operator			
WF001862	Credit	07/10/2024/ 11:00	VS	356 / Vincent Seah			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request
M BPNSUN
POLICY NO/ACC DATE : V5017264 // 25.06.2024
DRIVE IN/EXCESS : 25.06.2024 // TP SH7993X- FIRST CAPITAL
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

M BPNSUN
SUNDRIES

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY ON RHR FENDER , REAR BUMPER AND ACCIDENT AFFECTED AREA

M RIGHT REAR LAMP COMBINATION *cm*

M REAR BUMPER *de*

M LHR CHROME MOULDING *ne*

M RHR CHROME MOULDING *ne*

M BRACKET *ne*

M CUPPED BLIND RIVET *ne*

M LOWER RHR BRACKET *cm*

M RHR EXHUATS TIP CHROME TRIM STRIP *de x s v l*

M RHR SIDE STABILITY *? cm*

M RHR BASIC MOUNTING FOR BUMPER *? cm*

M TOP RHR BASIC MOUNTING FOR BUMPER *? cm*

M DISTANCE SENSOR *? x s v l*

M SPACER RING *ne*

M CUPPED BLIND RIVET *ne*

M REAR LOWER BUMPER *de*

15.00

0.10 380.00

120.00

1920 4320.00

0.01 1600 3200.00

1.00 840.76 00.00 840.76

1.00 1705.44 00.00 1705.44

1.00 207.42 00.00 207.42

1.00 207.42 00.00 207.42

1.00 57.90 00.00 57.90

12.00 5.50 00.00 66.00

1.00 70.12 00.00 70.12

1.00 225.86 00.00 225.86

1.00 118.84 00.00 118.84

1.00 92.10 00.00 92.10

1.00 50.51 00.00 50.51

2.00 201.17 00.00 402.34

6.00 8.89 00.00 53.34

2.00 5.50 00.00 11.00

1.00 441.74 00.00 441.74

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SCN113Z

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

WIP No

18991

Reg No/Reg Date

SCN113Z / 27/08/2018

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

WDD2130422A475009

27492031519037

MB/MB E 200 SEDAN EXCLUSIVE/EXCLUSIVE

029 992 Selenite Gr/ 048 801 Leather Nap

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	07/10/2024/ 11:00	VS	356 / Vincent Seah
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount
M REAR BUMPER CHROME MOULDING	1.00	414.53	00.00	414.53
M COVER, TOWING EYE	1.00	161.87	00.00	161.87
M RIGHT REFLECTING Emitter	1.00	49.88	00.00	49.88

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

Nett 13,212.07
9% GST on 13212.07 1189.09

Total Payable 14,401.16

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SCN113Z

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

18991
SCN113Z / 27/08/2018
14/10/2024/ 54562
WDD2130422A475009
27492031519037
MB/MB E 200 SEDAN EXCLUSIVE/EXCLUSIVE
029 992 Selenite Gr/ 048 801 Leather Nap

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	18/10/2024/ 14:59	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
M BPMSUN				
POLICY NO/ACC DATE : V5017264 // 25.06.2024				
DRIVE IN/EXCESS : 25.06.2024 // TP SH7993X- FIRST CAPITAL				
DATE IN/DATE SURVEY:				
BY/AUTHORIZED ON :				
X BASIC MOUNTING FOR BUMPER	1.00	94.05	00.00	94.05
X RIGHT REAR SHIELDING	1.00	99.14	00.00	99.14
X RIGHT TAIL PIPE COVER	1.00	493.48	00.00	493.48
X TOP BASIC MOUNTING FOR BUMPER	1.00	50.51	00.00	50.51

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

9% GST on **Nett** **737.18**
737.18 **66.35**

Authorized signatory and company stamp

Total Payable **803.53**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg